



CUSTOMER OPERATIONS
160 RIO ROBLES
SAN JOSE, CA 95134

PDN #: M000859

DATE: 02-Aug-2017

PRODUCT DISCONTINUANCE NOTICE

Notice Type	Maxim Part Number	Recommended Replacement	Last Order Date	Last Delivery Date	Reason
Lead-Free Conversion	DS9481R-309#	N/A	02-Aug-2018	01-Feb-2019	EVKIT is No Longer Supported
Lead-Free Conversion	MAX310MJE/883B	N/A	02-Aug-2018	01-Feb-2019	Part is leaded. Request information on lead-free version
Lead-Free Conversion	MAX6339AUT	MAX6339AUT+	02-Aug-2017	02-Aug-2017	Part is leaded. Request information on lead-free version
Lead-Free Conversion	MAX8881EUT33	MAX8881EUT33+	02-Aug-2018	01-Feb-2019	Part is leaded. Request information on lead-free version
Discontinuance	DS1210S+	N/A	02-Aug-2017	02-Aug-2017	Part can no longer be manufactured
Discontinuance	DS1210SN+	N/A	02-Aug-2017	02-Aug-2017	Part can no longer be manufactured
Discontinuance	DS1833-10+	N/A	02-Aug-2018	01-Feb-2019	Part can no longer be manufactured
Discontinuance	DS1833-5+	N/A	02-Aug-2018	01-Feb-2019	Part can no longer be manufactured
Discontinuance	DS1833Z-10+	N/A	02-Aug-2018	01-Feb-2019	Part can no longer be manufactured
Discontinuance	DS1833Z-5+T&R	N/A	02-Aug-2018	01-Feb-2019	Part can no longer be manufactured
Discontinuance	DS1844-010+	N/A	02-Aug-2018	01-Feb-2019	Part can no longer be manufactured
Discontinuance	DS1844E-010+	N/A	02-Aug-2018	01-Feb-2019	Part can no longer be manufactured
Discontinuance	DS1844E-010+T&R	N/A	02-Aug-2018	01-Feb-2019	Part can no longer be manufactured
Discontinuance	DS2762BE+025/T&R	N/A	02-Aug-2017	02-Aug-2017	Part can no longer be manufactured
Discontinuance	DS3503U+	N/A	02-Aug-2017	02-Aug-2017	The part was not released
Discontinuance	MAX14824ETG+	MAX14824GTG+	02-Aug-2018	01-Feb-2019	The part was not released
Discontinuance	MAX15040EWE+T	MAX15050EWE+T	02-Aug-2018	01-Feb-2019	Part can no longer be manufactured
Discontinuance	MAX16989ATJC/V+T	MAX16989BATJC/V+T	02-Aug-2017	02-Aug-2017	The part was not released
Discontinuance	MAX3660ETE+TG0F	N/A	02-Aug-2018	01-Feb-2019	Part can no longer be manufactured
Discontinuance	MAX3890ECB+D	N/A	02-Aug-2018	01-Feb-2019	Part can no longer be manufactured
Discontinuance	MAX3890ECB+TD	N/A	02-Aug-2018	01-Feb-2019	Part can no longer be manufactured
Discontinuance	MAX3890EVKIT	N/A	02-Aug-2017	02-Aug-2017	EVKIT is No Longer Supported
Discontinuance	MAX44005EDT+T	MAX44009EDT+T	02-Aug-2018	01-Feb-2019	Part can no longer be manufactured
Discontinuance	MAX44291AUA+	N/A	02-Aug-2018	01-Feb-2019	Part can no longer be manufactured
Discontinuance	MAX5700AUB+	MAX5702BAUB+T	02-Aug-2018	01-Feb-2019	Part can no longer be manufactured
Discontinuance	MAX5701AUB+	MAX5702BAUB+	02-Aug-2018	01-Feb-2019	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 02-Sep-2017

Discontinuance	MAX5702AAUB+	MAX5702BAUB+	02-Aug-2018	01-Feb-2019	Part can no longer be manufactured
Discontinuance	MAX5703AUB+	MAX5705BAUB+	02-Aug-2018	01-Feb-2019	Part can no longer be manufactured
Discontinuance	MAX5705AAUB+	MAX5705BAUB+	02-Aug-2018	01-Feb-2019	Part can no longer be manufactured
Discontinuance	MAX5713AUD+	MAX5715BAUD+	02-Aug-2018	01-Feb-2019	Part can no longer be manufactured
Discontinuance	MAX5714AUD+	MAX5715BAUD+	02-Aug-2018	01-Feb-2019	Part can no longer be manufactured
Discontinuance	MAX5715AAUD+	MAX5715BAUD+	02-Aug-2018	01-Feb-2019	Part can no longer be manufactured
Discontinuance	MAX5715AAUD+T	MAX5715BAUD+T	02-Aug-2018	01-Feb-2019	Part can no longer be manufactured
Discontinuance	MAX5715AAUD+TW	MAX5715BAUD+	02-Aug-2018	01-Feb-2019	Part can no longer be manufactured
Discontinuance	MAX5724AUP+	MAX5725BAUP+	02-Aug-2018	01-Feb-2019	Part can no longer be manufactured
Discontinuance	MAX5725AAUP+	MAX5725BAUP+	02-Aug-2018	01-Feb-2019	Part can no longer be manufactured
Discontinuance	MAX5800AUB+	MAX5802BAUB+	02-Aug-2018	01-Feb-2019	Part can no longer be manufactured
Discontinuance	MAX5801AUB+	MAX5802BAUB+	02-Aug-2018	01-Feb-2019	Part can no longer be manufactured
Discontinuance	MAX5802AAUB+	MAX5802BAUB+	02-Aug-2018	01-Feb-2019	Part can no longer be manufactured
Discontinuance	MAX5805AAUB+	MAX5805BAUB+	02-Aug-2018	01-Feb-2019	Part can no longer be manufactured
Discontinuance	MAX5813AUD+	MAX5815BAUD+	02-Aug-2018	01-Feb-2019	Part can no longer be manufactured
Discontinuance	MAX5814AUD+	MAX5815BAUD+	02-Aug-2018	01-Feb-2019	Part can no longer be manufactured
Discontinuance	MAX5815AAUD+	MAX5815BAUD+	02-Aug-2018	01-Feb-2019	Part can no longer be manufactured
Discontinuance	MAX5823AUP+	MAX5825BAUP+	02-Aug-2018	01-Feb-2019	Part can no longer be manufactured
Discontinuance	MAX9643UATA+T	N/A	02-Aug-2018	01-Feb-2019	Part can no longer be manufactured
Discontinuance	VT1697SBFQR	VT1697SBFQX	02-Aug-2017	02-Aug-2017	Part can no longer be manufactured
Discontinuance	ZA9L0010NW1LSGA201	MAX32590-L5S+	01-Feb-2019	01-Feb-2019	Part can no longer be manufactured
Discontinuance	ZA9L0020NW1LSGA300	MAX32590-L5S+	01-Feb-2019	01-Feb-2019	Part can no longer be manufactured