
# 1 Products affected

	-			-				
Product hierarchy no. *	Part no.	SBU	Type / Description	Customer part no.				
SBU PG PUG Type								
01 002 002 000000500	See list below	Fuseholder complete	useholder complete FPG1					
*SBU (2-digit) / PG (3-digit) / PUG (3-digit) / Type (10-digit)								
List of part numbers affected								
FPG1 complete			F	3101.0015				
3101.0010 3	101.1010	3101.0110	3101.0110 3101.0110.02					
3101.0115 3	101.0011	3101.0111	3101.0210	3101.0310				
3101.0215 3	101.0315							
FPG1 socket								
3101.1511.1 3	101.1511.2	3101.1513.1						
FPG1 carrier								
3101.7011 3	101.7012	3101.7022	3101.7022 3101.7021 3					
3101.7521								

#### 2 Type of change

## • Change of markings

### 3 Detailed description of change



### 4 Reason of change

• Newly approved nominal voltage according to IEC 60127-6

### 5 Release date

The change will be rolled-out starting ww 09/2017 (Date code 1709 or higher on label) and lasts approx. 6 months depending on the variant.

# 6 Impact of change and recommended action

Form Yes		Modified marking on product			
Fit	No	No change for dimension			
Function	No	No change in function			
Manufacturing	No	No change for manufacturing site			
Label	No	No change on label			
Packaging	No	No change in packaging			

## 7 Reference Documents / Attachments

Kind of document	Remarks
Data Sheet	

Product Change Notification				FPG1 change of the marks			
owner	creation date	release date	released by	change order no	rev	page	D10 010 014
zbindeja	2016-11-16	2017-01-30	nowakfr	2011481	А	1 of 1	D10-010-914