



Product Change Notification

Current Date: 25-Apr-2022

TE Connectivity

Product Change Notification: P-22-022542

PCN Date: 22-APR-22

Customer: TTI, Inc. (3057778)

Location: Maisach-gernlinden

Agreement: Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

Various Level 3 Board and RF Connector Products (RDO# 0037)

Description of Changes

Manufacturing location change of components and subassemblies. The following Part Numbers will have assemblies and/or component manufacturing transferred from TE Connectivity's manufacturing location in Norwood, MA to another TE Manufacturing location or to a TE Connectivity approved supplier.

Reason for Changes:

Dear Customer, we hereby inform you about a transfer of tools and/or processes for components and subassemblies of the part numbers listed below. The transfer is executed by following a strict transfer procedure, which ensures that there will be no negative influence on quality, ability to supply and form-fit-function of the concerned products. The new manufacturing location is under a certified quality management system according to industry standard requirements. An internal evaluation and first article based on our specifications will be executed before any parts will be delivered.

Estimated Dates:

| | |
|---|---|
| Last Order Date (Obsolete Parts Only): | First Date To Ship (Changed Parts Only): |
| | 01-JUL-2022 |
| Last Ship Date (Obsolete Parts Only): | Last Date for Mixed Shipments: (Changed Parts Only): |
| | 31-OCT-2023 |

Part Number(s) being Modified:

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|---------------------------|---------------------------|------------------|----------------------------------|-------------------------|------------------------|---------------------------------|---------------------------|
| 1218125-3 | NO | | TYC1218125-3, TYCM24308/24-9F | | | | |
| 1589687-3 | NO | | | QCM019SC2DMM02PB | | | |
| 1757837-1 | NO | | TYC1757837-1 | | | | |
| 443976-5 | NO | | TYCM24308/23-11F | | | | |



Product Change Notification

Current Date: 25-Apr-2022

TE Connectivity

Product Change Notification: P-22-022542

PCN Date: 22-APR-22

Customer: TTI, Inc. (1305175)

Location: Maisach-gernlinden

Agreement: EU-TTI-MASTK

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

Various Level 3 Board and RF Connector Products (RDO# 0037)

Description of Changes

Manufacturing location change of components and subassemblies. The following Part Numbers will have assemblies and/or component manufacturing transferred from TE Connectivity's manufacturing location in Norwood, MA to another TE Manufacturing location or to a TE Connectivity approved supplier.

Reason for Changes:

Dear Customer, we hereby inform you about a transfer of tools and/or processes for components and subassemblies of the part numbers listed below. The transfer is executed by following a strict transfer procedure, which ensures that there will be no negative influence on quality, ability to supply and form-fit-function of the concerned products. The new manufacturing location is under a certified quality management system according to industry standard requirements. An internal evaluation and first article based on our specifications will be executed before any parts will be delivered.

Estimated Dates:

| | |
|---|---|
| Last Order Date (Obsolete Parts Only): | First Date To Ship (Changed Parts Only): |
| | 01-JUL-2022 |
| Last Ship Date (Obsolete Parts Only): | Last Date for Mixed Shipments: (Changed Parts Only): |
| | 31-OCT-2023 |

Part Number(s) being Modified:

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|-----------------------------|---------------------------|------------------|----------------------------------|----------------------|------------------------|---------------------------------|---------------------------|
| 1-1589053-2 | NO | | TYC1-1589053-2 | STM03711500PCN | | | |
| 1-1589455-7 | NO | | TYC1-1589455-7 | SSL009PC2DC018N | | | |
| 1-1589472-5 | NO | | TYC1-1589472-5 | STL009PC2DC018N | | | |
| 1-1589473-2 | NO | | TYC1-1589473-2 | STM009PC2DC036N | | | |
| 1-1589475-8 | NO | | | STM065PC2DT018N | | | |
| 1-1589478-1 | NO | | | STM051B5N | | | |
| 1-1589946-7 | NO | | | STM037PC2DT024N | | | |
| 1-1811901-0 | NO | | | | | | |
| 1-1811902-0 | NO | | | | | | |
| 1-1811902-1 | NO | | | | | | |
| 1218125-3 | NO | | TYC1218125-3, TYCM24308/24-9F | | | | |
| 1445692-6 | NO | | | | | | |
| 1445693-3 | NO | | TYC1445693-3 | | | | |
| 1589070-4 | NO | | TYC1589070-4 | CX020PC2RG018N | | | |
| 1589675-4 | NO | | | JTM037PR2DT001N | | | |
| 1589676-7 | NO | | | JTM065PR2DC003N | | | |
| 1589687-3 | NO | | | QCM019SC2DMM02PB | | | |
| 1589688-6 | NO | | TYC1589688-6 | TCM019PC2DC072B | | | |
| 1589692-4 | NO | | | QCM019PC2DMC150B | | | |
| 1589827-5 | NO | | TYC1589827-5 | SSL015PC2DC036N | | | |
| 1757180-2 | NO | | TYC1757180-2 | | | | |
| 1757225-1 | NO | | | | | | |
| 1757543-3 | NO | | | | | | |
| 1757837-1 | NO | | TYC1757837-1 | | | | |
| 1877039-2 | NO | | | | | | |
| 1996092-1 | NO | | | | | | |
| 2-1589070-6 | NO | | TYC2-1589070-6 | CX030PC2RG060N | | | |
| 2-1589070-9 | NO | | | CX080PC2RG024N | | | |
| 2-1589456-0 | NO | | TYC2-1589456-0 | SSM025PC2DC018N | | | |

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|-----------------------------|---------------------------|------------------|----------------------|----------------------|------------------------|---------------------------------|---------------------------|
| 2-1589473-0 | NO | | | STM009PC2DM036N | | | |
| 2-846985-3 | NO | | TYC2-846985-3 | | | | |
| 2-846985-8 | NO | | TYC2-846985-8 | | | | |
| 2-858885-1 | NO | | TYC2-858885-1 | | | | |
| 208972-1 | NO | | TYC208972-1 | | | | |
| 2101136-1 | NO | | TYC2101136-1 | | | | |
| 2101598-1 | NO | | | | | | |
| 225831-3 | NO | | | | | | |
| 2286270-1 | NO | | | | | | |
| 2288886-1 | NO | | | | | | |
| 2294045-1 | NO | | | | | | |
| 2294317-1 | NO | | | | | | |
| 3-1589070-0 | NO | | TYC3-1589070-0 | CX060PC2RG036N | | | |
| 3-1589456-9 | NO | | TYC3-1589456-9 | SSM037PC2DC024N | | | |
| 3-1589472-0 | NO | | TYC3-1589472-0 | STL015PC2DC012N | | | |
| 3-1589476-1 | NO | | TYC3-1589476-1 | STL051SC2DC012N | | | |
| 3-208972-9 | NO | | | | | | |
| 4-1589455-4 | NO | | TYC4-1589455-4 | SSM005PC2DC012N | | | |
| 4-1589473-4 | NO | | TYC4-1589473-4 | STM015PC2DC024N | | | |
| 4-1589474-2 | NO | | TYC4-1589474-2 | STM037PC2DC024N | | | |
| 413242-1 | NO | | TYC413242-1 | | | | |
| 443976-5 | NO | | TYCM24308/23-11F | | | | |
| 445378-1 | NO | | | | | | |
| 447466-1 | NO | | | | | | |
| 449379-1 | NO | | TYC449379-1 | | | | |
| 449838-1 | NO | | TYC449838-1 | | | | |
| 5-1589456-0 | NO | | TYC5-1589456-0 | SSM051PC2DC024N | | | |
| 5-1589473-7 | NO | | | STM015PC2DM036N | | | |