

# PRODUCT CHANGE NOTIFICATION

**Product Category** \_\_\_\_\_ COMPUTER PRINTABLES \_\_\_\_\_ **20230308-1**

**Product Group** \_\_\_\_\_ ID AND SAFETY \_\_\_\_\_

**ISSUE DATE:**  1/11/23  EMEA  LATAM  APMar-23

**IMPACTED REGIONS:**  DISCONTINUATION

**REASON FOR CHANGE:**  OTHER

**DESCRIPTION OF CHANGE: (Required)**

Military Grade Single-Sided Heat Shrink Label Rolls, for use with TDP Thermal Transfer Desktop Printers, with 025, 034, and 044 diameter sizes, and H050, H100, and H200 widths will be updated to include a paper liner material in place of the current polyester liner material. The change will improve the ease of use for tearing off the liner to remove the heat shrink labels from a printer. The change has a slight difference in appearance, but no difference in form, fit, or functionality, compared to the previous design. This change affects part numbers within the following families:

H\*\*\*X025H\*T

H\*\*\*X034H\*T

H\*\*\*X044H\*T

H\*\*\*X025H\*T-B

H\*\*\*X034H\*T-B

H\*\*\*X044H\*T-B

Photos/Drawing (where applicable) Part number H050X025H2T shown below

Old polyester liner



New paper liner



Old polyester liner on left

New paper liner on right



IMPACTED PART NUMBERS AND REPLACEMENT PART NUMBERS: (where applicable)

[Reference Page 2 / Linked PDF](#)

**DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:**

SCHEDULE FOR CHANGE	Year (YYYY)	Month (MM)	Day (DD)
New product sample availability date			
Old product discontinuation date*			

**CUSTOMER SERVICE CONTACTS**

<b>ASIA PACIFIC</b>	<b>AUSTRALIA: 1-800 7263848</b> <a href="mailto:AUS-CSVM@panduit.com">AUS-CSVM@panduit.com</a>	<b>CHINA: 400-820-1900</b> <a href="mailto:CHN-CustomerService@panduit.com">CHN-CustomerService@panduit.com</a>	<b>HONG KONG: 800-965768</b> <a href="mailto:CHN-CustomerService@panduit.com">CHN-CustomerService@panduit.com</a>	
	<b>INDIA: 000 800 6501844 (Fixed) 000 800 6500369 (Mobile)</b> <a href="mailto:SGP-Customer_Service@panduit.com">SGP-Customer_Service@panduit.com</a>	<b>INDONESIA: 001 803 65 7571</b> <a href="mailto:SGP-Customer_Service@panduit.com">SGP-Customer_Service@panduit.com</a>	<b>JAPAN: +81-3-6863-6000</b> <a href="mailto:JPN-CS@panduit.com">JPN-CS@panduit.com</a>	
	<b>KOREA: 02-2182-7300</b> <a href="mailto:KOR-CustomerService@panduit.com">KOR-CustomerService@panduit.com</a>	<b>MALAYSIA 1800 801435</b> <a href="mailto:SGP-Customer_Service@panduit.com">SGP-Customer_Service@panduit.com</a>	<b>SINGAPORE: 1-800-7263848</b> <a href="mailto:SGP-Customer_Service@panduit.com">SGP-Customer_Service@panduit.com</a>	
	<b>TAIWAN: 0080 165 1487</b> <a href="mailto:SGP-Customer_Service@panduit.com">SGP-Customer_Service@panduit.com</a>	<b>THAILAND: 001-800-65-6385</b> <a href="mailto:SGP-Customer_Service@panduit.com">SGP-Customer_Service@panduit.com</a>		
<b>LATIN AMERICA</b>	<b>BRAZIL 08000562613 (Toll Free)</b> <a href="mailto:BRA-custservice@panduit.com">BRA-custservice@panduit.com</a>	<b>MEXICO: +52-33-37776000 x80520 01 800 360 86 00 (Toll Free)</b> <a href="mailto:MEX-customerservice@panduit.com">MEX-customerservice@panduit.com</a>	<b>OTHER LA COUNTRIES: Phone USA 1-708-532-1800</b> <a href="mailto:TP-CS-INTERNATIONAL@panduit.com">TP-CS-INTERNATIONAL@panduit.com</a>	
<b>NORTH AMERICA</b>	USA & CANADA: 1-800-777-3300 <a href="mailto:cs@panduit.com">cs@panduit.com</a>	<b>EMEA</b>	<b>EMEA: +44 208 6017219</b> <a href="mailto:EMEA-CustomerServices@panduit.com">EMEA-CustomerServices@panduit.com</a>	

IMPACTED PART NUMBER(s)	IMPACTED PART NUMBER(s)
H050X025H1T	H100X034H2T
H050X025H1T-B	H200X034H1T
H050X025H2T	H200X034H1T-B
H100X025H1T	H200X034H2T
H100X025H1T-B	H200X034H3T
H100X025H2T	H200X034H4T
H200X025H1T	H050X044H1T
H200X025H1T-B	H050X044H1T-B
H200X025H2T	H050X044H2T
H200X025H3T	H100X044H1T
H200X025H4T	H100X044H1T-B
H050X034H1T	H100X044H2T
H050X034H1T-B	H200X044H1T
H050X034H2T	H200X044H1T-B
H100X034H1T	H200X044H2T
H100X034H1T-B	H200X044H3T
	H200X044H4T