

Document Receipt Acknowledgement



Document Number: D07512-A-G0190

Date: Apr. 01, 2024

Date:
Section:
Name:

Attention:

FARNELL ELEC COMPONENTS

LTD

**Request for approval for alternative production at Yokaichi factory
due to impact of earthquake to Anamizu factory**

Winding type Common mode choke coil DLW5A/DLW5B series
Chip inductor LQH2HNNH_03, LQH2HPN/Z/H_GR, LQH2HPZ_JR, LQH32NZ/H_23, LQH3NPN/Z/H_ME, LQH43CN_03, LQH43NN/Z/H_03, LQH43PN/Z/H/B_26 series

Dear. Valued Customer

Thank you very much for your great and continued support for business with Murata.
This is the official notification that some of our products detailed below.
Please review this, and accept in writing.
Your understanding and support are highly appreciated.

1. Product Type and Customer/Murata Part Numbers:

Product DLW5A/DLW5B
Type: series
LQH2HNNH_03, LQH2HPN/Z/H_GR, LQH2HPZ_JR, LQH32NZ/H_23, LQH3NPN/Z/H_ME, LQH43CN_03, LQH43NN/Z/H_03,
LQH43PN/Z/H/B_26 series

Please refer to the attached documents for Part Numbers' information.

2. Background/Request:

These series are produced by our company, Anamizu Murata Manufacturing Co., Ltd. (Anamizu Factory).
Anamizu factory was affected by the 2024 Noto Peninsula earthquake that occurred on January 1, 2024.
At the present time, production has been suspended, but we are working on the recovery and earliest schedule will be after May.

Therefore, we will commence alternative production at Yokaichi Factory (*1) urgently. Please approve the temporary supply of Yokaichi Factory products until Anamizu Factory is recommence operation.

Please note that there are no changes to the 4M (Man, Machine, Material, Method).(*2)
If you agree to supply(*3) products produced at Yokaichi factory(*2), please sign and reply to us on separate sheet.

- *1: Murata Manufacturing Company, Ltd. Yokaichi Factory
- *2: Production will be carried out at Yokaichi factory using the equipment and production operator from Anamizu Factory.
- *3: Supply quantity and timing cannot be guaranteed.

3. Approval Due:
4. Contact Window:

May, 17, 2024

Should you have any questions or concerns,
please contact Murata Sales, Representative, or Distributor in your area.

Truly Yours. Thank you.

Murata Manufacturing, Co.,
Ltd.
Marketing & Promotion Department EMI Filter Division
Hiromi Nagasaka



Document Number: D07512-A-G0190

Confirmation Letter

**FARNELL ELEC COMPONENTS
LTD**

Murata Manufacturing, Co., Ltd.

Request for approval for alternative production at Yokaichi factory due to impact of earthquake to Anamizu factory

accepted. not accepted.

Regarding the supply of the following products,

Product DLW5A/DLW5B
Type: series

LQH2HNNH_03, LQH2HPN/Z/H_GR, LQH2HPZ_JR, LQH32NZ/H_23, LQH3NPN/Z/H_ME, LQH43CN_03, LQH43NN/Z/H_03,
LQH43PN/Z/H/B_26 series

Comments, Questions, etc.

Signature
Date: (MM, DD, YYYY)

Title:

Name:

Murata Part Number	Murata Part Number	Murata Part Number	Murata Part Number
LQH43CN100K03L	LQH43NH560J03L	LQH2HPN101MGRL	DLW5ATH401TQ2L
LQH43CN101K03L	LQH43NH680J03L	LQH2HPN220MGRL	DLW5ATH450TQ2L
LQH43CN150K03L	LQH43NH820J03L	LQH2HPN3R3MGRL	DLW5ATH500MQ2L
LQH43CN151K03L	LQH43NH101J03L	LQH2HPZ100MJRL	DLW5ATH501MQ2L
LQH43CN1R0M03L	LQH43NH102J03L	LQH2HPZ150MGRL	DLW5ATH501TQ2L
LQH43CN220K03L	LQH43NH121J03L	LQH2HPZ220MJRL	LQH2HNHR56K03L
LQH43CN221K03L	LQH43NH151J03L	LQH2HPZ2R2MJRL	LQH2HNHR68K03L
LQH43CN2R2M03L	LQH43NH181J03L	LQH2HPZ4R7MJRL	LQH2HNHR82K03L
LQH43CN470K03L	LQH43NH221J03L	LQH2HPZ6R8MJRL	LQH2HNN1R0M03L
LQH43CN4R7M03L	LQH43NH271J03L	LQH32NH471J23L	LQH2HNN1R2K03L
LQH43CN680K03L	LQH43NH331J03L	LQH3NPN100MMEL	LQH2HNN1R5K03L
DLW5BSN152SQ2L	LQH43NH391J03L	LQH3NPN101MMEL	LQH2HNN1R8J03L
DLW5BSN191SQ2L	LQH43NH471J03L	LQH3NPN220MMEL	LQH2HNN2R2J03L
DLW5BSN302SQ2L	LQH43NH561J03L	LQH3NPN2R2MMEL	LQH2HNN2R7K03L
DLW5BTN501SQ2L	LQH43NH681J03L	LQH3NPN330MMEL	LQH2HNN3R3J03L
LQH43PN100M26L	LQH43NH821J03L	LQH3NPN3R3MMEL	LQH2HNN3R9J03L
LQH43PN101M26L	LQH43NH122J03L	LQH3NPN470MMEL	LQH2HNN3R9J03L
LQH43PN1R0N26L	LQH43NH152J03L	LQH3NPN4R7MMEL	LQH2HNN5R6J03L
LQH43PN220M26L	LQH43NH182J03L	LQH3NPN6R8MMEL	LQH2HNN6R8J03L
LQH43PN2R2M26L	LQH43NH222J03L	LQH3NPZ100MMEL	LQH2HNN8R2J03L
LQH43PN470M26L	LQH32NH101J23L	LQH3NPZ150MMEL	LQH2HNN100J03L
LQH43PN6R8M26L	LQH32NH1R0M23L	LQH3NPZ220MMEL	LQH2HNN120J03L
DLW5BTM102SQ2L	LQH32NH220J23L	LQH3NPZ2R2MMEL	LQH2HNN150J03L
DLW5BTM142SQ2L	LQH32NH2R2J23L	LQH3NPZ330MMEL	LQH2HNN180J03L
DLW5BTM142TQ2L	LQH32NH4R7J23L	LQH3NPZ3R3MMEL	LQH2HNN220J03L
DLW5BTM251SQ2L	LQH3NPZ1R0MMEL	LQH43CN6R8M03L	LQH2HNN270J03L
LQH32NH100J23L	LQH43PB221M26L	LQH43NN182J03L	LQH2HNN330J03L
DLW5ATH111TQ2L	DLW5ATN112MQ2L	LQH43NN222J03L	LQH2HNN390J03L
DLW5BTH101TQ2L	DLW5ATN501MQ2L	LQH43NN222K03L	LQH2HNN470J03L
LQH43NH1R0M03L	DLW5ATZ112MQ2L	LQH43PH100M26L	LQH2HNN560J03L
LQH43NH1R2K03L	DLW5BSZ601TQ2L	LQH43PH4R7M26L	LQH2HNN680J03L
LQH43NH1R5J03L	LQH43NZ270K03L	LQH3NPH1R0MMEL	LQH2HNN820J03L
LQH43NH1R8J03L	DLW5ATN231TQ2L	LQH3NPH2R2MMEL	LQH2HNN101J03L
LQH43NH2R2J03L	DLW5ATN272SQ2L	LQH3NPH3R3MMEL	LQH2HPPH47MGRL
LQH43NH2R7J03L	DLW5ATN331MQ2L	LQH3NPH4R7MMEL	LQH2HPPH68MGRL
LQH43NH3R3J03L	DLW5BSM102SQ2L	LQH3NPH6R8MMEL	LQH2HPPH1R0MGRL
LQH43NH3R9J03L	DLW5BSM152SQ2L	LQH3NPH100MMEL	LQH2HPPH1R5MGRL
LQH43NH4R7J03L	DLW5BSM191SQ2L	LQH3NPH150MMEL	LQH2HPPH2R2MGRL
LQH43NH5R6J03L	DLW5BSM302SQ2L	LQH3NPH220MMEL	LQH2HPPH3R3MGRL

LQH43NH6R8J03L	DLW5BSM351SQ2L	LQH3NPH330MMEL	LQH2HPH4R7MGRL
LQH43NH8R2J03L	DLW5BSM501TQ2L	LQH3NPH470MMEL	LQH2HPH6R8MGRL
LQH43NH100J03L	DLW5BSM801TQ2L	LQH3NPH560MMEL	LQH2HPH100MGRL
LQH43NH120J03L	DLW5BTH142TQ2L	LQH3NPH680MMEL	LQH2HPH150MGRL
LQH43NH150J03L	DLW5BTH251TQ2L	LQH3NPH101MMEL	LQH2HPH220MGRL
LQH43NH180J03L	DLW5BTM101SQ2L	LQH3NPN560MMEL	LQH43CN1R0M03L
LQH43NH220J03L	DLW5BTM101TQ2L	LQH3NPN680MMEL	LQH43CN470K03L
LQH43NH270J03L	DLW5BTM102TQ2L	DLW5ATH112MQ2L	DLW5BTM142TQ2L
LQH43NH330J03L	DLW5BTM251TQ2L	DLW5ATH151MQ2L	
LQH43NH390J03L	DLW5BTM501SQ2L	DLW5ATH231TQ2L	
LQH43NH470J03L	DLW5BTM501TQ2L	DLW5ATH331MQ2L	