



infrastructure for a connected world

# PRODUCT CHANGE NOTIFICATION

Product Category ABRASION PROTECTION **20221003-1**

Product Group DUCT AND ABRASION

ISSUE DATE:  NA  MEA  LATAM  AP-Oct-22

IMPACTED REGIONS:  DISCONTINUATION

REASON FOR CHANGE:  OTHER

## DESCRIPTION OF CHANGE: (Required)

A tooling change occurred on Panduit's CLT products in April 2020 resulting in outside diameter and inside diameter dimensional changes. See below chart detailing nominal dimensional changes. See drawing GB0222BP REV. 11 for changes and tolerances.

Photos/Drawing (where applicable)

PART NUMBER PREFIX	NEW TOOLING OUTSIDE DIAMETER	OLD TOOLING OUTSIDE DIAMETER	OUTSIDE DIAMETER DIFFERENCE	NEW TOOLING INSIDE DIAMETER	OLD TOOLING INSIDE DIAMETER	INSIDE DIAMETER DIFFERENCE
CLT25	0.378" (9.6mm)	0.398" (7.20mm)	-0.02" (-0.508mm)	0.281" (7.14mm)	0.284" (7.20mm)	-0.003" (-0.076mm)
CLT35	0.417" (10.59mm)	0.504" (12.79mm)	-0.087" (-2.20mm)	0.323" (8.20mm)	0.350" (8.88mm)	-0.027" (-0.685mm)
CLT38	0.535" (13.59mm)	0.524" (13.30mm)	0.011" (0.279mm)	0.421" (10.69mm)	0.394" (9.99mm)	0.027" (0.685mm)
CLT50	0.675" (17.15mm)	0.654" (16.60mm)	0.021" (0.533mm)	0.518" (13.16mm)	0.512" (12.99mm)	0.006" (0.152mm)
CLT62	0.815" (20.70mm)	0.847" (21.05mm)	-0.032" (-0.812mm)	0.665" (16.89mm)	0.664" (16.85mm)	0.001" (0.025mm)
CLT75	0.933" (23.70mm)	0.941" (23.90mm)	-0.008" (-0.203mm)	0.762" (19.35mm)	0.767" (19.47mm)	-0.005" (-0.127mm)
CLT100	1.114" (28.30mm)	1.103" (28.00mm)	0.011" (0.279mm)	0.917" (23.29mm)	0.912" (23.15mm)	0.005" (0.127mm)
CLT125	1.524" (38.71mm)	1.536" (39.00mm)	-0.012" (-0.304mm)	1.303" (33.10mm)	1.278" (32.45mm)	0.025" (0.635mm)
CLT150	1.728" (43.89mm)	1.851" (47.00mm)	-0.123" (-3.12mm)	1.484" (37.69mm)	1.575" (39.99mm)	-0.091" (-2.311mm)
CLT188	2.175" (54.79mm)	2.194" (55.73mm)	-0.019" (-0.482mm)	1.87" (47.50mm)	1.849" (46.96mm)	0.021" (0.533mm)

IMPACTED PART NUMBERS AND REPLACEMENT PART NUMBERS: (where applicable)

**DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:**

SCHEDULE FOR CHANGE	Year (YYYY)	Month (MM)	Day (DD)
New product sample availability date	2020	4	1
Old product discontinuation date*			

**\*Important:** A return material authorization (RMA) may be obtained for these affected part numbers and they may be returned up to 60 days after the product discontinuation announcement date if purchased within the last 18 months and subject to the return policy requirements outlined in Panduit’s Authorized Distributor Policy. Please contact your local Panduit Customer Experience team if you have any questions.

**CUSTOMER SERVICE CONTACTS**

<b>ASIA PACIFIC</b>	<b>AUSTRALIA: 1-800 7263848</b> <a href="mailto:AUS-CSVM@panduit.com">AUS-CSVM@panduit.com</a>	<b>CHINA: 400-820-1900</b> <a href="mailto:CHN-CustomerService@panduit.com">CHN-CustomerService@panduit.com</a>	<b>HONG KONG: 800-965768</b> <a href="mailto:CHN-CustomerService@panduit.com">CHN-CustomerService@panduit.com</a>
	<b>INDIA: 000 800 6501844 (Fixed)</b> 000 800 6500369 (Mobile)  <a href="mailto:SGP-Customer_Service@panduit.com">SGP-Customer_Service@panduit.com</a>	<b>INDONESIA: 001 803 65 7571</b>  <a href="mailto:SGP-Customer_Service@panduit.com">SGP-Customer_Service@panduit.com</a>	<b>JAPAN: +81-3-6863-6000</b>  <a href="mailto:JPN-CS@panduit.com">JPN-CS@panduit.com</a>
	<b>KOREA: 02-2182-7300</b> <a href="mailto:KOR-CustomerService@panduit.com">KOR-CustomerService@panduit.com</a>	<b>MALAYSIA 1800 801435</b> <a href="mailto:SGP-Customer_Service@panduit.com">SGP-Customer_Service@panduit.com</a>	<b>SINGAPORE: 1-800-7263848</b>  <a href="mailto:SGP-Customer_Service@panduit.com">SGP-Customer_Service@panduit.com</a>
	<b>TAIWAN: 0080 165 1487</b>  <a href="mailto:SGP-Customer_Service@panduit.com">SGP-Customer_Service@panduit.com</a>	<b>THAILAND: 001-800-65-6385</b>  <a href="mailto:SGP-Customer_Service@panduit.com">SGP-Customer_Service@panduit.com</a>	
<b>LATIN AMERICA</b>	<b>BRAZIL 08000562613 (Toll Free)</b>  <a href="mailto:BRA-custservice@panduit.com">BRA-custservice@panduit.com</a>	<b>MEXICO: +52-33-37776000 x80520</b> 01 800 360 86 00 (Toll Free)  <a href="mailto:MEX-customerservice@panduit.com">MEX-customerservice@panduit.com</a>	<b>OTHER LA COUNTRIES:</b> Phone USA 1-708-532-1800  <a href="mailto:TP-CS-INTERNATIONAL@panduit.com">TP-CS-INTERNATIONAL@panduit.com</a>
<b>NORTH AMERICA</b>	USA & CANADA: 1-800-777-3300  <a href="mailto:cs@panduit.com">cs@panduit.com</a>	<b>EMEA</b>	<b>EMEA: +44 208 6017219</b>  <a href="mailto:EMEA-CustomerServices@panduit.com">EMEA-CustomerServices@panduit.com</a>

To add a contact or to unsubscribe, please send an email to:

[PCN@panduit.com](mailto:PCN@panduit.com)

IMPACTED PART NUMBER(s)
CLT100F-1.25M3
CLT100F-125M20

CLT100F-C20
CLT100F-C3
CLT100F-C4
CLT100F-X4
CLT100N-125M630
CLT100N-C630
CLT125F-.75M20
CLT125F-L20
CLT125F-L3
CLT125F-L4
CLT125N-.75M630
CLT125N-L630
CLT150F-D20
CLT150F-D3
CLT150F-D4
CLT150F-T20
CLT150F-X20
CLT150F-X3
CLT150F-X4
CLT150N-D630
CLT188F-3C20
CLT188F-C20
CLT188F-C3
CLT188F-C4
CLT188F-X20
CLT188F-X3
CLT188F-X4
CLT188N-3C630
CLT25F-10M20
CLT25F-C20
CLT25N-10M630

CLT25N-C630
CLT35F-7M20
CLT35N-7M630
CLT38F-5M20
CLT38N-5M630
CLT50F-4M20
CLT50N-4M630
CLT50N-C630
CLT62F-2.5M20
CLT62F-C20
CLT62F-C3
CLT62F-C4
CLT62N-2.5M630
CLT62N-C630
CLT75F-2M20
CLT75F-C20
CLT75F-C3
CLT75F-C4
CLT75N-2M630
CLT75N-C630
CLTS100F-1.25M
CLTS100F-C
CLTS100F-C3
CLTS100N-C
CLTS125F-L
CLTS125F-L3
CLTS125N-L
CLTS150F-D
CLTS150F-D3
CLTS25F-10M
CLTS25F-C

CLTS25N-10M
CLTS25N-C
CLTS35F-C
CLTS35F-C3
CLTS35N-C
CLTS38F-C
CLTS38N-C
CLTS50F-C
CLTS50F-C3
CLTS50N-C
CLTS62F-C
CLTS62F-C3
CLTS62N-C
CLTS75F-2M
CLTS75F-C
CLTS75F-C3
CLTS75N-C