

Data Sheet

FME adapter FME plug - SMA plug



Technical data

Connector: FME plug - SMA plug

Material: Copper

Operating Temperature: -40°C to 80°C

Operating humidity: 10 - 85 % RH

Storage humidity: 10 - 85 % RH