



Method to Identify Change:

code, top marking

Qualification Report:

Not applicable

Revision History:

July 22, 2019: Issued final notification.

The change described in this PCN does not alter Microchip's current regulatory compliance regarding the material content of the applicable products.

Attachment(s):

[PCN_KSRA-18DKCY941_Pre and Post Change.pdf](#)

Please contact your local [Microchip sales office](#) with questions or concerns regarding this notification.

Terms and Conditions:

If you wish to receive Microchip PCNs via email please register for our PCN email service at our [PCN home page](#) select register then fill in the required fields. You will find instructions about registering for Microchips PCN email service in the [PCN FAQ](#) section.

If you wish to change your PCN profile, including opt out, please go to the [PCN home page](#) select login and sign into your myMicrochip account. Select a profile option from the left navigation bar and make the applicable selections.

Affected Catalog Part Numbers (CPN)

BM20SPKS1NBC-0001AA

BM20SPKS1NBC-C001AA

BM20SPKS1NBC-C002AA

BM20SPKS1NBC-T001AA

BM20SPKS1NBC-Y003AA

BM20SPKS1NBC-Y202AB

BM20SPKS1NBC-Y202DP

BM20SPKS1NBC-Y202MA



MICROCHIP

PCN # KSRA-18DKCY941

CCB # 3885

**Implement top marking changes for
BM20SPKS1NBC device family available in
40L Shield type module at MMT and UMEC
assembly site.**

Top Marking

PRE CHANGE

Location	Line	Value
FRONT	1	BM20SPKS1NBC
FRONT	2	<Mac>
FRONT	3	YYWW-0001AA
FRONT	4	CMIIT ID: 2015DJ7134



POST CHANGE

Location	Line	Value
FRONT	1	BM20SPKS1NBC
FRONT	2	<Mac>
FRONT	3	YYWW-0001AA
FRONT	4	CMIIT ID: 2015DJ7134
FRONT	5	ANATEL: 01888-19-08759

