



Expertise Applied | Answers Delivered

8755 W. Higgins Road
Suite 500
Chicago, IL 60631

www.littelfuse.com

May 17th, 2019

To whom it may concern

Product Change Notification for Littelfuse Varistors Products

Littelfuse would like to notify you of a change relating to the UL and CSA logo marking on product surface and product packaging label (inner packing box). All current MOVs UR logo marking will be changed to cURus and the current CSA logo will be removed based on UL 1449 4th Ed. Rev: 2018-08-01 and CSA C22.2 No. 269.5-17, 2017-09 evaluation listed in UL file# E320116 (VZCA).


This change will take effective from **June 24th, 2019** and there will be no any changes to the part numbers, and product's electrical and dimensional specifications. Please refer to following current and new product and label marking.




Current UR and CSA marking on product surface



New cURus marking on product surface



Current label with UR and CSA marking



New label with cURus marking

Affected Product Series: HB34, HF34, HG34, DHB34, HA, RA, UltraMOV 25S, LA, CIII, UltraMOV, LV UltraMOV ,HMOV, AUMOV, ZA Varistor Series.
Please see attached the affected part number list.

Please respond to us by **May 31st, 2019** to acknowledge notification of this change. If we do not hear from you then we will expect that this change has been accepted and no further action is required.
Thank you.

Best Regards
Johnny Chang
Product Manager
Littelfuse, Inc.