

Customer Information Notification

202207008I: Product TJA1448: Single Wrong Character in 3rd Line Marking=> No Impact

Note: This notice is NXP Company Proprietary.

Issue Date: Jul 21, 2022 Effective date: Jul 22, 2022

Here is your personalized notification about a NXP general announcement. For detailed information we invite you to view this notification online

Management summary

Product TJA1448: Single Wrong Character in 3rd Line Marking=> No Impact **Change Category**

[]Wafer Fab Process	[]Assembly Process	[X]Product Marking	[]Test Process	[]Design
[]Wafer Fab Materials	[]Assembly Materials	[]Mechanical Specification	[]Test Equipment	[]Errata
[]Wafer Fab Location	[]Assembly Location	[]Packing/Shipping/Labeling	[]Test Location	[]Electrical spec./Test coverage
[]Firmware	[]Other			

[]Firmware []Other

PCN Overview

Description

For product TJA1448AT/0 and TJA1448BT/0 delivered to you with datecodes between 2129 (week 29 of 2021) and 2217, there's a single character '0' missing in the 3rd and final line of the product's topmarking. The datecode can also be read from this 3rd and final line of the product's topmarking.

There's no impact whatsoever on the product's design, physical composition or Bill-of-Material (BoM), nor on its functionality, performance, (datasheet) compliance or reliability. The only impact is visual, the '0' at the end of the 3rd line marking is not there.

Marking as should be, applying to all products with datecodes OUTSIDE the range 2129-2217:

Line A: TJA1448A or TJA1448B

Line B: ******* (NXP-internal tracebility info on diffusion and assembly lot)

Line C: Dnyyww0

- --- 'D' refers to the ATMC diffusion fab in Austin, Texas, USA
- --- 'n' refers to the assembly and final test fab in ATBK, Bangkok, Thailand

- --- 'yyww' refers to the product datecode (yy = two-digit year, ww = week number within the year)
- --- '0' refers to the 1st revision of the product, which is still actual

Marking as is, ONLY for the products with datecodes IN the range 2129 and 2217:

Line A: TJA1448A or TJA1448B

Line B: *******

Line C: Dnyyww (the '0' is missing)

Note that NXP has full traceability of all TJA1448 products, also for the affected datecodes, and can always identify genuine NXP material.

Reason

The root cause of the temporary wrong marking is a manual mistake in a system update. The issue has been corrected, and actions have been taken to prevent future occurence.

Identification of Affected Products

Top Side Marking

For the affected products only, the '0' at the end of the 3rd line marking is missing.

Anticipated Impact on Form, Fit, Function, Reliability or Quality

No Impact on form, fit, function, reliability or quality

Data Sheet Revision

No impact to existing datasheet

Contact and Support

For all inquiries regarding the ePCN tool application or access issues, please contact NXP "Global Quality Support Team".

For all Quality Notification content inquiries, please contact your local NXP Sales Support team.

For specific questions on this notice or the products affected please contact our specialist directly:

Name Kees van Hasselt

Position Quality Account Manager

e-mail

address <u>ivn.customer.service@nxp.com</u>

At NXP Semiconductors we are constantly striving to improve our product and processes to ensure they reach the highest possible Quality Standards. Customer Focus, Passion to Win.

NXP Quality Management Team.

About NXP Semiconductors

NXP Semiconductors N.V. (NASDAQ: NXPI) provides High Performance Mixed Signal and Standard Product solutions that leverage its leading RF, Analog, Power Management, Interface, Security and Digital Processing expertise. These innovations are used in a wide range of automotive, identification, wireless infrastructure, lighting, industrial, mobile, consumer and computing applications.

You have received this email because you are a designated contact or subscribed to NXP Quality Notifications. NXP shall not be held liable if this Notification is not correctly distributed within your organization.

This message has been automatically distributed. Please do not reply.

Changed Orderable Part#	Changed Product Type	
TJA1448AT/0Z	TJA1448AT/0	
TJA1448AT/0Z	TJA1448AT/0	
TJA1448BT/0Z	TJA1448BT/0	
TJA1448BT/0Z	TJA1448BT/0	

NXP Semiconductors

High Tech Campus, 5656 AG Eindhoven, The Netherlands

 $\hfill \odot$ 2006- 2022 NXP Semiconductors. All rights reserved.