




**Standardized Information Note (IN)**

1. Information Note basic data	
1.1 Company	
1.2 Information Note No.	IN17023
1.3 Title of IN	Revision of GBU40x & GBU60x & GBU80x & GBU100x & SK3xA Datasheet
1.4 Issue date	2017/06/29

2. Contact		
2.1 Contact supplier		
2.1.1 Name	Sunnie Pan	
2.1.2 Phone	886-2-8913-1588 Ext.2205	
2.1.3 Email	sunnie@mail.ts.com.tw	
2.2 Team supplier (optional)		
2.2.1 Name (optional)	2.2.2 Phone (optional)	2.2.3 Email (optional)
Celia Huang	886-2-8913-1588 Ext.2125	Celia@mail.ts.com.tw
Stanley Lin	886-2-8913-1588 Ext.2104	stanleylin@mail.ts.com.tw

3. Description		
	Old	New
Description #1	GBU40x & GBU60x & GBU80x & GBU100x MARKING DIAGRAM description :  <ul style="list-style-type: none"> <li>P/N = Specific Device Code</li> <li>G = Green Compound</li> <li>YW = Date Code</li> <li>F = Factory Code</li> </ul>	GBU40x & GBU60x & GBU80x & GBU100x MARKING DIAGRAM description :  <ul style="list-style-type: none"> <li>P/N = Specific Device Code</li> <li>G = Green Compound</li> <li>YWW = Date Code</li> <li>F = Factory Code</li> </ul>
Description #2	SK3xA : No "H code" in ordering information (For E3/E2).	SK3xA : Add "H code" in ordering information (For E3/E2).
Description #3		
Description #4		
Description #5		

4. Reason / motivation	
4.1 Motivation	Typing error and policy changing
4.2 Additional explanation (optional)	

5. Marking of parts / traceability	
5.1 Description	N/A

6. Timing / schedule	
6.1 Intended start of delivery	N/A

7. Attachments (e.g. additional documentation, pictures, part list...)
Please see in the official announcement mail.

8. Affected parts	
8.1 Current	8.2 New (if applicable)

