



FEATURES

- Excellent low price control potentiometer.
- Available in Carbon (SM-10) and Cermet (SMC-10).
- Based on the PT-10 / PTC-10 series.
- Enclosed in plastic housing.
- IP54 protection according to IEC 60529.

MECHANICAL SPECIFICATIONS

- Mechanical angle: $235^\circ \pm 5^\circ$
- Electrical angle: $220^\circ \pm 20^\circ$
- Torque: 0.5 to 2.5 Ncm.
(0.71 to 3.5 in-oz)
- Stop torque: > 25 Ncm. (> 35.5 in-oz)
- Nut Torque: > 80 Ncm. (113.6 in-oz)
- Mechanical life: $\geq 10K$ cycles (***)

ELECTRICAL SPECIFICATIONS

- Range of values (*)
 $100\Omega \leq R_n \leq 5 M$ (Decad. 1.0 - 2.0 - 2.2 - 2.5 - 4.7 - 5.0)
- Tolerance (*): $100\Omega \leq R_n \leq 1M \Omega$ $\pm 20\%$
 $1M\Omega < R_n \leq 5M \Omega$ $\pm 30\%$
- Max. Voltage: 200 VDC (lin) 100 VDC (no lin)
- Nominal Power :
 - Carbon SM-10 (50°C-122°F): 0.15W (lin), 0.07W (no lin)
 - Cermet SMC-10 (70°C-158°F): 0.33W(lin), 0.17 W (no lin)
- Taper (*) (Log. & Alog. only $R_n > 1K$) Lin ; Log; Alog.
- Residual resistance(*): $\leq 0.5\%$ R_n (5 Ω min.)
- Equivalent noise resistance: $\leq 3\%$ R_n (3 Ω min.)
- Operating temperature:
 - Carbon SM-10 : $-25^\circ C + 70^\circ C^{**}$ ($-13^\circ F + 158^\circ F$)
 - Cermet SMC-10 : $-40^\circ C + 90^\circ C$ ($-40^\circ F + 194^\circ F$)

* Others upon request

** Up to 85°C depending on application

*** For Ohmic values $\geq 1 K\Omega$. Lower values upon request

HOW TO ORDER

SM-10	H04	102	A	2020	OPTIONAL EXTRA	S																																				
Series	Code	Value	Taper	Tolerance	Nut and Washer	(See note 4)																																				
SM-10 SMC-10	<table border="1"> <thead> <tr> <th>Code</th> <th>Mounting Method</th> </tr> </thead> <tbody> <tr><td>H04</td><td>H 2.5A</td></tr> <tr><td>H14</td><td>H 5A</td></tr> <tr><td>H12</td><td>H 2.5PA</td></tr> <tr><td>H20</td><td>H 5PA</td></tr> <tr><td>V10</td><td>V</td></tr> <tr><td>V11</td><td>V P</td></tr> <tr><td>H03</td><td>H 2.5B</td></tr> <tr><td>H13</td><td>H 5B</td></tr> <tr><td>H22</td><td>H 2.5PB</td></tr> <tr><td>H30</td><td>H 5PB</td></tr> </tbody> </table> (See note 1)	Code	Mounting Method	H04	H 2.5A	H14	H 5A	H12	H 2.5PA	H20	H 5PA	V10	V	V11	V P	H03	H 2.5B	H13	H 5B	H22	H 2.5PB	H30	H 5PB	<table border="1"> <tbody> <tr><td>101 = 100Ω</td></tr> <tr><td>102 = 1 K</td></tr> <tr><td>504 = 500 K</td></tr> <tr><td>505 = 5 M</td></tr> <tr><td>000 = C M</td></tr> </tbody> </table> (See note 2)	101 = 100 Ω	102 = 1 K	504 = 500 K	505 = 5 M	000 = C M	<table border="1"> <tbody> <tr><td>A = Linear</td></tr> <tr><td>B = Log.</td></tr> <tr><td>C = Alog.</td></tr> </tbody> </table> (Other tapers on request)	A = Linear	B = Log.	C = Alog.	<table border="1"> <tbody> <tr><td>2020 = $\pm 20\%$</td></tr> <tr><td>3030 = $\pm 30\%$</td></tr> </tbody> </table> (See note 3)	2020 = $\pm 20\%$	3030 = $\pm 30\%$	<table border="1"> <tbody> <tr><td>-TA = Loose nut and washer</td></tr> <tr><td>MTA = Assembled nut and washer</td></tr> <tr><td>-T = Loose nut</td></tr> <tr><td>MT = Assembled nut</td></tr> </tbody> </table>	-TA = Loose nut and washer	MTA = Assembled nut and washer	-T = Loose nut	MT = Assembled nut	
Code	Mounting Method																																									
H04	H 2.5A																																									
H14	H 5A																																									
H12	H 2.5PA																																									
H20	H 5PA																																									
V10	V																																									
V11	V P																																									
H03	H 2.5B																																									
H13	H 5B																																									
H22	H 2.5PB																																									
H30	H 5PB																																									
101 = 100 Ω																																										
102 = 1 K																																										
504 = 500 K																																										
505 = 5 M																																										
000 = C M																																										
A = Linear																																										
B = Log.																																										
C = Alog.																																										
2020 = $\pm 20\%$																																										
3030 = $\pm 30\%$																																										
-TA = Loose nut and washer																																										
MTA = Assembled nut and washer																																										
-T = Loose nut																																										
MT = Assembled nut																																										

NOTES:

- Mount. Method: • Position with "P" will be with crimped terminals.
• Denominations (a), (b) (see Mounting Methods)
- Value: Code: $\begin{matrix} 10 & 1 & 100 \Omega \\ & \swarrow & \searrow \\ & \text{Number of zeros} & \\ & \text{2 first digits of the value.} & \end{matrix}$
• Standard values: Decades of 10, 20, 22, 25, 47, 50. Other values as specials.
• 000 = CM = Switch 45° (only SMC-10)
- Tolerance (non standard). Upon request. Code eg.: $\begin{matrix} +7 & & 07 & 05 \\ -5 & = & & \swarrow \searrow \\ & & & \text{negative tolerance} \\ & & & \text{positive tolerance} \end{matrix}$
- Leave blank for SMC-10


NOTE: The information contained here should be used for reference purposes only.

SM-10 H04 + DRAWING NUMBER (Max. 16 digits)


NUT AND WASHER = Without nut and washer

This way of ordering should be used for options which are not included in the "How to order" standard and optional extras.

COMMON DIMENSIONS



STANDARD SHAFT




Shaft: The standard option is E4 L30 black colour.

TERMINALS

NOT CRIMPED



CRIMPED




PACKAGING

TESTS


QUANTITY: 200 units

See PT-10 or PTC-10 data sheets.


h 2.5



h 5



v 10



Disclaimer

The product information in this catalogue is for reference purposes. Please consult for the most up to date and accurate design information. Piher Sensors & Controls S.A., its affiliates, agents, and employees, and all persons acting on its or their behalf (collectively, "Piher"), disclaim any and all liability for any errors, inaccuracies or incompleteness contained herein or in any other disclosure relating to any product described herein. Piher disclaims any and all liability arising out of the use or application of any product described herein or of any information provided herein to the maximum extent permitted by law. The product specifications do not expand or otherwise modify Piher's terms and conditions of sale, including but not limited to the warranty expressed therein, which apply to these products. No licence, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document or by any conduct of Piher. The products shown herein are not designed for use in medical, life-saving, or life-sustaining applications unless otherwise expressly indicated. Customers using or selling Piher products not expressly indicated for use in such applications do so entirely at their own risk and agree to fully indemnify Piher for any damages arising or resulting from such use or sale. Please contact authorised Piher personnel to obtain written terms and conditions regarding products designed for such applications. Product names and markings noted herein may be trademarks of their respective owners.

Information contained in and/or attached to this catalogue may be subject to export control regulations of the European Community, USA, or other countries. Each recipient of this document is responsible to ensure that usage and/or transfer of any information contained in this document complies with all relevant export control regulations. If you are in any doubt about the export control restrictions that apply to this information, please contact the sender immediately. For any Piher International Corp. Exports, Note: All products / technologies are EAR99 Classified commodities. Exports from the United States are in accordance with the Export Administration Regulations. Diversion contrary to US law is prohibited.

