



Date									
------	--	--	--	--	--	--	--	--	--

Method to Identify Change:

Traceability code, top marking

Qualification Report:

Not applicable

Revision History:

November 6, 2019: Issued final notification.

The change described in this PCN does not alter Microchip's current regulatory compliance regarding the material content of the applicable products.

Attachment(s):

[PCN JAON-04CLDR884 Pre and Post Change Summary.pdf](#)

Please contact your local [Microchip sales office](#) with questions or concerns regarding this notification.

Terms and Conditions:

If you wish to receive Microchip PCNs via email please register for our PCN email service at our [PCN home page](#) select register then fill in the required fields. You will find instructions about registering for Microchips PCN email service in the [PCN FAQ](#) section.

If you wish to change your PCN profile, including opt out, please go to the [PCN home page](#) select login and sign into your myMicrochip account. Select a profile option from the left navigation bar and make the applicable selections.

Affected Catalog Part Numbers (CPN)

BM64SPKS1MC1-0001AA

BM64SPKS1MC1-Y001AA


BM64SPKS1MC1-00M2AA

BM64SPKS1MC1-M0M1AA

BM64SPKS1MC1-H0M1AA



MICROCHIP



A Leading Provider of Microcontroller,
Mixed-Signal, Analog & Flash-IP Solutions



CCB 4022_ Pre and Post Change Summary
PCN# JAON-04CLDR884

Top Marking Pre and Post Change

PRE CHANGE

4 lines for BM64SPKS1MC1 module as below

Location	Line	Value
Front	1	BM64SPKS1MC1
Front	2	<Mac>
Front	3	YYWW-0001AA
Front	4	CMIIT: 2016DJ2453



POST CHANGE

Add Brazil certification ID at line 5

Location	Line	Value
Front	1	BM64SPKS1MC1
Front	2	<Mac>
Front	3	YYWW-Y001AA
Front	4	CMIIT: 2016DJ2453
Front	5	ANATEL 05784-19-08759

