# BROADCOM<sup>®</sup>

# PCN: V16-001-F48070-MA

# **Product Change Notice**

Issue Date: 15 Apr 2016

Change Type:


Minor

Parts Affected:

HFBR-1541ETZ	HFBR-2541ETZ
HFBR-1542ETZ	HFBR-2542ETZ
AFBR-1644Z	AFBR-2644Z
HFBR-1547ETZ	AFBR-2541CZ

### **Description and Extent of Change:**

Increase the housing staple pin length from 2.8mm to 4.6mm, to be same as active pins.



Housing staple pins (pin5 and pin8 in red circle): Length increased from 2.8mm to 4.6mm.

Active pins (pin1 to pin4 in blue circle): No Change.

The base material and plating of staple pins remain unchanged.

### **Reason for Change:**

To match the lead length with active pins.

### Effect of Change on Fit, Form, Function, Quality, or Reliability:

There is no change on the production build, characteristic, quality and reliability of the product.

#### **Effective Date of Change:**

Sample is available upon customer request from WW1620 onwards. Timing of shipment, on or after WW1632 will vary by part number depending on customer demand, and inventory levels.

#### **Qualification Data:**

Not applicable.

These changes have been reviewed and approved by Broadcom Limited engineers and managers per Broadcom Limited procedure: Change Control and Customer Notification, 5962-6052-80.

Please contact your Broadcom Limited field sales for any questions or support requirements. Please return any response as soon as possible, but not to exceed 30 days.