



31-Oct-2023

**PCN #:** P-23-025301

**Subject :** various Fortis assemblies

**Description of Change :** replacing plating tooling on chicklets

**Reason :** Product improvement.Tooling is worn out. NO CHANGE TO FORM, FIT, OR FUNCTION or MANUFACTURING LOCATION

**Key Dates :**

**Contact By Date:**31-Jan-2024

**Implementation Date:**31-Jan-2024

Product Affected	Alias Part Number	Substitute Part Number	AliasSub Part Number
2102320-5			
2102155-2			
2-2102247-3			
2000903-1			
2000892-1			
2000944-2			
2000943-7			
2102247-2			
2102319-1			
2102247-4			
2-2102247-6			
2000943-5			
2102318-1			
2102155-1			
2102320-3			
2-2102320-4			
2000943-1			

2102159-1			
2-2102320-1			
2102315-1			
2000944-5			
2102320-2			
2102320-4			
2102316-1			
2102247-5			
2102317-1			
2102159-2			
2102247-1			
2-2102247-4			
2-2102320-2			
2000944-1			
2000943-4			
2-2102320-3			
2000944-4			
2-2102320-6			
2102247-6			
2000943-2			
2000944-7			
2102318-2			
2102247-3			
2-2102247-2			
2000903-2			
2102316-2			
2-2102247-1			
2102320-1			
2102320-6			
2-2102247-5			
2102317-2			
2-2102320-5			
2102314-1			

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.

Alert document created by IHS Markit based on content provided by TE Connectivity.