



Product Change Notification

Current Date: 06-Apr-2022

TE Connectivity

Product Change Notification: P-22-022459

PCN Date: 05-APR-22

Customer: TTI, Inc. (1305175)

Location: Maisach-gernlinden

Agreement: Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:
Self Adhesive Labels for Identification of Wire and Cables

Description of Changes
Manufacturing location change. The following Part Numbers will be transferred from the TE plant located at Idento Roedermark Germany to a TE manufacturing plant located in Tangier, Morocco.

Reason for Changes:
Dear Customer, as a result of our continuous strive to improve our processes, we hereby inform you about a transfer of tools and/or processes. The transfer is executed by following a strict transfer procedure, which guarantees no negative influence on quality, ability to supply and form-fit-function of the concerned products. The new manufacturing location is under a certified quality management system according the standard industry requirements. An internal release based on our specifications will be executed before any parts will be delivered, which guarantees the performance of the product.

Estimated Dates:	
Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):
	01-AUG-2022
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):
	No Mixed Shipments

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
053232-000	NO		TYC053232-000, RAY053232-000	5-1198213-1, STD03W-L			
1-1768038-7	NO			F96790-000, STB05-0-0			
1-1768038-8	NO			F30147-000, STB05-1-1			
1-1768038-9	NO			D78939-000, STB05-2-2			
1-1768039-2	NO			A82422-000, STB09-3-3			
1-1768039-6	NO			D99527-000, STB09-5-5			
1-1768039-8	NO			F58106-000, STB09-6-6			
1-1768039-9	NO			D27778-000, STB09-7-7			
1-1768040-0	NO			A24059-000, STB17-3-3			
1-1768040-3	NO			E08473-000, STB17-5-5			
122028-000	NO			9-1198207-8, STD03W-G			
145890-000	NO			1198206-5, STD02W-G			
165426-000	NO			2-1198205-2, STD02W-L			
167476-000	NO		RAY167476-000	1-1198203-7, STD03W-A			
1768039-4	NO		TYC1768039-4	C79534-000, STB09-0-0			
1768039-6	NO		TYC1768039-6	A88198-000, STB09-1-1			
1768039-9	NO		TYC1768039-9	C89968-000, STB09-2-2			
1768040-4	NO			D36980-000, STB17-0-0			
185576-000	NO			5-1198204-4, STD03W-Q			
2-1768037-8	NO			E47027-000, STB02-5-5			
2-1768038-0	NO			A49581-000, STB05-3-3			
2-1768038-1	NO			D33128-000, STB05-5-5			
2-1768038-2	NO			D77905-000, STB05-6-6			
2-1768038-3	NO			F16862-000, STB05-7-7			
2-1768038-4	NO			D32116-000, STB05-8-8			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
2-1768039-0	NO			D19555-000, STB09-8-8			
2-1768043-5	NO		TYC2-1768043-5	F18215-000, STD05W-V			
213166-000	NO		RAY213166-000	3-1198202-3, STD03W-B			
236988-000	NO		TYC236988-000, RAY236988-000	4-1198198-2, STD03W-M			
261416-000	NO			1198198-3, STD01W-3			
3-1768038-3	NO			F19003-000, STB06-0-0			
3-1768038-8	NO			E62801-000, STB06-1-1			
3-1768043-4	NO		TYC3-1768043-4	"A83182-000", "STD05Y-4"			
3-1768043-5	NO		TYC3-1768043-5	"E85069-000", "STD05Y-5"			
3-1768043-6	NO		TYC3-1768043-6	"D39911-000", "STD05Y-6"			
3-1768043-9	NO		TYC3-1768043-9	"E40630-000", "STD05Y-9"			
321874-000	NO		RAY321874-000, TYC321874-000	2-1198190-2, STD03W-0			
365180-000	NO		RAY365180-000	5-1198189-4, STD02Y-4			
379708-000	NO		RAY379708-000	1198186-8, STD02Y-8			
4-1768037-8	NO			F92121-000, STB03-0-0			
4-1768038-4	NO			F98713-000, STB06-2-2			
4-1768039-4	NO			F28366-000, STB12-0-0			
4-1768039-5	NO			E60240-000, STB12-1-1			
4-1768039-6	NO			E92597-000, STB12-2-2			
4-1768039-7	NO			C22334-000, STB12-3-3			
4-1768039-8	NO			C50623-000, STB12-5-5			
4-1768039-9	NO			D21308-000, STB12-6-6			
403072-000	NO		TYC403072-000, RAY403072-000	5-1198183-9, STD03W-5			
424514-000	NO			3-1198185-4, STD02W-T			
446638-000	NO		RAY446638-000	7-1198182-7, STD03W-8			
472156-000	NO			5-1198179-5, STD01W-5			
489958-000	NO			5-1198177-1, STD03W-SLASH			
5-1768037-3	NO			D10730-000, STB03-1-1			
5-1768037-8	NO			A13096-000, STB03-2-2			
5-1768038-0	NO			F53609-000, STB06-3-3			
5-1768039-0	NO			D08200-000, STB12-7-7			
5-1768039-1	NO			E43082-000, STB12-8-8			
5-1768042-9	NO		TYC5-1768042-9	"C49366-000", "STD03Y-MINUS"			
543032-000	NO			6-1198173-3, STD01W-A			
557314-000	NO		RAY557314-000	1-1198171-8, STD02Y-1			
559060-000	NO		RAY559060-000, TYC559060-000	3-1198171-8, STD03W-R			
571230-000	NO		TYC571230-000, RAY571230-000	1198172-5, STD03W-6			
593358-000	NO		RAY593358-000, TYC593358-000	1-1198170-4, STD03W-U			
593434-000	NO		RAY593434-000, TYC593434-000	1-1198170-5, STD03W-X			
6-1768037-3	NO			A71066-000, STB03-3-3			
6-1768038-0	NO			F37971-000, STB06-5-5			
6-1768038-5	NO			F28558-000, STB06-6-6			
6-1768039-0	NO			F12342-000, STB15-0-0			
6-1768039-1	NO			E13080-000, STB15-1-1			
6-1768039-4	NO			D02389-000, STB15-2-2			
6-1768039-7	NO			C65953-000, STB15-3-3			
6-1768041-6	NO		TYC6-1768041-6, RAY6-1768041-6	"E82756-000", "STD02Y-0"			
6-1768042-4	NO		TYC6-1768042-4	"F80834-000", "STD03Y-PLUS"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
6-1768042-8	NO			"C81575-000", "STD03Y-T"			
7-1768036-9	NO			F20147-000, STB01-0-0			
7-1768037-3	NO			A68344-000, STB03-5-5			
7-1768037-8	NO			E48112-000, STB03-6-6			
7-1768038-1	NO			D97118-000, STB06-7-7			
7-1768038-6	NO			C62053-000, STB06-8-8			
7-1768039-0	NO			A49524-000, STB15-5-5			
7-1768039-2	NO			C04941-000, STB15-6-6			
7-1768039-6	NO			E85992-000, STB15-8-8			
7-1768042-1	NO			"D11441-000", "STD03Y-W"			
7-1768042-4	NO		TYC7-1768042-4	E47065-000, STD05W-1			
7-1768042-5	NO		TYC7-1768042-5	F79409-000, STD05W-2			
7-1768042-7	NO		TYC7-1768042-7	F46448-000, STD05W-4			
7-1768042-8	NO		TYC7-1768042-8	A12429-000, STD05W-5			
739622-000	NO			3-1198158-9, STD02W-H			
761148-000	NO		TYC761148-000, RAY761148-000	8-1198157-8, STD03W-I			
774414-000	NO		RAY774414-000	2-1198155-7, STD03Y-8			
8-1768036-2	NO			A20701-000, STB01-1-1			
8-1768036-5	NO			A42382-000, STB01-2-2			
8-1768036-8	NO			D61939-000, STB01-3-3			
8-1768037-3	NO			A79865-000, STB03-7-7			
8-1768037-8	NO			F21758-000, STB03-8-8			
8-1768039-2	NO		TYC8-1768039-2	D60131-000,,491701, STB15-BLANK-2			
8-1768039-4	NO		TYC8-1768039-4	A71420-000,,491703, STB15-BLANK-5			
8-1768039-5	NO		TYC8-1768039-5	A70477-000, STB15-BLANK-6			
8-1768042-2	NO			A84581-000, STD05W-9			
819694-000	NO		RAY819694-000, TYC819694-000	5-1198153-2, STD02W-1			
845704-000	NO			1-1198151-4, STD03W-D			
859984-000	NO		RAY859984-000	9-1198147-4, STD02Y-6			
875154-000	NO		RAY875154-000, TYC875154-000, RAYSTD03W-V	2-1198149-0, STD03W-V			
886014-000	NO			8-1198145-6, STD01W-4			
9-1768036-3	NO			E68974-000, STB01-5-5			
9-1768036-9	NO			F35140-000, STB01-7-7			
9-1768040-2	NO		TYC9-1768040-2	"E71285-000", "STD01Y-0"			
9-1768040-3	NO		TYC9-1768040-3	"D25942-000", "STD01Y-1"			
9-1768040-4	NO		TYC9-1768040-4	"E15550-000", "STD01Y-2"			
9-1768040-6	NO		TYC9-1768040-6	"C69971-000", "STD01Y-4"			
9-1768042-7	NO		TYC9-1768042-7	F96025-000, STD05W-F			
961776-000	NO		RAY961776-000	3-1198139-8, STD02W-F			
972648-000	NO		RAY972648-000	2-1198140-8, STD02Y-7			
983856-000	NO		RAY983856-000	5-1198140-7, STD02Y-2			
996838-000	NO		RAY996838-000	9-1198138-7, STD02Y-5			



Product Change Notification

Current Date: 06-Apr-2022

TE Connectivity

Product Change Notification: P-22-022459

PCN Date: 05-APR-22

Customer: TTI, Inc. (3057778)

Location: Maisach-gernlinden

Agreement: Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

Self Adhesive Labels for Identification of Wire and Cables

Description of Changes

Manufacturing location change. The following Part Numbers will be transferred from the TE plant located at Idento Roedermark Germany to a TE manufacturing plant located in Tangier, Morocco.

Reason for Changes:

Dear Customer, as a result of our continuous strive to improve our processes, we hereby inform you about a transfer of tools and/or processes. The transfer is executed by following a strict transfer procedure, which guarantees no negative influence on quality, ability to supply and form-fit-function of the concerned products. The new manufacturing location is under a certified quality management system according the standard industry requirements. An internal release based on our specifications will be executed before any parts will be delivered, which guarantees the performance of the product.

Estimated Dates:

Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):
	01-AUG-2022
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):
	No Mixed Shipments

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
053232-000	NO		TYC053232-000, RAY053232-000	5-1198213-1, STD03W-L			
1-1768038-7	NO			F96790-000, STB05-0-0			
1-1768038-8	NO			F30147-000, STB05-1-1			
1-1768038-9	NO			D78939-000, STB05-2-2			
1-1768039-2	NO			A82422-000, STB09-3-3			
1-1768039-6	NO			D99527-000, STB09-5-5			
1-1768039-8	NO			F58106-000, STB09-6-6			
1-1768039-9	NO			D27778-000, STB09-7-7			
1-1768040-0	NO			A24059-000, STB17-3-3			
1-1768040-3	NO			E08473-000, STB17-5-5			
122028-000	NO			9-1198207-8, STD03W-G			
145890-000	NO			1198206-5, STD02W-G			
165426-000	NO			2-1198205-2, STD02W-L			
167476-000	NO		RAY167476-000	1-1198203-7, STD03W-A			
1768039-4	NO		TYC1768039-4	C79534-000, STB09-0-0			
1768039-6	NO		TYC1768039-6	A88198-000, STB09-1-1			
1768039-9	NO		TYC1768039-9	C89968-000, STB09-2-2			
1768040-4	NO			D36980-000, STB17-0-0			
185576-000	NO			5-1198204-4, STD03W-Q			
2-1768037-8	NO			E47027-000, STB02-5-5			
2-1768038-0	NO			A49581-000, STB05-3-3			
2-1768038-1	NO			D33128-000, STB05-5-5			
2-1768038-2	NO			D77905-000, STB05-6-6			
2-1768038-3	NO			F16862-000, STB05-7-7			
2-1768038-4	NO			D32116-000, STB05-8-8			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
2-1768039-0	NO			D19555-000, STB09-8-8			
2-1768043-5	NO		TYC2-1768043-5	F18215-000, STD05W-V			
213166-000	NO		RAY213166-000	3-1198202-3, STD03W-B			
236988-000	NO		TYC236988-000, RAY236988-000	4-1198198-2, STD03W-M			
261416-000	NO			1198198-3, STD01W-3			
3-1768038-3	NO			F19003-000, STB06-0-0			
3-1768038-8	NO			E62801-000, STB06-1-1			
3-1768043-4	NO		TYC3-1768043-4	"A83182-000", "STD05Y-4"			
3-1768043-5	NO		TYC3-1768043-5	"E85069-000", "STD05Y-5"			
3-1768043-6	NO		TYC3-1768043-6	"D39911-000", "STD05Y-6"			
3-1768043-9	NO		TYC3-1768043-9	"E40630-000", "STD05Y-9"			
321874-000	NO		RAY321874-000, TYC321874-000	2-1198190-2, STD03W-0			
365180-000	NO		RAY365180-000	5-1198189-4, STD02Y-4			
379708-000	NO		RAY379708-000	1198186-8, STD02Y-8			
4-1768037-8	NO			F92121-000, STB03-0-0			
4-1768038-4	NO			F98713-000, STB06-2-2			
4-1768039-4	NO			F28366-000, STB12-0-0			
4-1768039-5	NO			E60240-000, STB12-1-1			
4-1768039-6	NO			E92597-000, STB12-2-2			
4-1768039-7	NO			C22334-000, STB12-3-3			
4-1768039-8	NO			C50623-000, STB12-5-5			
4-1768039-9	NO			D21308-000, STB12-6-6			
403072-000	NO		TYC403072-000, RAY403072-000	5-1198183-9, STD03W-5			
424514-000	NO			3-1198185-4, STD02W-T			
446638-000	NO		RAY446638-000	7-1198182-7, STD03W-8			
472156-000	NO			5-1198179-5, STD01W-5			
489958-000	NO			5-1198177-1, STD03W-SLASH			
5-1768037-3	NO			D10730-000, STB03-1-1			
5-1768037-8	NO			A13096-000, STB03-2-2			
5-1768038-0	NO			F53609-000, STB06-3-3			
5-1768039-0	NO			D08200-000, STB12-7-7			
5-1768039-1	NO			E43082-000, STB12-8-8			
5-1768042-9	NO		TYC5-1768042-9	"C49366-000", "STD03Y-MINUS"			
543032-000	NO			6-1198173-3, STD01W-A			
557314-000	NO		RAY557314-000	1-1198171-8, STD02Y-1			
559060-000	NO		RAY559060-000, TYC559060-000	3-1198171-8, STD03W-R			
571230-000	NO		TYC571230-000, RAY571230-000	1198172-5, STD03W-6			
593358-000	NO		RAY593358-000, TYC593358-000	1-1198170-4, STD03W-U			
593434-000	NO		RAY593434-000, TYC593434-000	1-1198170-5, STD03W-X			
6-1768037-3	NO			A71066-000, STB03-3-3			
6-1768038-0	NO			F37971-000, STB06-5-5			
6-1768038-5	NO			F28558-000, STB06-6-6			
6-1768039-0	NO			F12342-000, STB15-0-0			
6-1768039-1	NO			E13080-000, STB15-1-1			
6-1768039-4	NO			D02389-000, STB15-2-2			
6-1768039-7	NO			C65953-000, STB15-3-3			
6-1768041-6	NO		TYC6-1768041-6, RAY6-1768041-6	"E82756-000", "STD02Y-0"			
6-1768042-4	NO		TYC6-1768042-4	"F80834-000", "STD03Y-PLUS"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
6-1768042-8	NO			"C81575-000", "STD03Y-T"			
7-1768036-9	NO			F20147-000, STB01-0-0			
7-1768037-3	NO			A68344-000, STB03-5-5			
7-1768037-8	NO			E48112-000, STB03-6-6			
7-1768038-1	NO			D97118-000, STB06-7-7			
7-1768038-6	NO			C62053-000, STB06-8-8			
7-1768039-0	NO			A49524-000, STB15-5-5			
7-1768039-2	NO			C04941-000, STB15-6-6			
7-1768039-6	NO			E85992-000, STB15-8-8			
7-1768042-1	NO			"D11441-000", "STD03Y-W"			
7-1768042-4	NO		TYC7-1768042-4	E47065-000, STD05W-1			
7-1768042-5	NO		TYC7-1768042-5	F79409-000, STD05W-2			
7-1768042-7	NO		TYC7-1768042-7	F46448-000, STD05W-4			
7-1768042-8	NO		TYC7-1768042-8	A12429-000, STD05W-5			
739622-000	NO			3-1198158-9, STD02W-H			
761148-000	NO		TYC761148-000, RAY761148-000	8-1198157-8, STD03W-I			
774414-000	NO		RAY774414-000	2-1198155-7, STD03Y-8			
8-1768036-2	NO			A20701-000, STB01-1-1			
8-1768036-5	NO			A42382-000, STB01-2-2			
8-1768036-8	NO			D61939-000, STB01-3-3			
8-1768037-3	NO			A79865-000, STB03-7-7			
8-1768037-8	NO			F21758-000, STB03-8-8			
8-1768039-2	NO		TYC8-1768039-2	D60131-000,,491701, STB15-BLANK-2			
8-1768039-4	NO		TYC8-1768039-4	A71420-000,,491703, STB15-BLANK-5			
8-1768039-5	NO		TYC8-1768039-5	A70477-000, STB15-BLANK-6			
8-1768042-2	NO			A84581-000, STD05W-9			
819694-000	NO		RAY819694-000, TYC819694-000	5-1198153-2, STD02W-1			
845704-000	NO			1-1198151-4, STD03W-D			
859984-000	NO		RAY859984-000	9-1198147-4, STD02Y-6			
875154-000	NO		RAY875154-000, TYC875154-000, RAYSTD03W-V	2-1198149-0, STD03W-V			
886014-000	NO			8-1198145-6, STD01W-4			
9-1768036-3	NO			E68974-000, STB01-5-5			
9-1768036-9	NO			F35140-000, STB01-7-7			
9-1768040-2	NO		TYC9-1768040-2	"E71285-000", "STD01Y-0"			
9-1768040-3	NO		TYC9-1768040-3	"D25942-000", "STD01Y-1"			
9-1768040-4	NO		TYC9-1768040-4	"E15550-000", "STD01Y-2"			
9-1768040-6	NO		TYC9-1768040-6	"C69971-000", "STD01Y-4"			
9-1768042-7	NO		TYC9-1768042-7	F96025-000, STD05W-F			
961776-000	NO		RAY961776-000	3-1198139-8, STD02W-F			
972648-000	NO		RAY972648-000	2-1198140-8, STD02Y-7			
983856-000	NO		RAY983856-000	5-1198140-7, STD02Y-2			
996838-000	NO		RAY996838-000	9-1198138-7, STD02Y-5			