



31-Oct-2023

PCN #: PCN-23-191212

Subject : SBP labels

Description of Change : New liner sources due to supplier stopping current grade. The new liner has equivalent performances and behavior during thermal transfer printing step, the color is slightly whiter.

Reason :

Key Dates :

Contact By Date:01-May-2024

Implementation Date:01-May-2024

Product Affected	Alias Part Number	Substitute Part Number	AliasSub Part Number
1SET530111R000 0			
CN9926-000	1-1200607-8, SBP100375WE2.5 , SBP100375WE2.5		
2331956-1			
2407211-1			
2315467-1			
2322525-1			
CP8958-000	1899566-5, SBP200375OE2.5		
2381797-1			
CN9939-000	5-1200974-5, SBPH100375WE1 -T200		
1SET530119R000 0			
CN9919-000	3-1899555-4, SBP100075WE5		

1SET530106R000 0			
CR6865-000	SBP050100WE5- T200, 7-1899729- 5		
CN9934-000	4-1201036-7, SBP200225YW2.5		
1SET530115R000 0			
1SET530120R000 0			
CN2894-000	SBP050143WE5- T200, 2-1199194- 3		
CN2899-000	SBP100143WE2.5 -T200, 6-1199193- 0		
2418017-1			
2302650-1			
8-1768817-2			
CR1703-000	SBP200743YW1, 1899783-9		
2-1878617-3			
1SET530118R000 0			
CR4925-000	SBP100594YW1		
2-1768395-8			
1SET530101R000 0			
2407216-1			
CN9941-000	9-1200955-8, SBPH100375WE2 .5		
2466224-1			
2385300-1			
2407948-1			
1SET530114R000 0			
CN9922-000	7-1200608-8, SBP100225WE5		
CS9355-000	7-1899630-9		
2416423-1			
CV2085-000	9-1899769-5, SBP0753000YW2		

2-1768395-6			
2-1878567-6			
2407225-1			
CS4293-000	7-1899616-4, SBP200400WE2.5		
CN9936-000	7-1200603-0, SBP200375WE2.5		
CN9932-000	5-1200603-9, SBP200143WE2.5		
CM9614-000	SBP100143WE5, 5-1899545-9		
2407218-1			
2322519-1			
CN9935-000	5-1899545-8, SBP200375WE1- T200		
CM9613-000	5-1200612-3, SBP050100WE10		
2403915-1			
2-1768395-7			
CN9921-000	8-1199199-2, SBP100225WE2.5 -T200		
CN2893-000	SBP050143WE10, 1200604-5		
2407217-1			
CN2895-000	SBP075094WE10, 7-1201052-4		
CP8341-000	SBP050143YW10, 1-1899741-6		
CN9937-000	8-1200602-0, SBP200743WE1		
2331953-1			
2407215-1			
CN9923-000	6-1201321-6, SBP100375GN2.5		
1SET530112R000 0			
2381796-1			
1878658-5	QC210AC		
2322529-1			
1SET530108R000 0			

2331951-1			
1SET530102R000 0			
2322527-1			
3-1768395-1			
2331955-1			
2403853-1			
2407220-1			
CR6410-000	SBP100143YW5		
2-1878532-4	SBP200143YW2.5		
CR2326-000			
2331952-1			
CR1509-000	SBP100225RD5, 6-1899718-8		
CT79703001	4-1899658-1		
1SET530109R000 0			
8-1768423-2			
3-1768396-8			
1SET530117R000 0			
1SET530104R000 0			
1SET530105R000 0			
2331950-1			
CN9927-000	7-1199193-5, SBP100594WE0.5 -T200		
2403832-1			
CR7100-000	2-1899599-1		
1SET530110R000 0			
2407221-1			
CN9929-000	3-1200607-6, SBP100743WE1		
CN2896-000	SBP080150WE10, 8-1200601-3		
2407222-1			
2407224-1			

1SET530107R000 0			
2403876-1			
3-1768388-1			
CN9920-000	5-1200805-3		
CN9930-000	6-1200607-2, SBP190319WE2.5		
2448636-1			
2407214-1			
2331954-1			
1SET530113R000 0			
CT78813001	8-1899652-7, SBP100143GN5		
2407213-1			
CN2898-000	SBP100143WE1.5 -1AC-T200, 9- 1201371-7		
CN9928-000	1-1200606-6, SBP100594WE1		
2407219-1			
CN9931-000	9-1200607-3, SBP190594WE1		
CP7104-000	SBP200143WE1- T200, 7-1899710- 0		
2416424-1			
3-1768390-3			
1SET530116R000 0			
3-1768396-7			
2-1878605-6			
CN2897-000	SBP080150WE5- T200, 1-1199193- 2		
2459136-1			
2322531-1			
1SET530100R000 0			
1SET530103R000 0			

CN9925-000	8-1199192-9, SBP100375WE1- T200		
2414084-1			
CN9933-000	5-1200607-2, SBP200225WE2.5		

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.

Alert document created by IHS Markit based on content provided by TE Connectivity.