










# RTW Soldering Tips

## Chisel



A = Width mm  
B = Thickness mm  
C = Length mm


Model	A	B	C	PU	Order No.
<b>RTW SOLDERING TIP SET</b>	0.7	0.4		1	T005 44 661 99N
<b>RTW 2, 45°</b> 	0.7	0.4		1	T005 44 652 99
<b>RTW 3 45°</b> 	1.0	3	18	1	T005 44 653 99
<b>RTW 4 45°</b> 	1.0	6	20	1	T005 44 654 99
<b>RTW 7NW TIP SET 08X04MM CHROME</b>	1.0	3	18	1	T005 44 663 99


Model	A	B	C	PU	Order No.
<b>RTW 8</b> 	1.3	0.4	19	1	T005 44 664 99
<b>RTW 9</b> 	1.0	3.2	19	1	T005 44 666 99
<b>RTW 10</b> 	1.0	10	19	1	T005 44 668 99
<b>RTW 11</b> 	1.0	6	19	1	T005 44 667 99

## Conical



A = Width mm  
B = Thickness mm  
C = Length mm

Model	A	B	C	PU	Order No.
<b>RTW 1 45°</b> 	0.4			1	T005 44 651 99

Model	A	B	C	PU	Order No.
<b>RTW 6NW 45°</b> 	0.1			1	T005 44 656 99

A = Width mm  
B = Thickness mm  
C = Length mm

Model	A	B	C	PU	Order No.
<b>RTW MEASURING TIP SET</b>					