

Product Change Notification



Product Group: Vishay Dale/September 18, 2012/PCN-DI-241-2015 Rev 0

Design change on the IFSC-1111AZ-01, IFSC-1111AB-01 and IFSC-1515AH-01

DESCRIPTION OF CHANGE: The design of the IFSC-1111AZ-01, IFSC-1111AB-01, and IFSC-1515AH-01 is changing, along with the electrical specifications within these series. Please see attached new data sheets, or the Vishay web site.

http://www.vishay.com/docs/34293/sc11az01.pdf for IFSC-1111AZ-01 http://www.vishay.com/docs/34292/sc11ab01.pdf for IFSC-1111AB-01 http://www.vishay.com/docs/34295/sc15ah01.pdf for IFSC-1515AH-01

Original Part

New Part





CLASSIFICATION OF CHANGE: Assembly Process/Structure

REASON FOR CHANGE: The new design part is more robust than the original series. The new parts also have higher saturation current, making them a better part.

EXPECTED INFLUENCE ON QUALITY/RELIABILTY/PERFORMANCE: N/A

PRODUCT CATAGORY: Inductors

PART NUMBERS/SERIES/FAMILIES AFFECTED:

VISHAY BRAND(s): Vishay Dale

TIME SCHEDULE:

Start Shipment Date: Immediately

Last Time Buy Date: NA Last Time Shipment Date: NA

SAMPLE AVAILABILITY: N/A

PRODUCT IDENTIFICATION: Date Code

QUALIFICATION DATA: Available upon request

This PCN is considered approved, without further notification, unless we receive specific customer concerns or as specified by contract.

Vishay Intertechnology, Inc.

ISSUED BY: Doug Lillie, Sr. Product Marketing Manager

For further information, please contact your regional Vishay office.

CONTACT INFORMATION:

The Americas

Vishay Intertechnology, Inc 1505 East Highway 50 P. O. Box 180 Yankton, South Dakota 57078 Ph: 1 605-665-9301

Fax: 1 605-665-1627 doug.lillie@vishay.com

Europe

Vishay Electronic GmbH Geheimrat-Rosenthal-Str. 100 95100 Selb Germany

Ph: 49-9287-71-2282 Fax: 49-9287-71-2496 jens.walther@vishay.com

Asia

Vishay Asia Pte Ltd. 25 Tampines Street 92 Keppel Building #02-00 Singapore 528877 Ph: +65-788-6668 Fax: +65-788-3383 victor.goh@vishay.com