

Product Family	Microfit 3.0 Crimp Terminal Female	10701019	
		GCN Number	
Series	Various	August 27, 2015	
		Date Issued	
Reason For Change	New, Modified, Or Replacement Tooling		
Change Description	The letter is being sent to inform you that Molex is building a new die to make 43030 series tin plated terminals in Lincoln.		
Series image - reference only			
Part Numbers Affected	Please refer to CustomerPartList.csv attached to	e-mail message.	
Reason For Short Notice Exception			
Assessment Of Change (How Product Will Be Qualified & Validated)	There will be no change to the parts as a result of the new die. The die will complete Molex internal qualification/approval process prior to its release to production.		
Internal Molex Qualification Date (Planned Date Information Available)	September 18, 2015		
Sample Availability Date (Changed Part)	September 18, 2015		
Date of Implementation	October 01, 2015		
Method of Identifying Change	Product made after October 1, 2015 can be from	the new die.	
Recommended Replacement Parts	Not Applicable		
Last Time Buy Date for Obsolete Parts			
Last Time Ship Date for Obsolete Parts			

Contact	Name	E-mail	Phone Number
Sales Engineer	Please refer to e-mail message for your local sales engineer.		
Regional Coordinator (Japan and Korea)	Naomi Maruyama	Naomi.Maruyama@molex.co.jp	+81-46-265-2416
Regional Coordinator (Asia- excluding Japan and Korea)	Allen Yu	Allen.Yu@molex.com	+886-2-66251751
Regional Coordinator (Europe, Middle East, Africa)	Agnes Mburu	Agnes.Mburu@molex.com	+31-40-295-8271
Regional Coordinator (Americas)	Maria Sullivan	Maria.Sullivan@molex.com	1-727-322-4352

Molex, Inc. 2222 Wellington Court Lisle, IL 60532 TEL: 630-969-4747 www.molex.com