



Expertise Applied | Answers Delivered

8755 W. Higgins Road  
Suite 500  
Chicago, IL 60631

[www.littelfuse.com](http://www.littelfuse.com)

---

Subject: Component Change To SPF002 Fuse

Document# LFPCN\_PG0034

Date: 4/07/2013

This letter is to inform Littelfuse Sales, Sales Support & Customers of a component change used in the construction of the SPF002 (2 amp) fuses. The internal filament wire is being changed to improve manufacturability.

This change will have no significant effect on performance characteristics and shall meet or exceed UL standards for this rating. The product will meet IEC60269-6 performance requirements but will no longer be third party certified by VDE due to low customer demand for this certification. All changes will be validated by UL. This running change will be implemented on all production after June 1<sup>st</sup>, 2013.

There is no change to product numbers and no updates are required to ordering systems. Please see the table below for the affected SKUs.

Affected SKUs
0SPF002.H
0SPF002.HXG
0SPF002.HXR
0SPF002.T
90.0002

Thank you for your continued business.

Sincerely,

Jim McGuire  
Associate Product Manager  
Littelfuse Powr-Gard Products