

Global Change Notification (GCN)

Product Family	Modular Jacks	10704531	
		GCN Number	
Series	85502, 95540	August 17, 2015	
		Date Issued	
Reason For Change	MOQ (Not SPQ)		
Change Description	This is to inform you that Molex is changing the MOQ on some of its Modular Jacks Products. The reason for this change is to eliminate the risk of damaged parts on the blister pack reel. Due to the height of the blister pack pocket there is a risk where the first winding of the blister pack steps up that the part at this point could get damaged. To prevent this we are increasing the number of empty pockets at the centre of the blister pack reel to ensure the empty pockets go beyond this step up.		
Part Numbers Affected	Please refer to CustomerPartList.csv attached to e-r	mail message.	
Reason For Short Notice Exception	8D Corrective Action Changes		
Assessment Of Change (How Product Will Be Qualified & Validated)	This change has no affect on fit, form or function		
Internal Molex Qualification Date (Planned Date Information Available)			
Sample Availability Date (Changed Part)			
Date of Implementation	August 28, 2015		
Method of Identifying Change	Label on box with new quantity		
Recommended Replacement Parts	N/A		
Last Time Buy Date for Obsolete Parts			
Last Time Ship Date for Obsolete Parts			

Contact	Name	E-mail	Phone Number
Sales Engineer	Please refer to e-mail message for your local sales engineer.		
Regional Coordinator (Japan and Korea)	Naomi Maruyama	Naomi.Maruyama@molex.co.jp	+81-46-265-2416
Regional Coordinator (Asia- excluding Japan and Korea)	Allen Yu	Allen.Yu@molex.com	+886-2-66251751
Regional Coordinator (Europe, Middle East, Africa)	Agnes Mburu	Agnes.Mburu@molex.com	+31-40-295-8271
Regional Coordinator (Americas)	Maria Sullivan	Maria.Sullivan@molex.com	1-727-322-4352

Molex, Inc. 2222 Wellington Court Lisle, IL 60532 TEL: 630-969-4747 www.molex.com