



# PT Soldering tips

## Chisel shape



A = Width mm  
B = Thickness mm  
C = Length mm

Model	A	B	C	Temperature °C	PU	Order No.
<b>PT A6</b> 	1.6	0.7	33	310	1	4PTA6-1
<b>PT A7</b> 	1.6	0.7	33	370	1	4PTA7-1
<b>PT A8</b> 	1.6	0.7	33	425	1	4PTA8-1
<b>PT B6</b> 	2.4	0.8	33	310	1	4PTB6-1
<b>PT B7</b> 	2.4	0.8	33	370	1	4PTB7-1
<b>PT B8</b> 	2.4	0.8	33	425	1	4PTB8-1
<b>PT B9</b> 	2.4	0.8	33	480	1	4PTB9-1
<b>PT C7</b> 	3.2	0.8	33	370	1	4PTC7-1
<b>PT C8</b> 	3.2	0.8	33	425	1	4PTC8-1
<b>PT C9</b> 	3.2	0.8	33	480	1	4PTC9-1
<b>PT D7</b> 	4.6	0.8	33	370	1	4PTD7-1
<b>PT D8</b> 	4.6	0.8	33	425	1	4PTD8-1
<b>PT D9</b> 	4.6	0.8	33	480	1	4PTD9-1
<b>PT E7</b> 	5.6	1.2	33	370	1	4PTE7-1
<b>PT E8</b> 	5.6	1.2	33	425	1	4PTE8-1

Soldering Stations

Soldering iron  
and safety restSoldering tips  
and nozzles

Preheating plates

Soldering baths

Circuit board holder
















Solder feeder

Hot air heating gun

Temperature  
measuring

Accessories



Model	A	B	C	Temperature °C	PU	Order No.
<b>PT E9</b> 	5.6	1.2	33	480	1	4PTE9-1
<b>PT H6</b> 	0.8	0.4	35	310	1	4PTH6-1
<b>PT H7</b> 	0.8	0.4	35	370	1	4PTH7-1
<b>PT H8</b> 	0.8	0.4	35	425	1	4PTH8-1
<b>PT K6</b> 	1.2	0.4	42	310	1	4PTK6-1
<b>PT K7</b> 	1.2	0.4	42	370	1	4PTK7-1
<b>PT K8</b> 	1.2	0.4	42	425	1	4PTK8-1
<b>PT L6</b> 	2.0	1.0	44	310	1	4PTL6-1
<b>PT L7</b> 	2.0	1.0	42	370	1	4PTL7-1
<b>PT L8</b>	2.0	1.0	42	425	1	4PTL8-1
<b>PT M7</b> 	3.2	1.2		370	1	4PTM7-1
<b>PT M8</b> 	3.2	1.2		425	1	4PTM8-1
<b>PT M9</b> 	3.2	1.2		480	1	4PTM9-1
<b>PT MX7</b> 	3.2	1.2		370	1	T005 41 307 99
<b>PT R7</b> 	1.6	0.7	33	370	1	4PTR7-1
<b>PT R8</b> 	1.6	0.7	33	425	1	4PTR8-1



Round



A = Width mm  
B = Thickness mm  
C = Length mm

Model	A	B	C	Temperature °C	PU	Order No.
 PT AA7	1.6		33	370	1	4PTAA7-1
 PT AA8	1.6		33	425	1	4PTAA8-1
 PT AA9	1.6		33	480	1	4PTAA9-1
 PT BB7	2.4		34.5	370	1	4PTBB7-1
 PT BB8	2.4		34.5	425	1	4PTBB8-1
 PT BB9	2.4		34.5	480	1	4PTBB9-1
 PT BS7	2.4		34.5	480	1	4PTBS7-1
 PT CC7	3.2		33	370	1	4PTCC7-1
 PT CC8	3.2		33	425	1	4PTCC8-1
 PT CC9	3.2		33	480	1	4PTCC9-1
 PT CS7	3.2		33	370	1	4PTCS7-1
 PT DD7	5.0		33	370	1	4PTDD7-1
 PT DD8	5.0		33	425	1	4PTDD8-1
 PT DD9	5.0		33	480	1	4PTDD9-1
 PT F7	1.2		33	370	1	4PTF7-1
 PT F8	1.2		33	425	1	4PTF8-1
 PT O6	0.8		44	310	1	4PTO6-1
 PT O7	0.8		44	370	1	4PTO7-1
 PT O8	0.8		44	425	1	4PTO8-1

Soldering Stations

Soldering iron and safety rest

Soldering tips and nozzles

Preheating plates

Soldering baths

Circuit board holder





Solder feeder

Hot air heating gun

Temperature measuring






Accessories



Model	A	B	C	Temperature °C	PU	Order No.
<b>PT 09</b> 	0.8		44		1	4PT09- 1
<b>PT S7</b> 	0.4		44	370	1	4PTS7-1
<b>PT S8</b> 	0.4		44	425	1	4PTS8-1
<b>PT P7</b> 	44	0.30	44	425	1	4PTP7-1

### Adapter

A = Width mm  
B = Thickness mm  
C = Length mm







Model	A	B	C	PU	Order No.	Model	A	B	C	PU	Order No.
<b>PT5-LT</b> 				1	T005 87 207 85N	<b>PT8-LT</b> 				1	T005 87 207 88N
<b>PT6-LT</b> 				1	T005 87 207 86N	<b>PT9-LT</b> 				1	T005 87 207 89N
<b>PT7-LT</b> 				1	T005 87 207 87						

## RTP Soldering tips

### Chisel shape



A = Width mm  
B = Thickness mm  
C = Length mm

Model	Old name	A	B	C	PU	Order No.
<b>RTP 002 S</b> 		0.2	0.1	17	1	T005 01 039 99
<b>RTP 002 S NW</b> 		0.2	0.1	17	1	T005 01 040 99
<b>RTP 004 S</b> 		0.4	0.2	17	1	T005 01 041 99
<b>RTP 008 S</b> 		0.8	0.3	17	1	T005 01 042 99
<b>RTP 010 S</b> 		1	0.3	17	1	T005 01 043 99
<b>RTP 013 S</b> 		1.3	0.3	17	1	T005 01 044 99