



Product Change Notification

Current Date: 07-Jul-2020

TE Connectivity

Product Change Notification: P-20-019260

PCN Date: 07-JUL-20

Customer: TTI, Inc. (1305175)

Location: Maisach-gernlinden

Agreement: Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:
Change of approved manufacturing location for Type 91 Customers ONLY

Description of Changes
This notice only applies to customers in the Asia Pacific region. The following product lines typically supplied from TE s Kunshan, China, manufacturing plant will be supplied from a second qualified TE manufacturing location outside of the Asia Pacific region. This will have no impact on the fit, form or function of the product. Below are the alternative manufacturing locations: Spec 55 - Tijuana, Mexico or Redwood, CA, USA Spec 44 - Tijuana, Mexico or Redwood, CA, USA 100G (Incl. CK0226 & CK0042) Swindon, UK ZHPCG (Incl. CK0226 & CK0042) Swindon, UK C-Lite Swindon, UK

Reason for Changes:
As part of an effort to continually evaluate and optimize TE's operational footprint and service level, TE AD&M (Aerospace, Defense & Marine) Business Unit has announced its plan to close its wire & cable manufacturing site in Kunshan, China. The plan will help to streamline manufacturing processes and consolidate resources to enable a more competitive organization and improved service to our customers.

Estimated Dates:

Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):
	07-JUL-2020
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):
	No Mixed Shipments

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1153883001	NO			1-1199091-1, 100G1121-0.40-0/9-0			
1178493001	NO			8-1190857-6, 100G0111-0.75-2			
216002-005	NO			2-1191560-6,,, -METRES, 55A0111-22-2			
216012-005	NO			"4-1191561-3", "55A0111-22-0", "55A0111-22-0", "55A0111-22-0-METRES", "55A0111-22-0"			
2214173001	NO			4-1191631-9, 100G0111-0.25-0			
3025373001	NO			6-1192291-9, 100G0111-1.20-2			
316215-003	NO			3-1192395-1,, 55A1121-22-0/9-9			
3368913001	NO			6-1192543-9, 100G0111-3.00-0			
3970213001	NO			9-1192977-2, 100G0111-0.60-0			
4259973001	NO			2-1193206-4, 100G1121-1.20-0/9-0			
6679793001	NO			5-1195260-2, 100G0111-1.20-0			
6762513001	NO			7-1195317-7, 100G0111-0.25-2			
9460053001	NO			2-1197321-0, 100G0111-0.40-2			
9922713001	NO			1-1197675-4, 100G0111-0.40-0			
A165103001	NO			7-1200587-4, RAY-101-7.5(100)			
A513413001	NO			8-1200587-0, RAY-101-6.0(100)			
C538733001	NO			3-1200852-9, RAY-101-12.5(100)			
CD41833001	NO			6-1899292-8, 100G1121-1.50-0/9-0CK0226			
CD74773001	NO			"100G1131-0.40-0/2/9-0", "9-1899440-1"			
CQ11673001	NO			"100G0111-0.40-54"			
D561523001	NO			5-1200588-9, RAY-101-4.0(100)			
D761993001	NO			9-1200972-9, RAY-101-10.0(100)			
F345203001	NO			3-1200587-4, RAY-101-3.0(100)			



Product Change Notification

Current Date: 07-Jul-2020

TE Connectivity

Product Change Notification: P-20-019260

PCN Date: 07-JUL-20

Customer: TTI, Inc. (3057778)

Location: Maisach-gernlinden

Agreement: Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:
Change of approved manufacturing location for Type 91 Customers ONLY

Description of Changes
This notice only applies to customers in the Asia Pacific region. The following product lines typically supplied from TE s Kunshan, China, manufacturing plant will be supplied from a second qualified TE manufacturing location outside of the Asia Pacific region. This will have no impact on the fit, form or function of the product. Below are the alternative manufacturing locations: Spec 55 - Tijuana, Mexico or Redwood, CA, USA Spec 44 - Tijuana, Mexico or Redwood, CA, USA 100G (Incl. CK0226 & CK0042) Swindon, UK ZHPCG (Incl. CK0226 & CK0042) Swindon, UK C-Lite Swindon, UK

Reason for Changes:
As part of an effort to continually evaluate and optimize TE's operational footprint and service level, TE AD&M (Aerospace, Defense & Marine) Business Unit has announced its plan to close its wire & cable manufacturing site in Kunshan, China. The plan will help to streamline manufacturing processes and consolidate resources to enable a more competitive organization and improved service to our customers.

Estimated Dates:	
Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):
	07-JUL-2020
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):
	No Mixed Shipments

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1153883001	NO		RAY1153883001	1-1199091-1, 100G1121-0.40-0/9-0			
1178493001	NO			8-1190857-6, 100G0111-0.75-2			
2214173001	NO		RAY2214173001, TYC2214173001	4-1191631-9, 100G0111-0.25-0			
3025373001	NO		RAY3025373001	6-1192291-9, 100G0111-1.20-2			
316215-003	NO		RAY316215-003	3-1192395-1,, 55A1121-22-0/9-9			
3368913001	NO		RAY3368913001	6-1192543-9, 100G0111-3.00-0			
3970213001	NO		RAY3970213001	9-1192977-2, 100G0111-0.60-0			
4259973001	NO		RAY4259973001	2-1193206-4, 100G1121-1.20-0/9-0			
6679793001	NO		RAY6679793001	5-1195260-2, 100G0111-1.20-0			
6762513001	NO		RAY6762513001, TYC6762513001	7-1195317-7, 100G0111-0.25-2			
9460053001	NO		RAY9460053001	2-1197321-0, 100G0111-0.40-2			
9922713001	NO		RAY9922713001	1-1197675-4, 100G0111-0.40-0			
A165103001	NO		RAYA165103001	7-1200587-4, RAY-101-7.5(100)			
A513413001	NO		RAYA513413001	8-1200587-0, RAY-101-6.0(100)			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
C538733001	NO		RAYC538733001	3-1200852-9, RAY-101-12.5(100)			
CD41833001	NO		RAYCD41833001	6-1899292-8, 100G1121-1.50-0/9-0CK0226			
CD74773001	NO		RAYCD74773001	"100G1131-0.40-0/2/9-0", "9-1899440-1"			
CQ11673001	NO			"100G0111-0.40-54"			
D561523001	NO		RAYD561523001	5-1200588-9, RAY-101-4.0(100)			
D761993001	NO		RAYD761993001	9-1200972-9, RAY-101-10.0(100)			
F345203001	NO		RAYF345203001	3-1200587-4, RAY-101-3.0(100)			