




PRODUCT CHANGE NOTIFICATION

SINGLFUSE™ SMD FUSES



Bourns® Model SF-3812SP-T and SF-3812TL-T Series SinglFuse™ SMD Fuses

New TÜV Certification Mark

Riverside, California – August 2, 2021 – Effective October 31, 2021, Bourns will change the TÜV certification mark on product labels for the Model [SF-3812SP-T](#) and [SF-3812TL-T](#) Series SinglFuse™ SMD Fuses. The new mark will include more information such as the IEC standard, rated current, rated voltage and a TÜV Certified logo.

Affected Part Numbers

SF-3812SP125T-2	SF-3812TL075T-2	SF-3812TL150T-2	SF-3812TL250T-2	SF-3812TL350T-2	SF-3812TL500T-2
SF-3812TL050T-2	SF-3812TL100T-2	SF-3812TL200T-2	SF-3812TL300T-2	SF-3812TL400T-2	

The form, fit, function, quality, and reliability of the products are not impacted by this change. Bourns will begin phasing in this process on October 31, 2021 on a roll-out basis.

Affected Series	Original Label	New Label
SF-3812SP-T	<p>PN: SF-3812SP125T-2 QTY: 2500 DC: 1804 QRA LOT: 8040180-001</p>	<p>PN: SF-3812SP125T-2 T1.25AL250V QTY: 2500 DC: 2106 QRA LOT: 1060180-001</p> <p>MADE IN:TAIWAN</p>
SF-3812TL-T	<p>PN: SF-3812TL050T-2 QTY: 2500 DC: 1804 QRA LOT: 8040180-001</p>	<p>PN: SF-3812TL050T-2 500mA 250V QTY: 2500 DC: 2106 QRA LOT: 1060180-001</p> <p>MADE IN:TAIWAN</p>

If you have any questions or need additional information, please feel free to [contact Customer Service/Inside Sales](#).

Users should verify that the described changes will not impact the performance of the product in their specific applications.

SF2122