



09-Mar-2020

PCN #:E-20-003164

Subject:Refer to ECR page for complete list of the PDs that are affected by this change.

Description of Change: To be in compliance with Stockholm Convention on Persistent Organic Pollutants legislation. New solder is classified as ROL0 and is HBCDD free.

Reason: Product Improvement. TE has actively worked with our supplier to come up with an alternate flux which does not contain the above mentioned banned substance. As a result of this change, we have done all required tests needed to make sure the new parts have same level of performance and still comply with the TE internal specifications as well as external agency specifications including the MIL approvals as and where applicable.

Key Dates:

Contact By Date:11-Mar-2020

Implementation Date:11-Mar-2020

Product Affected

664565-000

(Alias Part Numbers:

"7-1195236-6")

171104-000

(Alias Part Numbers:

"7-1198936-6"

"B-020-20-NCS2822")

601677-000

(Alias Part Numbers:

"2-1194763-7"

"B-041-26-N")

CN3060-000

Product Affected

662493-000

(Alias Part Numbers:

"1195222-3"

"ST63-2-55-22-9")

696179-000

(Alias Part Numbers:

"1-1195461-6"

"B-015-20")

089827-000

(Alias Part Numbers:

"9-1190658-6"

"B-040-26-N")

256049-000

(Alias Part Numbers:

"9-1191873-2"

"B-020-24-N")

911358-000

(Alias Part Numbers:

"1-1197078-0"

"ST63-2-55-22-5")

707406-000

(Alias Part Numbers:

"5-1195545-2"

"B-020-40-03")

440727-000

(Alias Part Numbers:

"8-1193313-3"

"B-040-20-N")

284303-000

(Alias Part Numbers:

"7-1192148-1"

"B-020-22-N")

224633-000

(Alias Part Numbers:

"8-1191654-1"

"B-041-28-2N")

443631-000

(Alias Part Numbers:

"2-1193334-9"

"B-040-30-N")

Product Affected

696948-000

(Alias Part Numbers:
"6-1195469-3")

365348-000

(Alias Part Numbers:
"1198936-1")

"B-040-22-NCS2823")

696488-000

(Alias Part Numbers:
"7-1195463-5")

"B-900-01")

695638-000

(Alias Part Numbers:
"3-1195457-0")

"B-020-44-01")

6230280004

(Alias Part Numbers:
"9-1194924-1")

"D-133-06CS384")

149657-000

(Alias Part Numbers:
"1-1191082-9")

"B-020-20-N")

905802-000

(Alias Part Numbers:
"1197038-7")

"ST63-2-55-22-90")

799337-000

(Alias Part Numbers:
"1196180-8")

"B-046-18-N")

899489-000

(Alias Part Numbers:
"9-1196991-7")

"D-133-06CS298")

696316-000

(Alias Part Numbers:
"3-1195462-0")

864114-000

(Alias Part Numbers:

"1196730-6"

"ST63-2-55-24-0")

601072-000

(Alias Part Numbers:

"7-1194756-8")

696113-000

(Alias Part Numbers:

"8-1195460-1"

"B-040-25-01")

763963-000

(Alias Part Numbers:

"9-1195947-0"

"B-041-30-N")

435441-000

(Alias Part Numbers:

"1-1193274-9")

151550-000

(Alias Part Numbers:

"4-1191095-8"

"B-020-42-05")

005299-000

(Alias Part Numbers:

"4-1190040-6"

"B-040-22-N"

"B-040-22-N")

295477-000

(Alias Part Numbers:

"6-1192238-9")

EG7637-000

(Alias Part Numbers:

"B-020-24-N-CS2973")

CV6398-000

178139-000

(Alias Part Numbers:

"4-1191295-6"

"B-041-28-N")

041911-000

(Alias Part Numbers:

"3-1190321-5")

CV6399-000

604541-000

(Alias Part Numbers:

"5-1194783-3"

"B-021-26-N")

EH8950-000

(Alias Part Numbers:

"B-040-22-N-CS4118")

696227-000

(Alias Part Numbers:

"5-1195461-6"

"B-015-22")

623033-000

(Alias Part Numbers:

"1194925-4")

623161-000

(Alias Part Numbers:

"1-1194927-4"

"D-148-0206")

304639-000

(Alias Part Numbers:

"9-1192306-9"

"B-041-24-N")

CR0923-000

269683-000

(Alias Part Numbers:

"4-1191990-2"

"ST63-2-55-20-9")

153910-000

(Alias Part Numbers:

"9-1191111-9"

"ST63-2-55-20-90")

556933-000

(Alias Part Numbers:

"1-1194393-2"

"B-020-26-N")

CV6400-000

292151-000

(Alias Part Numbers:

"9-1192214-3"

"B-040-28-N")

Product Affected

879923-000

(Alias Part Numbers:

"6-1196850-8"

"ST63-2-55-26-90")

623028-000

(Alias Part Numbers:

"8-1194924-8"

"D-133-06")

CV6397-000

623028N003

(Alias Part Numbers:

"9-1194924-2"

"D-133-06CS301")

930112-000

(Alias Part Numbers:

"2-1198934-4"

"B-020-22-NCS2822")

623163-000

(Alias Part Numbers:

"1-1194927-8")

719752-000

(Alias Part Numbers:

"8-1195628-6")

695991-000

(Alias Part Numbers:

"6-1195459-8"

"B-058-00")

709046-000

(Alias Part Numbers:

"5-1195556-7"

"B-040-22-03")

555219-000

(Alias Part Numbers:

"7-1194380-2"

"ST63-2-55-20-0")

068037-000

(Alias Part Numbers:

"6-1190512-6"

"ST63-2-55-24-9")

193729-000

Product Affected

(Alias Part Numbers:

"7-1191405-7"

"ST63-2-55-22-0")

601072N006

(Alias Part Numbers:

"5-1200935-9"

"D-607-10CS2584")

623162-000

(Alias Part Numbers:

"1-1194927-6")

024015-000

(Alias Part Numbers:

"1190186-1")

840443-000

(Alias Part Numbers:

"1-1196557-8"

"B-020-42-04")

696896-000

(Alias Part Numbers:

"1-1195469-3"

"B-016-24")

120411-000

(Alias Part Numbers:

"9-1190875-3"

"B-040-24-N")

063749-000

(Alias Part Numbers:

"2-1190482-8"

"ST63-2-55-24-90")

696254-000

(Alias Part Numbers:

"8-1195461-0")

696745-000

(Alias Part Numbers:

"8-1195466-3")

EM9867-000

(Alias Part Numbers:

"B-040-20-N-250")

187405-000

(Alias Part Numbers:
"3-1191360-4"
"D-100-00-WOTI")

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN. TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.

[Copyright](#) TE Connectivity Corporation
