



# Product Change Notification

Current Date: 17-Nov-2020

## TE Connectivity

**Product Change Notification:** P-20-020044

**PCN Date:** 17-NOV-20

**Customer:** TTI, Inc. ( 1305175 )

**Location:** Maisach-gernlinden

**Agreement:** TTI001

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

**General Product Description:**  
Power F Relay

**Description of Changes**  
Dear Customer, within our ongoing efforts to optimize our product portfolio throughout the lifecycle, we hereby inform you upfront about a tool replacement for Power F Frame to continuously meet all specification requirements. This PCN is for information purposes only, with no need to release this change.

**Reason for Changes:**  
Product improvement.Current running manufacturing tool is worn out.

**Estimated Dates:**

<b>Last Order Date</b> (Obsolete Parts Only):	<b>First Date To Ship</b> (Changed Parts Only):
	27-NOV-2020
<b>Last Ship Date</b> (Obsolete Parts Only):	<b>Last Date for Mixed Shipments:</b> (Changed Parts Only):
	No Mixed Shipments

**Part Number(s) being Modified:**

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">1-1393302-4</a>	NO			<b>VF7-11H11</b>			
<a href="#">1-1393302-7</a>	NO			"VF7-41H11"			
<a href="#">1-1393303-0</a>	NO			"V23134B 53G242"			
<a href="#">1-1393304-1</a>	NO		TYC1-1393304-1	"V23134J1053D642"			
<a href="#">1-1414099-0</a>	NO						
<a href="#">1-1414147-0</a>	NO		TYC1-1414147-0	"V23134J0052X429"			
<a href="#">1-1414167-0</a>	NO						
<a href="#">1-1414286-0</a>	NO		TYC1-1414286-0				
<a href="#">1-1414312-0</a>	NO			"V23134-M0052-X440"			
<a href="#">1-1414315-0</a>	NO		TYC1-1414315-0				
<a href="#">1-1414610-0</a>	NO		TYC1-1414610-0				
<a href="#">1393303-7</a>	NO			"V23134B 52X372"			
<a href="#">1393303-8</a>	NO		TYC1393303-8	"V23134B 52X372 * B"			
<a href="#">1393303-9</a>	NO			"V23134-B0053-C642", "V23134B 53C642"			
<a href="#">1393304-5</a>	NO		TYC1393304-5	"V23134J 56X408"			
<a href="#">1393304-9</a>	NO		TYC1393304-9	"V23134J1052D642"			
<a href="#">2-1393302-2</a>	NO		TYC2-1393302-2	"V23134A 52C643", "V23134A0052C643", "D33228-000", "AMPS-2-1393302-2"			
<a href="#">3-1393303-4</a>	NO		TYC3-1393303-4	"V23134B1052C642"			
<a href="#">3-1393303-7</a>	NO		TYC3-1393303-7	"V23134B1053C642"			
<a href="#">3-1414937-3</a>	NO		TYC3-1414937-3				

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">3-1904131-5</a>	NO						
<a href="#">4-1393302-1</a>	NO		TYC4-1393302-1	"V23134A 52X278"			
<a href="#">5-1393302-1</a>	NO		TYC5-1393302-1	"V23134A 53C643"			
<a href="#">5-1393302-2</a>	NO		TYC5-1393302-2	"V23134-A0053-G243", "V23134A 53G243"			
<a href="#">5-1393302-8</a>	NO		TYC5-1393302-8	"V23134A1052C643"			
<a href="#">5-1393304-2</a>	NO		TYC5-1393304-2	"V23134K 59X312", "V23134K0059X312"			
<a href="#">5-1393304-7</a>	NO		TYC5-1393304-7	"V23134M 52G242", "V23134M0052G242", "V23134M52G242"			
<a href="#">5-1393306-3</a>	NO			"VF7-11H11-S05"			
<a href="#">6-1393302-3</a>	NO		TYC6-1393302-3	"V23134A1053C643"			
<a href="#">6-1393303-7</a>	NO		TYC6-1393303-7	"V23134E 59X285"			
<a href="#">6-1393304-7</a>	NO			"V23134M 53C642", "V23134M0053C642"			
<a href="#">7-1393302-5</a>	NO		TYC7-1393302-5	"V23134B 52C642"			
<a href="#">7-1393303-3</a>	NO		TYC7-1393303-3	"V23134J 52D642", "V23134J0052D642"			
<a href="#">7-1393304-5</a>	NO			"V23134N 52X171", "V23134N0052X171"			
<a href="#">9-1393303-7</a>	NO		TYC9-1393303-7	"V23134J 53D642"			
<a href="#">9-1904049-3</a>	NO		TYC9-1904049-3				



# Product Change Notification

Current Date: 17-Nov-2020

## TE Connectivity

**Product Change Notification:** P-20-020044

**PCN Date:** 17-NOV-20

**Customer:** TTI, Inc. ( 3057778 )

**Location:** Maisach-gernlinden

**Agreement:** Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

**General Product Description:**  
Power F Relay

**Description of Changes**  
Dear Customer, within our ongoing efforts to optimize our product portfolio throughout the lifecycle, we hereby inform you upfront about a tool replacement for Power F Frame to continuously meet all specification requirements. This PCN is for information purposes only, with no need to release this change.

**Reason for Changes:**  
Product improvement.Current running manufacturing tool is worn out.

**Estimated Dates:**

<b>Last Order Date</b> (Obsolete Parts Only):	<b>First Date To Ship</b> (Changed Parts Only):
	27-NOV-2020
<b>Last Ship Date</b> (Obsolete Parts Only):	<b>Last Date for Mixed Shipments:</b> (Changed Parts Only):
	No Mixed Shipments

**Part Number(s) being Modified:**

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">1-1393303-0</a>	NO			"V23134B 53G242"			
<a href="#">1-1414147-0</a>	NO		TYC1-1414147-0	"V23134J0052X429"			
<a href="#">1-1414167-0</a>	NO						
<a href="#">1-1414286-0</a>	NO		TYC1-1414286-0				
<a href="#">1-1414315-0</a>	NO		TYC1-1414315-0				
<a href="#">1-1414610-0</a>	NO		TYC1-1414610-0				
<a href="#">1393303-9</a>	NO			"V23134-B0053-C642", "V23134B 53C642"			
<a href="#">1393304-5</a>	NO		TYC1393304-5	"V23134J 56X408"			
<a href="#">1393304-9</a>	NO		TYC1393304-9	"V23134J1052D642"			
<a href="#">3-1393303-4</a>	NO		TYC3-1393303-4	"V23134B1052C642"			
<a href="#">3-1393303-7</a>	NO		TYC3-1393303-7	"V23134B1053C642"			
<a href="#">3-1414937-3</a>	NO		TYC3-1414937-3				
<a href="#">3-1904131-5</a>	NO						
<a href="#">4-1393302-1</a>	NO		TYC4-1393302-1	"V23134A 52X278"			
<a href="#">5-1393302-1</a>	NO		TYC5-1393302-1	"V23134A 53C643"			
<a href="#">5-1393302-2</a>	NO		TYC5-1393302-2	"V23134-A0053-G243", "V23134A 53G243"			
<a href="#">5-1393302-8</a>	NO		TYC5-1393302-8	"V23134A1052C643"			
<a href="#">6-1393302-3</a>	NO		TYC6-1393302-3	"V23134A1053C643"			
<a href="#">6-1393303-7</a>	NO		TYC6-1393303-7	"V23134E 59X285"			
<a href="#">6-1393304-7</a>	NO			"V23134M 53C642", "V23134M0053C642"			
<a href="#">7-1393302-5</a>	NO		TYC7-1393302-5	"V23134B 52C642"			
<a href="#">9-1393303-7</a>	NO		TYC9-1393303-7	"V23134J 53D642"			
<a href="#">9-1904049-3</a>	NO		TYC9-1904049-3				