



The DNA of tech.™

Product Information Notification

Product Group: DBR/Tue Nov 26, 2024/PIN-DBR-00036-2024-REV-0



Notification of fire accident at our Sub Con factory in South Korea: Product Delivery Interruption of SFR16S and NFR25, NFR25H

For further information, please contact your regional Vishay office.

CONTACT INFORMATION

Americas

Vishay Americas Inc
1122 23rd Street
-
Columbus NE United States 68601
Phone: +1-402-563-6400
Fax: +1-402-563-6565
business-americas@vishay.com

Europe

Vishay Electronic GmbH
Dr Felix Zandman Platz 1
-
Selb Germany D-95100
Phone: +49 481 95-338
Fax: +49 481 95-204
business-europe@vishay.com

Asia

Vishay Intertechnology Asia Pte Ltd
37A Tampines Street 92
-
Singapore Singapore 528886
Phone: +65-6788-6668
Fax: +65-6788-0988
business-asia@vishay.com

Description of Change: This Advisory is being issued to announce an unfortunate fire accident on 19 November 2024 at our sub con factory in South Korea, which has damaged their production lines considerably. Due to this unforeseen situation, will not be able to accept new orders of SFR16S, NFR25, NFR25H until further notifications. Please refer attached letter for more information.

For SFR16S customers can choose equivalent MBA/SMA 0204 series metal film resistors as drop-in replacement as shown in Appendix page. NFR25, NFR25H status will be updated by mid-December 2024.

Reason for Change: Unavailability of production equipments due to fire in the factory.

Expected Influence on Quality/Reliability/Performance: N/A

Part Numbers/Series/Families Affected: SFR16S*, NFR25*,

Vishay Brand(S): Vishay BCcomponents

Time Schedule:

Start Shipment Date: Tue Nov 26, 2024

Sample Availability: Samples of MBA/SMA 0204 series are readily available as shown in Start Shipment Date.

Product Identification: MBA/SMA 0204 series products will be light blue in color.

Qualification Data: Qualification reports of MBA/SMA 0204 series are readily available.

Issued By: Pavan Kulkarni, pavan.kulkarni@vishay.com



Advisory – Product Delivery Interruption

Product Group: Draloric /Beyschlag Resistors

November 22, 2024

Subject: Notification of fire accident at our Sub Con factory in South Korea:
Product Delivery Interruption

Dear Valued Customers, Channel Partners,

This Advisory is being issued to announce an unfortunate fire accident on 19th November 2024 at our sub con factory in South Korea, which has damaged their production lines considerably.

The extent of damage is yet to be fully ascertained, but it will disrupt production and delivery of following product line:

1. SFR16S: [sfr16s25.pdf](#)
2. NFR25/H: [nfr25.pdf](#)

We are working on the mitigation plans with utmost urgency and will come back to you with further information latest by mid-December 2024.

Due to this unforeseen situation, which is beyond our control, we regret to inform that we will not be able to accept new orders of SFR16S, NFR25/H until further notifications. The backlog status of these products will be informed by planning, customer service in the coming days, as we receive updates from our sub con.

We sincerely apologize for the inconvenience caused to you on account of this unfortunate incident.

Thanking you for your patience and understanding and looking forward to your kind cooperation for handling this situation.

Yours sincerely,

A handwritten signature in black ink, appearing to be "Nirbhay Gopal", written over a horizontal line.

(Nirbhay Gopal)
Director-Product Marketing
Draloric / Beyschlag Resistors



The DNA of tech™

Product Information Notification



Appendix to PIN-DBR-00036-2024-REV-0

SFR16S Series Affected Part Numbers

SFR16S part number	Replacement part number with preferred packaging	SFR16S part number	Replacement part number with preferred packaging
SFR16S0001000FA500	MBA02040C1000FCT00	SFR16S0001071FR500	MBA02040C1071FRP00
SFR16S0001000FR500	MBA02040C1000FRP00	SFR16S0001074FR500	MBA02040C1074FRP00
SFR16S0001000JA100	MBA02040C1000FCT00	SFR16S0001100FR500	MBA02040C1100FRP00
SFR16S0001000JA500	MBA02040C1000FCT00	SFR16S0001101FA500	MBA02040C1101FCT00
SFR16S0001000JR500	MBA02040C1000FRP00	SFR16S0001101FR500	MBA02040C1101FRP00
SFR16S0001001FA500	MBA02040C1001FCT00	SFR16S0001102FR500	MBA02040C1102FRP00
SFR16S0001001FR500	MBA02040C1001FRP00	SFR16S0001103FR500	MBA02040C1103FRP00
SFR16S0001001JA100	MBA02040C1001FCT00	SFR16S0001109FR500	MBA02040C1109FRP00
SFR16S0001001JA500	MBA02040C1001FCT00	SFR16S0001109JA100	MBA02040C1109FCT00
SFR16S0001001JR500	MBA02040C1001FRP00	SFR16S0001109JA500	MBA02040C1109FCT00
SFR16S0001002FA500	MBA02040C1002FCT00	SFR16S0001153FR500	MBA02040C1153FRP00
SFR16S0001002FR500	MBA02040C1002FRP00	SFR16S0001182FR500	MBA02040C1182FRP00
SFR16S0001002JA100	MBA02040C1002FCT00	SFR16S0001200FA500	MBA02040C1200FCT00
SFR16S0001002JA500	MBA02040C1002FCT00	SFR16S0001200JA100	MBA02040C1200FCT00
SFR16S0001002JR500	MBA02040C1002FRP00	SFR16S0001200JA500	MBA02040C1200FCT00
SFR16S0001003FA500	MBA02040C1003FCT00	SFR16S0001200JR500	MBA02040C1200FRP00
SFR16S0001003FR500	MBA02040C1003FRP00	SFR16S0001201FA500	MBA02040C1201FCT00
SFR16S0001003JA100	MBA02040C1003FCT00	SFR16S0001201JA100	MBA02040C1201FCT00
SFR16S0001003JA500	MBA02040C1003FCT00	SFR16S0001201JA500	MBA02040C1201FCT00
SFR16S0001003JR500	MBA02040C1003FRP00	SFR16S0001201JR500	MBA02040C1201FRP00
SFR16S0001004FA500	MBA02040C1004FCT00	SFR16S0001202FA500	MBA02040C1202FCT00
SFR16S0001004FR500	MBA02040C1004FRP00	SFR16S0001202JA100	MBA02040C1202FCT00
SFR16S0001004JA100	MBA02040C1004FCT00	SFR16S0001202JA500	MBA02040C1202FCT00
SFR16S0001004JA500	MBA02040C1004FCT00	SFR16S0001203JA100	MBA02040C1203FCT00
SFR16S0001004JR500	MBA02040C1004FRP00	SFR16S0001203JA500	MBA02040C1203FCT00
SFR16S0001008JA100	MBA02040C1008FCT00	SFR16S0001203JR500	MBA02040C1203FRP00
SFR16S0001008JA500	MBA02040C1008FCT00	SFR16S0001204FA500	MBA02040C1204FCT00
SFR16S0001008JR500	MBA02040C1008FRP00	SFR16S0001208JA500	MBA02040C1208FCT00
SFR16S0001009FR500	MBA02040C1009FRP00	SFR16S0001208JR500	MBA02040C1208FRP00
SFR16S0001009JA100	MBA02040C1009FCT00	SFR16S0001209JA100	MBA02040C1209FCT00
SFR16S0001009JA500	MBA02040C1009FCT00	SFR16S0001209JA500	MBA02040C1209FCT00
SFR16S0001009JR500	MBA02040C1009FRP00	SFR16S0001209JR500	MBA02040C1209FRP00
SFR16S0001021FR500	MBA02040C1021FRP00	SFR16S0001210FR500	MBA02040C1210FRP00
SFR16S0001022FR500	MBA02040C1022FRP00	SFR16S0001211FR500	MBA02040C1211FRP00
SFR16S0001024FR500	MBA02040C1024FRP00	SFR16S0001212FR500	MBA02040C1212FRP00
SFR16S0001051FR500	MBA02040C1051FRP00	SFR16S0001213FR500	MBA02040C1213FRP00
SFR16S0001052FA500	MBA02040C1052FCT00	SFR16S0001214FR500	MBA02040C1214FRP00
SFR16S0001052FR500	MBA02040C1052FRP00	SFR16S0001240FR500	MBA02040C1240FRP00
SFR16S0001053FR500	MBA02040C1053FRP00	SFR16S0001241FR500	MBA02040C1241FRP00



The DNA of tech™

Product Information Notification



Appendix to PIN-DBR-00036-2024-REV-0

SFR16S Series Affected Part Numbers

SFR16S part number	Replacement part number with preferred packaging	SFR16S part number	Replacement part number with preferred packaging
SFR16S0001242FR500	MBA02040C1242FRP00	SFR16S0001583FR500	MBA02040C1583FRP00
SFR16S0001243FR500	MBA02040C1243FRP00	SFR16S0001601JA100	MBA02040C1601FCT00
SFR16S0001272FA500	MBA02040C1272FCT00	SFR16S0001620FR500	MBA02040C1620FRP00
SFR16S0001300FR500	MBA02040C1300FRP00	SFR16S0001621FR500	MBA02040C1621FRP00
SFR16S0001300JA500	MBA02040C1300FCT00	SFR16S0001622FR500	MBA02040C1622FRP00
SFR16S0001301FR500	MBA02040C1301FRP00	SFR16S0001651FR500	MBA02040C1651FRP00
SFR16S0001301JA500	MBA02040C1301FCT00	SFR16S0001653FR500	MBA02040C1653FRP00
SFR16S0001302FR500	MBA02040C1302FRP00	SFR16S0001691FR500	MBA02040C1691FRP00
SFR16S0001303FA500	MBA02040C1303FCT00	SFR16S0001692FR500	MBA02040C1692FRP00
SFR16S0001303JA500	MBA02040C1303FCT00	SFR16S0001693FR500	MBA02040C1693FRP00
SFR16S0001332FR500	MBA02040C1332FRP00	SFR16S0001782FR500	MBA02040C1782FRP00
SFR16S0001402FR500	MBA02040C1402FRP00	SFR16S0001800JA500	MBA02040C1800FCT00
SFR16S0001470FR500	MBA02040C1470FRP00	SFR16S0001801FA500	MBA02040C1801FCT00
SFR16S0001472FR500	MBA02040C1472FRP00	SFR16S0001801JA100	MBA02040C1801FCT00
SFR16S0001500FR500	MBA02040C1500FRP00	SFR16S0001801JA500	MBA02040C1801FCT00
SFR16S0001500JA500	MBA02040C1500FCT00	SFR16S0001802FA500	MBA02040C1802FCT00
SFR16S0001500JR500	MBA02040C1500FRP00	SFR16S0001802FR500	MBA02040C1802FRP00
SFR16S0001501FA500	MBA02040C1501FCT00	SFR16S0001802JA500	MBA02040C1802FCT00
SFR16S0001501FR500	MBA02040C1501FRP00	SFR16S0001802JR500	MBA02040C1802FRP00
SFR16S0001501JA100	MBA02040C1501FCT00	SFR16S0001803FA500	MBA02040C1803FCT00
SFR16S0001501JA500	MBA02040C1501FCT00	SFR16S0001803JA500	MBA02040C1803FCT00
SFR16S0001501JR500	MBA02040C1501FRP00	SFR16S0001804FA500	MBA02040C1804FCT00
SFR16S0001502FA500	MBA02040C1502FCT00	SFR16S0001804JA500	MBA02040C1804FCT00
SFR16S0001502FR500	MBA02040C1502FRP00	SFR16S0001808JA100	MBA02040C1808FCT00
SFR16S0001502JA100	MBA02040C1502FCT00	SFR16S0001808JA500	MBA02040C1808FCT00
SFR16S0001502JA500	MBA02040C1502FCT00	SFR16S0001809JA500	MBA02040C1809FCT00
SFR16S0001502JR500	MBA02040C1502FRP00	SFR16S0001821FR500	MBA02040C1821FRP00
SFR16S0001503FA500	MBA02040C1503FCT00	SFR16S0001822FR500	MBA02040C1822FRP00
SFR16S0001503FR500	MBA02040C1503FRP00	SFR16S0001823FR500	MBA02040C1823FRP00
SFR16S0001503JA100	MBA02040C1503FCT00	SFR16S0001872FR500	MBA02040C1872FRP00
SFR16S0001503JA500	MBA02040C1503FCT00	SFR16S0001910FR500	MBA02040C1910FRP00
SFR16S0001504JR500	MBA02040C1504FRP00	SFR16S0001911FA500	MBA02040C1911FCT00
SFR16S0001508JA100	MBA02040C1508FCT00	SFR16S0001961FR500	MBA02040C1961FRP00
SFR16S0001509JA100	MBA02040C1509FCT00	SFR16S0002000FA500	MBA02040C2000FCT00
SFR16S0001509JA500	MBA02040C1509FCT00	SFR16S0002000FR500	MBA02040C2000FRP00
SFR16S0001509JR500	MBA02040C1509FRP00	SFR16S0002000JA500	MBA02040C2000FCT00
SFR16S0001543FR500	MBA02040C1543FRP00	SFR16S0002000JR500	MBA02040C2000FRP00
SFR16S0001580FR500	MBA02040C1580FRP00	SFR16S0002001FA500	MBA02040C2001FCT00
SFR16S0001581FR500	MBA02040C1581FRP00	SFR16S0002001FR500	MBA02040C2001FRP00



The DNA of tech™

Product Information Notification



Appendix to PIN-DBR-00036-2024-REV-0

SFR16S Series Affected Part Numbers

SFR16S part number	Replacement part number with preferred packaging	SFR16S part number	Replacement part number with preferred packaging
SFR16S0002001JA100	MBA02040C2001FCT00	SFR16S0002209JA500	MBA02040C2209FCT00
SFR16S0002001JA500	MBA02040C2001FCT00	SFR16S0002210FR500	MBA02040C2210FRP00
SFR16S0002001JR500	MBA02040C2001FRP00	SFR16S0002211FR500	MBA02040C2211FRP00
SFR16S0002002FA500	MBA02040C2002FCT00	SFR16S0002212FR500	MBA02040C2212FRP00
SFR16S0002002FR500	MBA02040C2002FRP00	SFR16S0002213FR500	MBA02040C2213FRP00
SFR16S0002002JA500	MBA02040C2002FCT00	SFR16S0002219FR500	MBA02040C2219FRP00
SFR16S0002002JR500	MBA02040C2002FRP00	SFR16S0002260FR500	MBA02040C2260FRP00
SFR16S0002003FR500	MBA02040C2003FRP00	SFR16S0002261FR500	MBA02040C2261FRP00
SFR16S0002003JA500	MBA02040C2003FCT00	SFR16S0002269FR500	MBA02040C2269FRP00
SFR16S0002003JR500	MBA02040C2003FRP00	SFR16S0002321FR500	MBA02040C2321FRP00
SFR16S0002004FA500	MBA02040C2004FCT00	SFR16S0002370FR500	MBA02040C2370FRP00
SFR16S0002004FR500	MBA02040C2004FRP00	SFR16S0002371FR500	MBA02040C2371FRP00
SFR16S0002008JA500	MBA02040C2008FCT00	SFR16S0002400JA500	MBA02040C2400FCT00
SFR16S0002009FR500	MBA02040C2009FRP00	SFR16S0002401JR500	MBA02040C2401FRP00
SFR16S0002052FR500	MBA02040C2052FRP00	SFR16S0002402JA100	MBA02040C2402FCT00
SFR16S0002159FR500	MBA02040C2159FRP00	SFR16S0002402JA500	MBA02040C2402FCT00
SFR16S0002200FA500	MBA02040C2200FCT00	SFR16S0002402JR500	MBA02040C2402FRP00
SFR16S0002200JA100	MBA02040C2200FCT00	SFR16S0002431FR500	MBA02040C2431FRP00
SFR16S0002200JA500	MBA02040C2200FCT00	SFR16S0002432FR500	MBA02040C2432FRP00
SFR16S0002200JR500	MBA02040C2200FRP00	SFR16S0002471FR500	MBA02040C2471FRP00
SFR16S0002201FA500	MBA02040C2201FCT00	SFR16S0002490FR500	MBA02040C2490FRP00
SFR16S0002201FR500	MBA02040C2201FRP00	SFR16S0002491FR500	MBA02040C2491FRP00
SFR16S0002201JA100	MBA02040C2201FCT00	SFR16S0002492FR500	MBA02040C2492FRP00
SFR16S0002201JA500	MBA02040C2201FCT00	SFR16S0002551FR500	MBA02040C2551FRP00
SFR16S0002201JR500	MBA02040C2201FRP00	SFR16S0002552FR500	MBA02040C2552FRP00
SFR16S0002202FA500	MBA02040C2202FCT00	SFR16S0002611FR500	MBA02040C2611FRP00
SFR16S0002202JA100	MBA02040C2202FCT00	SFR16S0002612FR500	MBA02040C2612FRP00
SFR16S0002202JA500	MBA02040C2202FCT00	SFR16S0002619FR500	MBA02040C2619FRP00
SFR16S0002202JR500	MBA02040C2202FRP00	SFR16S0002670FR500	MBA02040C2670FRP00
SFR16S0002203FA500	MBA02040C2203FCT00	SFR16S0002672FR500	MBA02040C2672FRP00
SFR16S0002203FR500	MBA02040C2203FRP00	SFR16S0002700FA500	MBA02040C2700FCT00
SFR16S0002203JA100	MBA02040C2203FCT00	SFR16S0002700JA500	MBA02040C2700FCT00
SFR16S0002203JA500	MBA02040C2203FCT00	SFR16S0002700JR500	MBA02040C2700FRP00
SFR16S0002203JR500	MBA02040C2203FRP00	SFR16S0002701FA500	MBA02040C2701FCT00
SFR16S0002208JA100	MBA02040C2208FCT00	SFR16S0002701JA100	MBA02040C2701FCT00
SFR16S0002208JA500	MBA02040C2208FCT00	SFR16S0002701JA500	MBA02040C2701FCT00
SFR16S0002208JR500	MBA02040C2208FRP00	SFR16S0002701JR500	MBA02040C2701FRP00
SFR16S0002209FA500	MBA02040C2209FCT00	SFR16S0002702FA500	MBA02040C2702FCT00
SFR16S0002209JA100	MBA02040C2209FCT00	SFR16S0002702FR500	MBA02040C2702FRP00



The DNA of tech™

Product Information Notification



Appendix to PIN-DBR-00036-2024-REV-0

SFR16S Series Affected Part Numbers

SFR16S part number	Replacement part number with preferred packaging	SFR16S part number	Replacement part number with preferred packaging
SFR16S0002702JA500	MBA02040C2702FCT00	SFR16S0003300JR500	MBA02040C3300FRP00
SFR16S0002702JR500	MBA02040C2702FRP00	SFR16S0003301FA500	MBA02040C3301FCT00
SFR16S0002703FA500	MBA02040C2703FCT00	SFR16S0003301FR500	MBA02040C3301FRP00
SFR16S0002703JA500	MBA02040C2703FCT00	SFR16S0003301JA100	MBA02040C3301FCT00
SFR16S0002708JA500	MBA02040C2708FCT00	SFR16S0003301JA500	MBA02040C3301FCT00
SFR16S0002708JR500	MBA02040C2708FRP00	SFR16S0003301JR500	MBA02040C3301FRP00
SFR16S0002709FA500	MBA02040C2709FCT00	SFR16S0003302FA500	MBA02040C3302FCT00
SFR16S0002709FR500	MBA02040C2709FRP00	SFR16S0003302FR500	MBA02040C3302FRP00
SFR16S0002709JA100	MBA02040C2709FCT00	SFR16S0003302JA100	MBA02040C3302FCT00
SFR16S0002709JA500	MBA02040C2709FCT00	SFR16S0003302JA500	MBA02040C3302FCT00
SFR16S0002740FR500	MBA02040C2740FRP00	SFR16S0003303FA500	MBA02040C3303FCT00
SFR16S0002741FR500	MBA02040C2741FRP00	SFR16S0003303JA100	MBA02040C3303FCT00
SFR16S0002749FR500	MBA02040C2749FRP00	SFR16S0003303JA500	MBA02040C3303FCT00
SFR16S0002800FR500	MBA02040C2800FRP00	SFR16S0003303JR500	MBA02040C3303FRP00
SFR16S0002801FR500	MBA02040C2801FRP00	SFR16S0003308JA500	MBA02040C3308FCT00
SFR16S0002802FR500	MBA02040C2802FRP00	SFR16S0003309JA100	MBA02040C3309FCT00
SFR16S0002809FR500	MBA02040C2809FRP00	SFR16S0003309JA500	MBA02040C3309FCT00
SFR16S0003000JA500	MBA02040C3000FCT00	SFR16S0003309JR500	MBA02040C3309FRP00
SFR16S0003001JA100	MBA02040C3001FCT00	SFR16S0003320FR500	MBA02040C3320FRP00
SFR16S0003002FA500	MBA02040C3002FCT00	SFR16S0003321FR500	MBA02040C3321FRP00
SFR16S0003002JA100	MBA02040C3002FCT00	SFR16S0003322FR500	MBA02040C3322FRP00
SFR16S0003003FA500	MBA02040C3003FCT00	SFR16S0003323FR500	MBA02040C3323FRP00
SFR16S0003004JA500	MBA02040C3004FCT00	SFR16S0003329FR500	MBA02040C3329FRP00
SFR16S0003009JA100	MBA02040C3009FCT00	SFR16S0003400FR500	MBA02040C3400FRP00
SFR16S0003010FR500	MBA02040C3010FRP00	SFR16S0003481FR500	MBA02040C3481FRP00
SFR16S0003011FR500	MBA02040C3011FRP00	SFR16S0003483FR500	MBA02040C3483FRP00
SFR16S0003012FR500	MBA02040C3012FRP00	SFR16S0003572FR500	MBA02040C3572FRP00
SFR16S0003013FR500	MBA02040C3013FRP00	SFR16S0003579FR500	MBA02040C3579FRP00
SFR16S0003019FR500	MBA02040C3019FRP00	SFR16S0003600JR500	MBA02040C3600FRP00
SFR16S0003090FR500	MBA02040C3090FRP00	SFR16S0003602FR500	MBA02040C3602FRP00
SFR16S0003091FR500	MBA02040C3091FRP00	SFR16S0003650FR500	MBA02040C3650FRP00
SFR16S0003162FR500	MBA02040C3162FRP00	SFR16S0003651FR500	MBA02040C3651FRP00
SFR16S0003240FR500	MBA02040C3240FRP00	SFR16S0003652FR500	MBA02040C3652FRP00
SFR16S0003241FA500	MBA02040C3241FCT00	SFR16S0003740FR500	MBA02040C3740FRP00
SFR16S0003241FR500	MBA02040C3241FRP00	SFR16S0003749FR500	MBA02040C3749FRP00
SFR16S0003242FR500	MBA02040C3242FRP00	SFR16S0003830FR500	MBA02040C3830FRP00
SFR16S0003300FA500	MBA02040C3300FCT00	SFR16S0003831FR500	MBA02040C3831FRP00
SFR16S0003300JA100	MBA02040C3300FCT00	SFR16S0003900FA500	MBA02040C3900FCT00
SFR16S0003300JA500	MBA02040C3300FCT00	SFR16S0003900FR500	MBA02040C3900FRP00



The DNA of tech™

Product Information Notification



Appendix to PIN-DBR-00036-2024-REV-0

SFR16S Series Affected Part Numbers

SFR16S part number	Replacement part number with preferred packaging	SFR16S part number	Replacement part number with preferred packaging
SFR16S0003900JA500	MBA02040C3900FCT00	SFR16S0004701FR500	MBA02040C4701FRP00
SFR16S0003901FA500	MBA02040C3901FCT00	SFR16S0004701JA100	MBA02040C4701FCT00
SFR16S0003901JA500	MBA02040C3901FCT00	SFR16S0004701JA500	MBA02040C4701FCT00
SFR16S0003901JR500	MBA02040C3901FRP00	SFR16S0004701JR500	MBA02040C4701FRP00
SFR16S0003902FA500	MBA02040C3902FCT00	SFR16S0004702FA500	MBA02040C4702FCT00
SFR16S0003902JA500	MBA02040C3902FCT00	SFR16S0004702FR500	MBA02040C4702FRP00
SFR16S0003903FA500	MBA02040C3903FCT00	SFR16S0004702JA100	MBA02040C4702FCT00
SFR16S0003903FR500	MBA02040C3903FRP00	SFR16S0004702JA500	MBA02040C4702FCT00
SFR16S0003903JA500	MBA02040C3903FCT00	SFR16S0004702JR500	MBA02040C4702FRP00
SFR16S0003908JA500	MBA02040C3908FCT00	SFR16S0004703FA500	MBA02040C4703FCT00
SFR16S0003909JA100	MBA02040C3909FCT00	SFR16S0004703JA500	MBA02040C4703FCT00
SFR16S0003909JA500	MBA02040C3909FCT00	SFR16S0004703JR500	MBA02040C4703FRP00
SFR16S0003909JR500	MBA02040C3909FRP00	SFR16S0004708JA100	MBA02040C4708FCT00
SFR16S0003920FR500	MBA02040C3920FRP00	SFR16S0004708JA500	MBA02040C4708FCT00
SFR16S0003921FR500	MBA02040C3921FRP00	SFR16S0004708JR500	MBA02040C4708FRP00
SFR16S0003922FR500	MBA02040C3922FRP00	SFR16S0004709JA100	MBA02040C4709FCT00
SFR16S0003929FR500	MBA02040C3929FRP00	SFR16S0004709JA500	MBA02040C4709FCT00
SFR16S0004020FR500	MBA02040C4020FRP00	SFR16S0004709JR500	MBA02040C4709FRP00
SFR16S0004021FR500	MBA02040C4021FRP00	SFR16S0004750FR500	MBA02040C4750FRP00
SFR16S0004022FR500	MBA02040C4022FRP00	SFR16S0004751FR500	MBA02040C4751FRP00
SFR16S0004023FR500	MBA02040C4023FRP00	SFR16S0004752FR500	MBA02040C4752FRP00
SFR16S0004122FR500	MBA02040C4122FRP00	SFR16S0004753FR500	MBA02040C4753FRP00
SFR16S0004123FR500	MBA02040C4123FRP00	SFR16S0004759FR500	MBA02040C4759FRP00
SFR16S0004221FR500	MBA02040C4221FRP00	SFR16S0004870FR500	MBA02040C4870FRP00
SFR16S0004302JA500	MBA02040C4302FCT00	SFR16S0004872FR500	MBA02040C4872FRP00
SFR16S0004303JA500	MBA02040C4303FCT00	SFR16S0004990FR500	MBA02040C4990FRP00
SFR16S0004309JA100	MBA02040C4309FCT00	SFR16S0004991FR500	MBA02040C4991FRP00
SFR16S0004320FR500	MBA02040C4320FRP00	SFR16S0004992FR500	MBA02040C4992FRP00
SFR16S0004321FR500	MBA02040C4321FRP00	SFR16S0004993FR500	MBA02040C4993FRP00
SFR16S0004322FR500	MBA02040C4322FRP00	SFR16S0004998FR500	MBA02040C4998FRP00
SFR16S0004421FR500	MBA02040C4421FRP00	SFR16S0004999FR500	MBA02040C4999FRP00
SFR16S0004530FA500	MBA02040C4530FCT00	SFR16S0005100JA100	MBA02040C5100FCT00
SFR16S0004531FR500	MBA02040C4531FRP00	SFR16S0005100JR500	MBA02040C5100FRP00
SFR16S0004700FA500	MBA02040C4700FCT00	SFR16S0005101FA500	MBA02040C5101FCT00
SFR16S0004700FR500	MBA02040C4700FRP00	SFR16S0005101JA100	MBA02040C5101FCT00
SFR16S0004700JA100	MBA02040C4700FCT00	SFR16S0005101JA500	MBA02040C5101FCT00
SFR16S0004700JA500	MBA02040C4700FCT00	SFR16S0005102JA100	MBA02040C5102FCT00
SFR16S0004700JR500	MBA02040C4700FRP00	SFR16S0005102JA500	MBA02040C5102FCT00
SFR16S0004701FA500	MBA02040C4701FCT00	SFR16S0005108FA500	MBA02040C5108FCT00



The DNA of tech™

Product Information Notification



Appendix to PIN-DBR-00036-2024-REV-0

SFR16S Series Affected Part Numbers

SFR16S part number	Replacement part number with preferred packaging	SFR16S part number	Replacement part number with preferred packaging
SFR16S0005109FA500	MBA02040C5109FCT00	SFR16S0005901FR500	MBA02040C5901FRP00
SFR16S0005109JA500	MBA02040C5109FCT00	SFR16S0006040FR500	MBA02040C6040FRP00
SFR16S0005110FR500	MBA02040C5110FRP00	SFR16S0006042FR500	MBA02040C6042FRP00
SFR16S0005111FR500	MBA02040C5111FRP00	SFR16S0006049FR500	MBA02040C6049FRP00
SFR16S0005112FR500	MBA02040C5112FRP00	SFR16S0006191FR500	MBA02040C6191FRP00
SFR16S0005119FR500	MBA02040C5119FRP00	SFR16S0006192FR500	MBA02040C6192FRP00
SFR16S0005231FR500	MBA02040C5231FRP00	SFR16S0006199FA500	MBA02040C6199FCT00
SFR16S0005361FR500	MBA02040C5361FRP00	SFR16S0006201JA500	MBA02040C6201FCT00
SFR16S0005362FA500	MBA02040C5362FCT00	SFR16S0006201JR500	MBA02040C6201FRP00
SFR16S0005369FA500	MBA02040C5369FCT00	SFR16S0006203FA500	MBA02040C6203FCT00
SFR16S0005369FR500	MBA02040C5369FRP00	SFR16S0006203JA500	MBA02040C6203FCT00
SFR16S0005490FR500	MBA02040C5490FRP00	SFR16S0006343FR500	MBA02040C6343FRP00
SFR16S0005491FR500	MBA02040C5491FRP00	SFR16S0006349FR500	MBA02040C6349FRP00
SFR16S0005492FR500	MBA02040C5492FRP00	SFR16S0006491FR500	MBA02040C6491FRP00
SFR16S0005499FR500	MBA02040C5499FRP00	SFR16S0006499FR500	MBA02040C6499FRP00
SFR16S0005600FA500	MBA02040C5600FCT00	SFR16S0006650FR500	MBA02040C6650FRP00
SFR16S0005600FR500	MBA02040C5600FRP00	SFR16S0006800FA500	MBA02040C6800FCT00
SFR16S0005600JA100	MBA02040C5600FCT00	SFR16S0006800JA100	MBA02040C6800FCT00
SFR16S0005600JA500	MBA02040C5600FCT00	SFR16S0006800JA500	MBA02040C6800FCT00
SFR16S0005600JR500	MBA02040C5600FRP00	SFR16S0006800JR500	MBA02040C6800FRP00
SFR16S0005601JA100	MBA02040C5601FCT00	SFR16S0006801FA500	MBA02040C6801FCT00
SFR16S0005601JA500	MBA02040C5601FCT00	SFR16S0006801JA100	MBA02040C6801FCT00
SFR16S0005602FA500	MBA02040C5602FCT00	SFR16S0006801JA500	MBA02040C6801FCT00
SFR16S0005602JA100	MBA02040C5602FCT00	SFR16S0006801JR500	MBA02040C6801FRP00
SFR16S0005602JA500	MBA02040C5602FCT00	SFR16S0006802FA500	MBA02040C6802FCT00
SFR16S0005603JA500	MBA02040C5603FCT00	SFR16S0006802JA100	MBA02040C6802FCT00
SFR16S0005603JR500	MBA02040C5603FRP00	SFR16S0006802JA500	MBA02040C6802FCT00
SFR16S0005608FA500	MBA02040C5608FCT00	SFR16S0006802JR500	MBA02040C6802FRP00
SFR16S0005608JA500	MBA02040C5608FCT00	SFR16S0006803JA500	MBA02040C6803FCT00
SFR16S0005609JA100	MBA02040C5609FCT00	SFR16S0006808JA500	MBA02040C6808FCT00
SFR16S0005609JA500	MBA02040C5609FCT00	SFR16S0006808JR500	MBA02040C6808FRP00
SFR16S0005609JR500	MBA02040C5609FRP00	SFR16S0006809FA500	MBA02040C6809FCT00
SFR16S0005620FR500	MBA02040C5620FRP00	SFR16S0006809JA500	MBA02040C6809FCT00
SFR16S0005621FA500	MBA02040C5621FCT00	SFR16S0006809JR500	MBA02040C6809FRP00
SFR16S0005621FR500	MBA02040C5621FRP00	SFR16S0006810FR500	MBA02040C6810FRP00
SFR16S0005622FR500	MBA02040C5622FRP00	SFR16S0006811FR500	MBA02040C6811FRP00
SFR16S0005623FR500	MBA02040C5623FRP00	SFR16S0006812FR500	MBA02040C6812FRP00
SFR16S0005769FR500	MBA02040C5769FRP00	SFR16S0006813FR500	MBA02040C6813FRP00
SFR16S0005900FR500	MBA02040C5900FRP00	SFR16S0006819FR500	MBA02040C6819FRP00



The DNA of tech™

Product Information Notification



Appendix to PIN-DBR-00036-2024-REV-0

SFR16S Series Affected Part Numbers

SFR16S part number	Replacement part number with preferred packaging	SFR16S part number	Replacement part number with preferred packaging
SFR16S0006980FR500	MBA02040C6980FRP00	SFR16S0008252FA500	MBA02040C8252FCT00
SFR16S0006981FR500	MBA02040C6981FRP00	SFR16S0008252FR500	MBA02040C8252FRP00
SFR16S0006982FR500	MBA02040C6982FRP00	SFR16S0008259FR500	MBA02040C8259FRP00
SFR16S0007150FR500	MBA02040C7150FRP00	SFR16S0008660FR500	MBA02040C8660FRP00
SFR16S0007151FA500	MBA02040C7151FCT00	SFR16S0009090FR500	MBA02040C9090FRP00
SFR16S0007322FR500	MBA02040C7322FRP00	SFR16S0009091FR500	MBA02040C9091FRP00
SFR16S0007500FR500	MBA02040C7500FRP00	SFR16S0009092FR500	MBA02040C9092FRP00
SFR16S0007501FR500	MBA02040C7501FRP00	SFR16S0009099FR500	MBA02040C9099FRP00
SFR16S0007501JA500	MBA02040C7501FCT00	SFR16S0009100JA500	MBA02040C9100FCT00
SFR16S0007502FA500	MBA02040C7502FCT00	SFR16S0009100JR500	MBA02040C9100FRP00
SFR16S0007502FR500	MBA02040C7502FRP00	SFR16S0009101JR500	MBA02040C9101FRP00
SFR16S0007503FA500	MBA02040C7503FCT00	SFR16S0009103JA500	MBA02040C9103FCT00
SFR16S0007508JA500	MBA02040C7508FCT00	SFR16S0009108FR500	MBA02040C9108FRP00
SFR16S0007509FR500	MBA02040C7509FRP00	SFR16S0009108JR500	MBA02040C9108FRP00
SFR16S0007509JA100	MBA02040C7509FCT00	SFR16S0009109JA100	MBA02040C9109FCT00
SFR16S0007509JA500	MBA02040C7509FCT00	SFR16S0009311FR500	MBA02040C9311FRP00
SFR16S0007689FR500	MBA02040C7689FRP00	SFR16S0009319FR500	MBA02040C9319FRP00
SFR16S0007870FR500	MBA02040C7870FRP00	SFR16S0009530FR500	MBA02040C9530FRP00
SFR16S0007871FR500	MBA02040C7871FRP00	SFR16S0009531FR500	MBA02040C9531FRP00
SFR16S0008060FR500	MBA02040C8060FRP00	SFR16S000Z0000ZA500	MBA02040C0000FCT00
SFR16S0008063FR500	MBA02040C8063FRP00	SFR16S000Z0000ZR500	MBA02040C0000FRP00
SFR16S0008069FR500	MBA02040C8069FRP00	SFR16S0008203FA500	MBA02040C8203FCT00
SFR16S0008200FA500	MBA02040C8200FCT00	SFR16S0008203FR500	MBA02040C8203FRP00
SFR16S0008200JA100	MBA02040C8200FCT00	SFR16S0008203JA500	MBA02040C8203FCT00
SFR16S0008200JA500	MBA02040C8200FCT00	SFR16S0008208JA500	MBA02040C8208FCT00
SFR16S0008201FR500	MBA02040C8201FRP00	SFR16S0008209JA100	MBA02040C8209FCT00
SFR16S0008201JA500	MBA02040C8201FCT00	SFR16S0008209JA500	MBA02040C8209FCT00
SFR16S0008201JR500	MBA02040C8201FRP00	SFR16S0008209JR500	MBA02040C8209FRP00
SFR16S0008202JA100	MBA02040C8202FCT00	SFR16S0008250FR500	MBA02040C8250FRP00
SFR16S0008202JA500	MBA02040C8202FCT00	SFR16S0008251FR500	MBA02040C8251FRP00



The DNA of tech™

Product Information Notification



Appendix to PIN-DBR-00036-2024-REV-0

NFR25, NFR25H Series Affected Part Numbers

NFR2500001000JA100	NFR2500002207JA500	NFR2500004701JR500	NFR25H0001009JA500
NFR2500001000JA500	NFR2500002207JR500	NFR2500004707JR500	NFR25H0001009JR500
NFR2500001000JR500	NFR2500002208JA100	NFR2500004708JA100	NFR25H0001100JA500
NFR2500001001JA100	NFR2500002208JA500	NFR2500004708JA500	NFR25H0001202JA500
NFR2500001001JA500	NFR2500002208JR500	NFR2500004708JR500	NFR25H0001209JA100
NFR2500001001JR500	NFR2500002209JA100	NFR2500004709JA100	NFR25H0001500JA500
NFR2500001002JA100	NFR2500002209JA500	NFR2500004709JA500	NFR25H0001500JR500
NFR2500001002JA500	NFR2500002209JR500	NFR2500004709JR500	NFR25H0001501JR500
NFR2500001002JR500	NFR2500002700JA100	NFR2500005100JA500	NFR25H0001502JA500
NFR2500001008JA100	NFR2500002701JA100	NFR2500005608JA500	NFR25H0001502JR500
NFR2500001008JA500	NFR2500002701JA500	NFR2500006800JR500	NFR25H0001508JR500
NFR2500001008JR500	NFR2500002708JR500	NFR2500006807JR500	NFR25H0001509JA500
NFR2500001009JA100	NFR2500002709JA100	NFR2500006808JR500	NFR25H0001509JR500
NFR2500001009JA500	NFR2500003000JR500	NFR2500006809JA100	NFR25H0001800JA100
NFR2500001009JR500	NFR2500003300JA500	NFR2500006809JR500	NFR25H0001800JA500
NFR2500001200JA500	NFR2500003300JR500	NFR2500008200JA100	NFR25H0001808JA100
NFR2500001201JA100	NFR2500003307JR500	NFR25H0001000JA100	NFR25H0002001JA500
NFR2500001500JR500	NFR2500003308JA100	NFR25H0001000JA500	NFR25H0002008JA100
NFR2500001501JR500	NFR2500003308JA500	NFR25H0001000JR500	NFR25H0002200JA100
NFR2500001508JA100	NFR2500003308JR500	NFR25H0001001JA100	NFR25H0002200JA500
NFR2500001508JA500	NFR2500003309JA100	NFR25H0001001JA500	NFR25H0002200JR500
NFR2500001508JR500	NFR2500003309JR500	NFR25H0001001JR500	NFR25H0002201JA500
NFR2500002009JA500	NFR2500003600JA100	NFR25H0001002JA100	NFR25H0002201JR500
NFR2500002200JA100	NFR2500004309JA100	NFR25H0001002JA500	NFR25H0002207JA100
NFR2500002200JA500	NFR2500004700JA100	NFR25H0001002JR500	NFR25H0002207JN200
NFR2500002200JR500	NFR2500004700JA500	NFR25H0001008JA100	NFR25H0002207JR500
NFR2500002201JA100	NFR2500004700JR500	NFR25H0001008JA500	NFR25H0002208JA100
NFR2500002201JA500	NFR2500004701JA100	NFR25H0001008JR500	NFR25H0002208JA500
NFR2500002201JR500	NFR2500004701JA500	NFR25H0001009JA100	NFR25H0002208JR500
NFR25H0002209JA100	NFR25H0004708JA100	NFR25H0003307JR500	NFR25H0006800JA100
NFR25H0002209JA500	NFR25H0004708JA500	NFR25H0003308JA500	NFR25H0006800JR500
NFR25H0002209JR500	NFR25H0004708JN200	NFR25H0003308JR500	NFR25H0006801JA500
NFR25H0002700JA500	NFR25H0004708JR500	NFR25H0003309JA100	NFR25H0006801JR500
NFR25H0002701JA100	NFR25H0004709JA100	NFR25H0003309JA500	NFR25H0006807JA100
NFR25H0002701JA500	NFR25H0004709JA500	NFR25H0003309JR500	NFR25H0006807JR500
NFR25H0002707JA500	NFR25H0004709JR500	NFR25H0003900JA500	NFR25H0006808JR500
NFR25H0002708JA100	NFR25H0005100JR500	NFR25H0003907JA500	NFR25H0006809JA100
NFR25H0003300JA100	NFR25H0005109JR500	NFR25H0004700JA100	NFR25H0006809JR500
NFR25H0003300JA500	NFR25H0005608JA500	NFR25H0004700JA500	NFR25H0008200JA500
NFR25H0003300JR500	NFR25H0005609JA100	NFR25H0004700JR500	NFR25H0008208JA500



Appendix to PIN-DBR-00036-2024-REV-0

NFR25H0003301JR500	NFR25H0005609JR500	NFR25H0004701JA100	NFR25H0008209JA100
NFR25H0004701JA500	NFR25H0004701JR500	NFR25H0004707JA100	NFR25H0004707JA500
NFR25H0004707JR500	NFR25H0008209JA500		