



09-Jan-2025

PCN #: PCN-25-231513

Subject : Piano Dip Switches

Description of Change : Please be aware of an upcoming change to the listed part numbers (not affecting the function of the product only to improve current product production and quality to our customers).

Changes: 1. To enhance production stability and delivery flexibility, the manual production line was replaced with an automated production line. 2. Stop plates were added to both sides of the spring plate, and

positioning grooves were added to both sides of the actuator's protrusion to effectively secure the positioning of the spring plate and actuators. 3. Ink printing has been changed to laser printing.

Note: The product appearance, body dimensions, specifications and current performance remain unchanged.

Reason for Change: Product improvement

Key Dates :

Contact By Date: 01-Apr-2025

Implementation Date: 01-Apr-2025

Product Affected	Alias Part Number	Substitute Part Number	AliasSub Part Number
1-2319764-4	EDSP08SGLFNTU04		
2-2319764-5	EDSP10SGRNSTU04		
2319764-1	EDSP02SGLNNTU04		
2319764-2	EDSP04SGLNNTU04		
2319764-3	EDSP06SGLNNTU04		
2319764-4	EDSP08SGLNNTU04		
2319764-5	EDSP10SGLNNTU04		
2319764-8	EDSP06SGRNNTU04		
3-2319764-1	EDSP02SGLNNTR04		
3-2319764-2	EDSP04SGLNNTR04		
3-2319764-3	EDSP06SGLNNTR04		
3-2319764-4	EDSP08SGLNNTR04		
3-2319764-5	EDSP10SGLNNTR04		
3-2319764-8	EDSP06SGRNNTR04		
4-2319764-1	EDSP02SGLFNTR04		
4-2319764-2	EDSP04SGLFNTR04		
4-2319764-9	EDSP08SGRFNTR04		

5-2319764-1	EDSP02SGRNSTR04		
5-2319764-3	EDSP06SGRNSTR04		
5-2319764-5	EDSP10SGRNSTR04		

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.

Alert document created by Accuris based on content provided by TE Connectivity.