

PRODUCT CHANGE NOTIFICATION

PRODUCT CHANGE NOTIFICATION NUMBER: PC12587

PCN DATE: Sept. 30, 2025

This notice is to inform you about the following changes to the listed Stewart Connector products. For any further questions about these changes, please contact your Stewart Connector sales contact, or customer service representative.

PARTS AFFECTED:

450-011, 450-012, 450-013, 450-014, 450-015, 450-016, 450-017, 450-018, 450-023, 450-024, 450-025, 450-026, 450-027, 450-028, 450-029, 450-030, 450-031, 450-032, 450-044

REPLACEMENT PARTS:

Part numbers remain the same, with the changes outlined below.

GENERAL PRODUCT DESCRIPTION:

Strain relief boots with cable opening diameters of 0.224 inch and 0.24 inch.

REASON FOR CHANGE:

Our previous molds are at their end-of-life stage and can no longer be used for production.

We have new molds that will produce the replacement boots.

DESCRIPTION OF CHANGES:

We will be replacing these strain relief boots with the current mold formations.

Please note differences in the table on the next page and Appendix A.

ESTIMATED IMPLEMENTATION DATE:

This change is now in effect. There are no further older style boots available.

SIGNATURE:




Tim Kurten
Product Manager

| Obsolete Part Numbers | Replacement Part Numbers | New Part Drawing Numbers | Noteable Differences |
|---|--------------------------|--------------------------|--|
| 450-011 through 450-018 For Boot diam 0.224" | Same | CT999002 Rev D0 | Slightly smaller size and shape of anti-snag feature, No Stewart logo. |
| 450-023 through 450-032, and 450-044 For Boot diam 0.24" | Same | CT999007 Rev C0 | Slightly smaller size and shape of anti-snag feature, Cable exit hole is .27" versus .24" diameter |


Appendix A

450-011 through 450-018



450-023 through 450-044

Old style



New style

