

- PRIVACY POLICY
- COPYRIGHTED MATERIAL
- PROCEDURE FOR MAKING A CLAIM OF COPYRIGHTED INFRINGEMENT
- EXPORT CONTROL DATA
- CONTACT US

---

## Product Change Notification - SYST-11HIDZ834 (Printer Friendly)

**Date:**

12 Jan 2017

**Product Category:**

USB to Ethernet Controllers

**Affected CPNs:**



**Notification subject:**

Data Sheet - LAN7800 - SuperSpeed USB 3.1 Gen 1 10/100/1000 Ethernet Controller Data Sheet Document Revision

**Notification text:**

SYST-11HIDZ834

---

Microchip has released a new DeviceDoc for the LAN7800 - SuperSpeed USB 3.1 Gen 1 10/100/1000 Ethernet Controller of devices. If you are using one of these devices please read the document located at [LAN7800 - SuperSpeed USB 3.1 Gen 1 10/100/1000 Ethernet Controller](#).

**Notification Status:** Final

**Description of Change:** 1) Updated bits 12:9 descriptions in section 14.1.23.

**Impacts to Data Sheet:** None

**Reason for Change:** To Improve Productivity

**Change Implementation Status:** Complete

**Date Document Changes Effective:** 12 Jan 2017

**NOTE:** Please be advised that this is a change to the document only the product has not been changed.

**Markings to Distinguish Revised from Unrevised Devices:** N/A

---

**Attachment(s):**

[LAN7800 - SuperSpeed USB 3.1 Gen 1 10/100/1000 Ethernet Controller](#)