

Issue Date: March 19,2020

Dear Valued Customer,

This notice is to inform you of a product change affecting selected items that you have purchased from Littelfuse.

Description of the Change:

The manufacturing locations for plastic components associated with Part Number: 883-083 & 883-084, are being insourced from an outside injection molding supplier to a Littelfuse injection molding facility.

Part Numbers Affected:

Component	Part Number
883-083	PDM21001LXM
883-083	PDM21002LXM
883-083	PDM21004LXM
883-083	PDM21005LXM
883-083	PDM71001ZXM
883-083	PDM71002ZXM
883-083	PDM71003ZXM
883-083	PDM71004ZXM
883-083	PDM71006ZXM
883-083	PDM71007ZXM
883-083	PDM71008ZXM
883-083	PDM71009ZXM

Component	Part Number
883-084	PDM31001ZXM
883-084	PDM31004ZXM
883-084	PDM31002ZXM

Reason for Change:

The above parts are being insourced to strengthen our supply chain and increase our responsiveness to demand.

Effective Date of the Change:

The transition will happen over the course of Q2, 2020 with a tentative completion date of: 5/27/20



Expertise Applied | Answers Delivered

PRODUCT CHANGE NOTICE

What You Need to Do:

New quality and PPAP documentation will be prepared upon completion of the transfer and available upon request.

If you have any questions, please feel free to contact your Littelfuse Customer Service Representative or your Inside Sales Representative. We appreciate your business and our continued partnership.

Sincerely,

Joe Plazyk

Global Product Manager
Commercial Vehicle Products
Littelfuse, Inc.