

3/31/2023

Subject: Change Notification

To Our Valued Customer:

HellermannTyton continually evaluates our manufacturing and supply chain to provide you with quality service at a reasonable price. To better serve your business, we inform you of the following change affecting the list of parts enclosed with this letter.

CHANGE DETAILS

Transfer of production to improve capacity and optimize the supply chain. We are in the process of moving production from our USA site to our MX site. Changes will be in effect 6/1/2023 through end of 12/2023.

Impact	Old	New
Manufacturing Location	Milwaukee, WI, USA	Escobedo, NL, MX
2nd Manufacturing Location	N/A	N/A
Assembly Location	N/A	N/A
Country of Origin	USA	MX
Print Number & Revision	N/A	N/A
Material	N/A	N/A
Lead Time	N/A	N/A
Point of Purchase	N/A	N/A
Point of Pickup	N/A	N/A
Cost	N/A	N/A

LAST DAY TO PURCHASE CURRENT PRODUCT: 6/1/2023 *Subject to availability

Please update your requirements accordingly prior to this date. We ask that you send acknowledgement of this notification within 15 business days, informing us if you need any additional information or data. If we do not receive a response, we assume the change can be executed as planned without further notice. For assistance please contact your HellermannTyton Customer Service Representative. We appreciate your support in this change

Thank you for your continued business,

Tiffany Hinton
Quality Project Admin.
(414) 355-1130
Tiffany.Hinton@htamericas.com



HT Order Code	Customer PN	New HT Order Code/
		Replacement
111-12300	75Y4075	111-12300
111-12301	75Y4076	111-12301
111-12302	75Y4077	111-12302
SNP18A10C2	80Y1487	SNP18A10C2
SNP2410C2	75Y3045	SNP2410C2
SNP8GHS0C2	75Y3095	SNP8GHS0C2
T120MR0H4	75Y3427	T120MR0H4
T120RDH0K2	75Y3432	T120RDH0K2
T120RSM0HIRK2	75Y3433	T120RSM0HIRK2
11201011101111112	7010100	11201011101111112
+		
L		