



## PRODUCT BULLETIN

Generic Copy

**ISSUE DATE:** 21-Sep-2012  
**NOTIFICATION:** 15375  
**TITLE:** DZ60 2M74K ERRATA DISTRIBUTION  
**EFFECTIVE DATE:** 22-Sep-2012

### **DEVICE(S)**

MPN
MC9S08DN16ACLC
MC9S08DN16AMLC
MC9S08DN16AMLF
MC9S08DN32ACLF
MC9S08DN32ACLH
MC9S08DN32AMLC
MC9S08DN32AMLF
MC9S08DN32AMLH
MC9S08DN32AVLF
MC9S08DN60ACLF
MC9S08DN60ACLH
MC9S08DN60AMLC
MC9S08DN60AMLF
MC9S08DN60AMLH
MC9S08DV16ACLC
MC9S08DV16ACLF
MC9S08DV16AMLC
MC9S08DV16AMLF
MC9S08DV32ACLC
MC9S08DV32ACLF
MC9S08DV32ACLH
MC9S08DV32AMLC
MC9S08DV32AMLCR
MC9S08DV32AMLF
MC9S08DV32AMLH
MC9S08DV48ACLC
MC9S08DV48ACLF
MC9S08DV48ACLH

MC9S08DV48AMLC
MC9S08DV48AMLF
MC9S08DV48AMLH
MC9S08DV60ACLC
MC9S08DV60ACLF
MC9S08DV60ACLFR
MC9S08DV60ACLH
MC9S08DV60AMLC
MC9S08DV60AMLF
MC9S08DV60AMLH
MC9S08DZ16ACLC
MC9S08DZ16ACLF
MC9S08DZ16AMLC
MC9S08DZ16AMLF
MC9S08DZ32ACLC
MC9S08DZ32ACLF
MC9S08DZ32ACLH
MC9S08DZ32AMLC
MC9S08DZ32AMLF
MC9S08DZ32AMLFR
MC9S08DZ32AMLH
MC9S08DZ48ACLC
MC9S08DZ48ACLF
MC9S08DZ48ACLH
MC9S08DZ48AMLC
MC9S08DZ48AMLF
MC9S08DZ48AMLH
MC9S08DZ60ACLC
MC9S08DZ60ACLF
MC9S08DZ60ACLH
MC9S08DZ60AMLC
MC9S08DZ60AMLF
MC9S08DZ60AMLH
S9S08DN16F2CLC
S9S08DN16F2CLF
S9S08DN32F2CLC
S9S08DN32F2CLCR
S9S08DN32F2CLF
S9S08DN32F2CLH

S9S08DN32F2MLC
S9S08DN32F2MLH
S9S08DN32F2VLC
S9S08DN32F2VLF
S9S08DN32F2VLFR
S9S08DN48F2CLF
S9S08DN48F2CLFR
S9S08DN48F2MLF
S9S08DN48F2MLFR
S9S08DN48F2MLH
S9S08DN48F2VLC
S9S08DN48F2VLF
S9S08DN48F2VLFR
S9S08DN60F2CLF
S9S08DN60F2CLH
S9S08DN60F2VLF
S9S08DN60F2VLH
S9S08DV16F2MLC
S9S08DV32F2MLC
S9S08DV32F2MLH
S9S08DV32F2VLC
S9S08DV32F2VLCR
S9S08DV48F2CLC
S9S08DV60F2CLH
S9S08DV60F2MLF
S9S08DZ16F2CLC
S9S08DZ16F2MLC
S9S08DZ16F2MLF
S9S08DZ16F2VLF
S9S08DZ32F2CLC
S9S08DZ32F2CLF
S9S08DZ32F2CLH
S9S08DZ32F2MLC
S9S08DZ32F2MLCR
S9S08DZ32F2MLF
S9S08DZ32F2MLFR
S9S08DZ32F2MLH
S9S08DZ32F2VLC
S9S08DZ32F2VLCR

S9S08DZ32F2VLF
S9S08DZ32F2VLH
S9S08DZ32F2VLHR
S9S08DZ48F2CLF
S9S08DZ48F2CLFR
S9S08DZ48F2CLH
S9S08DZ48F2MLF
S9S08DZ48F2MLH
S9S08DZ48F2VLF
S9S08DZ48F2VLFR
S9S08DZ60F2CLC
S9S08DZ60F2CLF
S9S08DZ60F2CLH
S9S08DZ60F2CLHR
S9S08DZ60F2MLC
S9S08DZ60F2MLCR
S9S08DZ60F2MLF
S9S08DZ60F2MLFR
S9S08DZ60F2MLH
S9S08DZ60F2MLHR
S9S08DZ60F2VLC
S9S08DZ60F2VLCR
S9S08DZ60F2VLH
S9S08DZ60F2VLHR

---

### **AFFECTED CHANGE CATEGORIES**

- DEVICE SPECIFICATION / ERRATA

### **DESCRIPTION OF CHANGE**

The 9S08DZ60 family of parts 2M74K mask set errata documentation is available now on Freescale website.

The errata documentation can be found at [http://www.freescale.com/webapp/sps/site/prod\\_summary.jsp?code=S08D&fpp=1&tab=Documentation\\_Tab](http://www.freescale.com/webapp/sps/site/prod_summary.jsp?code=S08D&fpp=1&tab=Documentation_Tab)

The 2M74K errata document is the same with 1M74K errata except removed following errata: SE182-MCG-HighSIDD3: High SIDD3 at cold.

## **REASON FOR CHANGE**

Initially published the errata documentation for 9S08DZ60 family of parts on 2M74K mask set.

## **ANTICIPATED IMPACT OF PRODUCT CHANGE(FORM, FIT, FUNCTION, OR RELIABILITY)**

There is no impact to device form, fit, function or reliability. There has been no change made to the current production device. The errata describes an existing condition that was identified on current production processes.

---

### **NOTE:**

THE CHANGE(S) SPECIFIED IN THIS NOTIFICATION WILL BE IMPLEMENTED ON THE EFFECTIVE DATE LISTED ABOVE. To request further data or inquire about the notification, please enter a [Service Request](#)

For sample inquiries - please go to [www.freescale.com](http://www.freescale.com)

---

**QUAL DATA AVAILABILITY DATE:** 11-Nov-2009

**QUALIFICATION STATUS:** COMPLETED

### **QUALIFICATION PLAN:**

N/A

### **RELIABILITY DATA SUMMARY:**

N/A

### **ELECTRICAL CHARACTERISTIC SUMMARY:**

N/A

---

### **CHANGED PART IDENTIFICATION:**

N/A

**SAMPLE AVAILABILITY DATE:** 20-Sep-2012

---

---

**ATTACHMENT(S):**

External attachment(s) FOR this notification can be viewed AT:

[15375\\_MSE9S08DZ60\\_2M74K.pdf](#)

---