

XAC, followed by A, followed by 20 or 21 - Auxiliary Devices

Auxiliary Devices

File Number: E164353

COMPANY

Schneider Electric Industries S A, DBA Telemecanique

8001 Knightdale Blvd
Knightdale, NC 27545 United States

MODEL INFO

XAC, followed by A, followed by 20 or 21 followed by 1, 3, 5, or 7, may be followed by 3 or 4.

Pendant stations

AUXILIARY DEVICES	VALUE
UL Standard	ANSI/UL 508
cUL Standard	CAN/CSA-C22.2 No. 14



The appearance of a company's name or product in this database does not in itself assure that products so identified have been manufactured under UL Solutions' Follow - Up Service. Only those products bearing the UL Mark should be considered to be Certified and covered under UL Solutions' Follow - Up Service. Always look for the Mark on the product.

UL Solutions permits the reproduction of the material contained in Product iQ subject to the following conditions: 1. The Guide Information, Assemblies, Constructions, Designs, Systems, and/or Certifications (files) must be presented in their entirety and in a non-misleading manner, without any manipulation of the data (or drawings). 2. The statement "Reprinted from Product iQ with permission from UL Solutions" must appear adjacent to the extracted material. In addition, the reprinted material must include a copyright notice in the following format: "©2023 UL LLC."