

10627256
GCN Number
June 13, 2014
Date Issued
ified, Or Replacement Tooling
used to make housing 5569-04 has reached its end of life and is aced by an identical tool.
er to CustomerPartList.csv attached to e-mail message.
ool will be fully qualified by Molex before it is released to n. The housings produced from the new mold will be identical to the arts.
014
014
r 01, 2014
ade after September 1, 2014
able

Contact	Name	E-mail	Phone Number
Sales Engineer	Please refer to e-mail message for your local sales engineer.		
Regional Coordinator (Japan and Korea)	Naomi Maruyama	Naomi.Maruyama@molex.co.jp	+81-46-265-2416
Regional Coordinator (Asia- excluding Japan and Korea)	Allen Yu	Allen.Yu@molex.com	+886-2-66251751
Regional Coordinator (Europe, Middle East, Africa)	QuiNann Lim	QuiNann.Lim@molex.com	+31-40-295-8472
Regional Coordinator (Americas)	Maria Sullivan	Maria.Sullivan@molex.com	1-727-322-4352

Molex, Inc. 2222 Wellington Court Lisle, IL 60532 TEL: 630-969-4747 www.molex.com