



Product Change Notification

Current Date: 21-Oct-2020

TE Connectivity

Product Change Notification: P-20-019869

PCN Date: 20-OCT-20

Customer: TTI, Inc. (1305175)

Location: Maisach-gernlinden

Agreement: Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

Manufacturing location change product change notification

Description of Changes

The following Part Numbers will be transferred from the Bath facility, UK, to Hastings UK location.

Reason for Changes:

Relocating the products will support a fully integrated, vertical model including machining, plating and assembly with a view to improving lead times and operational flexibility. Our plan includes mitigating actions to ensure this is a smooth transfer, and both facilities operating under AS9100. The transfer will be in phases, starting at the end of 2020, and target competition date end of 2021.

Estimated Dates:

Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):
	31-DEC-2020
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):
	31-DEC-2021

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
019147-000	NO		RAY019147-000	6-1190149-1, TXR40AB00-1007AI			
028943-000	NO			2-1190224-4, STXR40AB00-1414AI			
038625-000	NO		RAY038625-000	7-1190296-4, TXR40AB00-1208BI			
046753-000	NO		RAY046753-000	1-1190359-8, TXR40AB00-2218BI			
055735-000	NO			1190425-9, TXR54AB00-1405AI			
069533-000	NO			1-1190523-7, STXR40AB00-1618AI			
109349-000	NO			8-1190798-2, TXR41AB00-1810AI			
116827-000	NO			1190851-9, 202M218-19B			
119071-000	NO			3-1190866-6, TXR40BW00-1608BI			
166169-000	NO			5-1191199-5, STXR40AB00-1010AI			
172921-000	NO			7-1191257-7, TXR54AB00-1607AI			
182815-000	NO			2-1191328-2, TXR54AC00-1006AIF			
209901-000	NO		RAY209901-000	2-1191521-2, STXR40AB00-0807AI			
246419-000	NO		RAY246419-000	6-1191807-4, TXR40BW00-2412AI			
279241-000	NO			8-1192066-3, TXR40BW90-0804AI			
296535-000	NO			4-1192246-6, TXR41AB00-1605AI			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
349831-000	NO			9-1192631-3, TXR41AB00-1612AI			
393537-000	NO		RAY393537-000	4-1192952-9, TXR54AB00-2410AI			
427167-000	NO			2-1193214-4, TXR40AB00-1805AI			
458497-000	NO		RAY458497-000	7-1193439-7, TXR40AB00-1410BI			
482511-000	NO			6-1193611-3, TXR41AC00-0804BI			
511311-000	NO		RAY511311-000	1-1194019-6, TXR40AB00-1808AI			
515403-000	NO		RAY515403-000	1194048-3, TXR40AB00-1008AI			
519093-000	NO			7-1194073-5, TXR41AB00-1808AI			
559084-000	NO			5-1194413-0, 209M424-19C			
629267-000	NO		RAY629267-000	2-1194981-0, TXR40AB00-1608AI			
679493-000	NO			6-1195341-5, TXR21AB00-1208AI			
807176-000	NO			2-1196252-5, 203M012-19C07			
808742-000	NO			8-1196280-3, 201M912-19G			
830023-000	NO			3-1196481-9, TXR21AB00-2416AI			
876282-000	NO			5-1199253-9, TXR40BW00-2214AI			
886065-000	NO		RAY886065-000	4-1196894-2, TXR40AB00-1005AI			
889283-000	NO			5-1196918-3, TXR40AB00-1607AI			
893443-000	NO			2-1196949-3, TXR40AB00-1212AI			
904861-000	NO			6-1197031-1, TXR41AB00-1606AI			
917397-000	NO			9-1197120-1, 201M916-19B			
998903-000	NO			2-1197723-3, TXR40BW00-2210AI			
A95128-000	NO			8-1201255-9, TXR76AU00-1004AI			
AAF3425-000	NO			TXR40AB90-2422BI			
CH1189-000	NO			6-1899527-4, STXR76AB00-0810AI			
CV4709-000	NO			TXR40BW00-1406BI			
CW1295-000	NO			TX40AZ90-1608			
EF5733-000	NO			225M328-19B			
EM5088-000	NO			TXR40BW00-1807AI			
EM6771-000	NO			TXR54AC00-2420BI			
F85976-000	NO		RAYF85976-000	9-1200801-8, TXR76AU00-1006AI			



Product Change Notification

Current Date: 21-Oct-2020

TE Connectivity

Product Change Notification: P-20-019869

PCN Date: 20-OCT-20

Customer: TTI, Inc. (3057778)

Location: Maisach-gernlinden

Agreement: Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

Manufacturing location change product change notification

Description of Changes

The following Part Numbers will be transferred from the Bath facility, UK, to Hastings UK location.

Reason for Changes:

Relocating the products will support a fully integrated, vertical model including machining, plating and assembly with a view to improving lead times and operational flexibility. Our plan includes mitigating actions to ensure this is a smooth transfer, and both facilities operating under AS9100. The transfer will be in phases, starting at the end of 2020, and target competition date end of 2021.

Estimated Dates:

Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):
	31-DEC-2020
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):
	31-DEC-2021

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
019147-000	NO		RAY019147-000	6-1190149-1, TXR40AB00-1007AI			
028943-000	NO			2-1190224-4, STXR40AB00-1414AI			
038625-000	NO		RAY038625-000	7-1190296-4, TXR40AB00-1208BI			
046753-000	NO		RAY046753-000	1-1190359-8, TXR40AB00-2218BI			
055735-000	NO			1190425-9, TXR54AB00-1405AI			
069533-000	NO			1-1190523-7, STXR40AB00-1618AI			
109349-000	NO			8-1190798-2, TXR41AB00-1810AI			
116827-000	NO			1190851-9, 202M218-19B			
119071-000	NO			3-1190866-6, TXR40BW00-1608BI			
166169-000	NO			5-1191199-5, STXR40AB00-1010AI			
172921-000	NO			7-1191257-7, TXR54AB00-1607AI			
182815-000	NO			2-1191328-2, TXR54AC00-1006AIF			
209901-000	NO		RAY209901-000	2-1191521-2, STXR40AB00-0807AI			
246419-000	NO		RAY246419-000	6-1191807-4, TXR40BW00-2412AI			
279241-000	NO			8-1192066-3, TXR40BW90-0804AI			
296535-000	NO			4-1192246-6, TXR41AB00-1605AI			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
349831-000	NO			9-1192631-3, TXR41AB00-1612AI			
393537-000	NO		RAY393537-000	4-1192952-9, TXR54AB00-2410AI			
427167-000	NO			2-1193214-4, TXR40AB00-1805AI			
482511-000	NO			6-1193611-3, TXR41AC00-0804BI			
511311-000	NO		RAY511311-000	1-1194019-6, TXR40AB00-1808AI			
515403-000	NO		RAY515403-000	1194048-3, TXR40AB00-1008AI			
519093-000	NO			7-1194073-5, TXR41AB00-1808AI			
559084-000	NO			5-1194413-0, 209M424-19C			
629267-000	NO		RAY629267-000	2-1194981-0, TXR40AB00-1608AI			
679493-000	NO			6-1195341-5, TXR21AB00-1208AI			
807176-000	NO			2-1196252-5, 203M012-19C07			
808742-000	NO			8-1196280-3, 201M912-19G			
830023-000	NO			3-1196481-9, TXR21AB00-2416AI			
876282-000	NO			5-1199253-9, TXR40BW00-2214AI			
886065-000	NO		RAY886065-000	4-1196894-2, TXR40AB00-1005AI			
889283-000	NO			5-1196918-3, TXR40AB00-1607AI			
893443-000	NO			2-1196949-3, TXR40AB00-1212AI			
904861-000	NO			6-1197031-1, TXR41AB00-1606AI			
917397-000	NO			9-1197120-1, 201M916-19B			
998903-000	NO			2-1197723-3, TXR40BW00-2210AI			
A95128-000	NO			8-1201255-9, TXR76AU00-1004AI			
AAF3425-00	NO			TXR40AB90-2422BI			
CH1189-000	NO			6-1899527-4, STXR76AB00-0810AI			
CV4709-000	NO			TXR40BW00-1406BI			
CW1295-000	NO			TX40AZ90-1608			
EF5733-000	NO			225M328-19B			
EM5088-000	NO			TXR40BW00-1807AI			
EM6771-000	NO			TXR54AC00-2420BI			
F85976-000	NO		RAYF85976-000	9-1200801-8, TXR76AU00-1006AI			