

10-Nov-2023

PCN #: PCN-23-192238

Subject : Dynamic D5000 Header s Housing

Description of Change : Reference performance test data: Please be aware of an upcoming alternative resin material add to the listed part numbers.

Product spec, customer drawing, and UL file number (E28476) are not changed.

Reason: Add the alternative resin material to reduce the risk of resin supply capacity against huge demand.

Adding the alternative material, we try to keep the production and continue supplying our products. The change follows a strict procedure, which fully maintains quality, ability to supply and form -fit-function of the concerned products.

Key Dates:

Contact By Date:07-May-2024 Implementation Date:07-May-2024

Product Affected	Alias Part Number	Substitute Part Number	AliasSub Part Number
2-353082-3			
1-353082-2			
1-353081-2			
2-353080-2			
1-917541-2			
1-1318983-6			
1-179960-2			
1-917542-2			
1-353079-2			
1-353080-2			
2-353079-2			
2-917541-2			
2-353082-2			

1-353082-3		
1-917542-3		
1-1123309-2		
2-179960-2		
2-917542-2		

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.

Alert document created by IHS Markit based on content provided by TE Connectivity.