



WCS2-GT-BR Set

Holes are provided on the guide trolley WCS2-GT09-... for fitting the cleaning brushes for the code rail. The cleaning brushes are only necessary if the code rail becomes so soiled that the slots in the code rail can not longer be recognised by the reading head (error signal from reading head).

In systems with such extreme ambient conditions, in addition to the cleaning brushes use of the stainless steel code rail is recommended. The cleaning brushes can be retrofitted.

## Technical data

### Mechanical specifications

Material Polyamide (PA)

Mass 20 g

### General information

Packing unit 2 item(s)