

Product Change Notice

Issue Date: 24-February-2022

Change Description:

Alternative dice source for IR PLCC4

Parts Affected:

AREQ-80C0-00000
AREQ-80C0-LN000
AREQ-83C0-QS000
AREQ-85C0-NQ000
AREQ-90C0-00000
AREQ-90C0-LN000
AREQ-93C0-QR000
AREQ-95C0-NQ000
QREQ-90MB-00000

Description and Extent of Change:

Introduction of new dice source

Reasons for Change:

Assurance of supply

Effect of Change on Fit, Form, Function, Quality, or Reliability:

There will be no change on fit, form, function, quality and reliability of final product.

Effective Date of Change:

Parts with above change will commence 90 days after issuance date above.

Broadcom will continue ship parts with current lead frame and die sources after implementation date until inventories are fully depleted.

Qualification Data:

No change in reliability performance. Product and qualification data will be available upon request.

Please contact your Broadcom field sales engineer or Contact Center for any questions or support requirements. Please acknowledge the receipt of the notice within 30 days of delivery. Lack of acknowledgement within 30 days constitutes acceptance of the change per JEDEC J-STD-046.