

Product Advisory Notice

Subject: Minimum Line Quantity Change

Publication Date: 2/18/2015

Effective Date: 3/1/2015

Revision Description:

Initial Release

This advisory is to inform you that Intersil has updated the minimum line quantity (MLQ) for the parts listed in this notice. This notice is distributed for information only as the change does not affect product form, fit or function.

A product list, citing the old and new MLQ (minimum order quantity) is included in this notice.

These changes will affect all orders placed on the books on or after 3/1/2015 but will not affect any orders currently on the books or placed on the books prior to that date.

If you have concerns with this advisory, Intersil must hear from you promptly. Please contact the nearest Intersil Sales Office or call the Intersil Corporate line at 1-888-468-3774, in the United States, or 1-321-724-7143 outside of the United States.