



Product Change Notification

TE Connectivity

Product Change Notification: P-20-018881

PCN Date: 06-APR-20

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:
Notification of packaging changes for -STK tubing products.

Description of Changes
This is a notification informing TE Connectivity customers that the packaging boxes used for the tubing -STK products will be changing.
Other attachments:
[Stick parts for Box changes 0232](#)
[New Stick Boxes 2020](#)
[PCN - Changes to -STK boxes](#)

Reason for Changes:
Product improvement. We are moving to a more robust design that will give better protection to the tubing products during transportation. The boxes are moving from a square profile to a rectangular one with different cardboard and latching method. We will be transitioning boxes as existing packaging is consumed so not all product will change at the same time.

Estimated Dates:

Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):
	08-APR-2020
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):
	31-OCT-2020

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
0021032009	NO			"9-1190015-4", "RBK-ILS-125-NR3-0-STK"			
0989072006	NO			"6-1190724-4", "RBK-ILS-125-NR2-0-STK"			
1074372007	NO			"7-1190784-1", "DWTC-8/2-X-STK"			
1880982003	NO			"1-1191365-8", "RAYRIM-NR7-0-STK"			
2525592005	NO			"4-1191848-8", "RBK-ILS-125-NR1-0-STK"			
3128592004	NO			"6-1192366-6", "CGAT-12/4-0-STK"			
4177512003	NO			"6-1193147-1", "ATUM-24/6-0-STK", "ATUM-24/6-0-STK"			
4426612006	NO			"7-1193327-6", "RAYRIM-NR9-0-STK"			
5039572011	NO			"6-1193803-4", "TPEM-NR7-0-STK"			
5039582014	NO			"8-1193803-1", "TPEM-NR8-0-STK"			
5039822001	NO			"1-1193804-1", "TPEM-NR6-0-STK"			
5068832008	NO			"6-1193942-9", "TPEM-NR9-0-STK"			
5504062129	NO			"7-1194343-9", "ATUM-3/1-0-MS-STK"			
5677562009	NO			"5-1194493-7", "RNF-3000-3/1-0-STK"			
5983222002	NO			"7-1198045-3", "DSPL-NR2-0-STK"			
6918832001	NO						

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
				"9-1195431-6", "RAYRIM-NR12-0-STK"			
7024702003	NO			"1195512-3", "ATUM-52/13-0-STK", "ATUM-52/13-0-STK"			
7501712002	NO			"3-1195850-1", "RBK-ILS-125-NR4-0-STK"			
7574442007	NO			"2-1195902-1", "RAYRIM-NR8-0-STK"			
8503232002	NO			"9-1196629-6", "DWTC-12/3-X-STK"			
8953152001	NO			"1196962-3", "RPPM-12/3-X-STK"			
9556822004	NO			"1-1197399-8", "DWTC-4/1-X-STK"			
CH03472001	NO			"QSZH-125-NR1-STK", "1899487-7"			
CH03542001	NO			"QSZH-125-NR2-STK", "1-1899487-6"			
CH03612001	NO			"QSZH-125-NR3-STK", "2-1899487-3"			
CH03642001	NO			"QSZH-125-NR4-STK", "2-1899487-5"			
CV20922001	NO			"RW-175-E-3/64-X-STK"			
CV25372001	NO			"RW-175-E-3/16-X-STK", "5-1899810-2"			
CV25382001	NO			"RW-175-E-3/32-X-STK", "5-1899810-1"			
CV25852001	NO			"RW-175-E-3/8-X-STK", "5-1899810-0"			
CV37312001	NO			"RW-175-E-3/4-X-STK", "3-1899810-9"			
E296612001	NO			"2-1201664-9", "DSPL-NR1-X-STK"			
EL84962001	NO			"RBK-VWS-125-NR3-X-STK", "8-1899840-6"			
EL88602001	NO			"RBK-VWS-125-NR2-X-STK", "9-1899840-9"			
NB07402001	NO			"HTAT-12/3-0-STK", "1899848-1"			
NB07552001	NO						
NB07892001	NO						
NB08012001	NO						
NB09012001	NO						
NB09312001	NO			"ATUM--12/4-0-STK"			
NB09542001	NO			"ATUM--16/4-0-STK"			
NB09662001	NO						
NB10372001	NO			"ATUM--24/8-0-STK"			
NB10602001	NO						
NB11022001	NO						
NB13282001	NO						
NB13942001	NO						
NB13982001	NO						
NB14002001	NO						
NB14862001	NO						
NB14912001	NO						
NB15492001	NO						
NB16212001	NO						
NB16282001	NO						
NB16412001	NO						
NB16622001	NO						
NB16702001	NO						
NB17002001	NO						
NB17012001	NO						
NB17372001	NO			"RP-4800-NO.2-0-STK"			
NB17932001	NO						
NB18162001	NO						
NB18742001	NO						
NB19382001	NO						
NB19392001	NO						
NB24322001	NO						

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
NB25802001	NO						
NB25822001	NO						
NB25862001	NO						
NB25882001	NO						
NB25912001	NO						
NB25922001	NO						

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
3128592004	NO			"6-1192366-6", "CGAT-12/4-0-STK"			
4177512003	NO			"6-1193147-1", "ATUM-24/6-0-STK", "ATUM-24/6-0-STK"			
4426612006	NO			"7-1193327-6", "RAYRIM-NR9-0-STK"			
5504062129	NO			"7-1194343-9", "ATUM-3/1-0-MS-STK"			
5677562009	NO			"5-1194493-7", "RNF-3000-3/1-0-STK"			
7024702003	NO			"1195512-3", "ATUM-52/13-0-STK", "ATUM-52/13-0-STK"			
9556822004	NO			"1-1197399-8", "DWTC-4/1-X-STK"			
NB09012001	NO						
NB09312001	NO			"ATUM--12/4-0-STK"			
NB09542001	NO			"ATUM--16/4-0-STK"			
NB10372001	NO			"ATUM--24/8-0-STK"			
NB10602001	NO						
NB11022001	NO						
NB13282001	NO						
NB13942001	NO						
NB13982001	NO						
NB14002001	NO						
NB14862001	NO						
NB14912001	NO						
NB15492001	NO						
NB16212001	NO						
NB16282001	NO						
NB16412001	NO						
NB16622001	NO						
NB16702001	NO						
NB17002001	NO						
NB17372001	NO			"RP-4800-NO.2-0-STK"			
NB17932001	NO						
NB18162001	NO						
NB18742001	NO						
NB19382001	NO						
NB19392001	NO						
NB24322001	NO						
NB25822001	NO						
NB25862001	NO						
NB25882001	NO						
NB25922001	NO						

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
4426612006	NO			"7-1193327-6", "RAYRIM-NR9-0-STK"			
5504062129	NO			"7-1194343-9", "ATUM-3/1-0-MS-STK"			
5677562009	NO			"5-1194493-7", "RNF-3000-3/1-0-STK"			
7024702003	NO			"1195512-3", "ATUM-52/13-0-STK", "ATUM-52/13-0-STK"			
9556822004	NO			"1-1197399-8", "DWTC-4/1-X-STK"			
CH03472001	NO			"QSZH-125-NR1-STK", "1899487-7"			
CV25852001	NO			"RW-175-E-3/8-X-STK", "5-1899810-0"			
NB09012001	NO						
NB09312001	NO			"ATUM--12/4-0-STK"			
NB09542001	NO			"ATUM--16/4-0-STK"			
NB10372001	NO			"ATUM--24/8-0-STK"			
NB10602001	NO						
NB11022001	NO						
NB13982001	NO						
NB14862001	NO						
NB14912001	NO						
NB16412001	NO						
NB24322001	NO						

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
0021032009	NO			"9-1190015-4", "RBK-ILS-125-NR3-0-STK"			
0989072006	NO			"6-1190724-4", "RBK-ILS-125-NR2-0-STK"			
1074372007	NO			"7-1190784-1", "DWTC-8/2-X-STK"			
1880982003	NO			"1-1191365-8", "RAYRIM-NR7-0-STK"			
2525592005	NO			"4-1191848-8", "RBK-ILS-125-NR1-0-STK"			
4426612006	NO			"7-1193327-6", "RAYRIM-NR9-0-STK"			
5039582014	NO			"8-1193803-1", "TPEM-NR8-0-STK"			
5983222002	NO			"7-1198045-3", "DSPL-NR2-0-STK"			
6918832001	NO			"9-1195431-6", "RAYRIM-NR12-0-STK"			
7501712002	NO			"3-1195850-1", "RBK-ILS-125-NR4-0-STK"			
7574442007	NO			"2-1195902-1", "RAYRIM-NR8-0-STK"			
8953152001	NO			"1196962-3", "RPPM-12/3-X-STK"			
CH03472001	NO			"QSZH-125-NR1-STK", "1899487-7"			
CH03542001	NO			"QSZH-125-NR2-STK", "1-1899487-6"			
CH03612001	NO			"QSZH-125-NR3-STK", "2-1899487-3"			
CH03642001	NO			"QSZH-125-NR4-STK", "2-1899487-5"			
CV20922001	NO			"RW-175-E-3/64-X-STK"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
CV25372001	NO			"RW-175-E-3/16-X-STK", "5-1899810-2"			
CV25852001	NO			"RW-175-E-3/8-X-STK", "5-1899810-0"			
CV37312001	NO			"RW-175-E-3/4-X-STK", "3-1899810-9"			
E296612001	NO			"2-1201664-9", "DSPL-NR1- X-STK"			
EL84962001	NO			"RBK-VWS-125-NR3-X-STK", "8-1899840-6"			
EL88602001	NO			"RBK-VWS-125-NR2-X-STK", "9-1899840-9"			
NB07402001	NO			"HTAT-12/3-0-STK", "1899848-1"			
NB07552001	NO						
NB07892001	NO						
NB08012001	NO						
NB09662001	NO						

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
0021032009	NO			"9-1190015-4", "RBK-ILS- 125-NR3-0-STK"			
0989072006	NO			"6-1190724-4", "RBK-ILS- 125-NR2-0-STK"			
1074372007	NO			"7-1190784-1", "DWTC-8/2-X-STK"			
1880982003	NO			"1-1191365-8", "RAYRIM- NR7-0-STK"			
2525592005	NO			"4-1191848-8", "RBK-ILS- 125-NR1-0-STK"			
4426612006	NO			"7-1193327-6", "RAYRIM- NR9-0-STK"			
5039572011	NO			"6-1193803-4", "TPEM-NR7- 0-STK"			
5039582014	NO			"8-1193803-1", "TPEM-NR8- 0-STK"			
5039822001	NO			"1-1193804-1", "TPEM-NR6- 0-STK"			
5068832008	NO			"6-1193942-9", "TPEM-NR9- 0-STK"			
5983222002	NO			"7-1198045-3", "DSPL-NR2- 0-STK"			
6918832001	NO			"9-1195431-6", "RAYRIM- NR12-0-STK"			
7501712002	NO			"3-1195850-1", "RBK-ILS- 125-NR4-0-STK"			
7574442007	NO			"2-1195902-1", "RAYRIM- NR8-0-STK"			
8503232002	NO			"9-1196629-6", "DWTC- 12/3-X-STK"			
8953152001	NO			"1196962-3", "RPPM-12/3-X- STK"			
CH03472001	NO			"QSZH-125-NR1-STK", "1899487-7"			
CH03542001	NO			"QSZH-125-NR2-STK", "1-1899487-6"			
CH03612001	NO			"QSZH-125-NR3-STK", "2-1899487-3"			
CH03642001	NO			"QSZH-125-NR4-STK", "2-1899487-5"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
CV20922001	NO			"RW-175-E-3/64-X-STK"			
CV25372001	NO			"RW-175-E-3/16-X-STK", "5-1899810-2"			
CV25382001	NO			"RW-175-E-3/32-X-STK", "5-1899810-1"			
CV25852001	NO			"RW-175-E-3/8-X-STK", "5-1899810-0"			
CV37312001	NO			"RW-175-E-3/4-X-STK", "3-1899810-9"			
E296612001	NO			"2-1201664-9", "DSPL-NR1-X-STK"			
EL84962001	NO			"RBK-VWS-125-NR3-X-STK", "8-1899840-6"			
EL88602001	NO			"RBK-VWS-125-NR2-X-STK", "9-1899840-9"			
NB07402001	NO			"HTAT-12/3-0-STK", "1899848-1"			
NB07552001	NO						
NB07892001	NO						
NB08012001	NO						
NB09662001	NO						
NB17002001	NO						
NB17012001	NO						
NB25802001	NO						
NB25912001	NO						