



24-Mar-2021

PCN #:P-21-020686

Subject:Semi-Rigid Modified [-3] Molded Parts

Description of Change: -3 Molded Parts are chemically cross linked. The chemical added to this product material that enables the cross linking process has been replaced from a solid supplied version to a liquid equivalent.

Reason: Product improvement. Manufacturing trials performed on our manufacturing site have shown mixer is able to provide a more dispersed and homogeneous compound when a liquid cross-linking chemical is used. TE Connectivity has conducted exhaustive manufacturing trials, and final product evaluation to the performance requirements of RT-301 specification on two consecutive compound batches. Test report summarizing results can be shared upon request.

Key Dates:

Contact By Date:24-Mar-2021

Implementation Date:24-Mar-2021

Product Affected	Alias Part Number
823202-000	"423A014-3-0", "8-1196422-4"
CX4848-000	
181973-000	"3-1191322-0", "202K153-4-00-0"
273707-000	"202K153-25-00/86-0", "4-1192027-1"
034084-001	"9-1190263-6", "F133-200-FR"
813909-000	"222A132-3-0", "1-1196333-0"
823340-000	"382A012-3/42-0", "2-1196426-0"
163497-000	"1191180-3", "234A032-3/86-0"
813854-000	"202A153-3-0", "6-1196332-3"
814729-000	"202A174-3/42-0", "1196347-9"
823043-000	"342A034-4-00-0", "7-1196420-4"

Product Affected	Alias Part Number
814714-000	"222A111-3/42-0", "5-1196346-1"
584259-000	"322A112-3/86-0", "1194627-3"
174271-000	"101A011-3/86-0", "5-1191267-2"
878086-000	"202K163-3/42-0", "1196832-6"
807759-000	"202D132-3-60/42-0", "6-1196262-0"
249315-000	"202D211-3/180-0", "3-1191828-4"
814769-000	"234A652-3-0", "9-1196347-8"
805816-000	"222A111-25-00-0", "2-1196228-6"
106935-000	"1-1190781-1", "222A111-25-00/86-0"
863003-000	"201A241-3-0", "5-1196721-4"
814511-000	"222A121-3-0", "7-1196342-0"
823829-000	"382A046-3/42-0", "3-1196434-8"
297544-001	"3-1200275-5", "T150-300FR-CS-2065"
808342-000	"222A021-3-0", "7-1196273-1"
979579-000	"202D211-3-63/42-0", "8-1197566-4"
852013-000	"222A121-15-CS-2067-0", "4-1196642-6"
117395-000	"8-1190854-4", "362A014-3-0-CS6634"
806541-000	"202D221-4-32-0", "3-1196238-5"
398956-001	"4-1192991-7", "CES-2A-T1"
808312-000	"202A132-3-00-0", "9-1196272-2"
808472-000	"222D932-4-00-0", "7-1196275-3"
809133-000	"202D242-3/42-0", "9-1196286-8"
823258-000	"342A112-3-0", "2-1196424-7"
294113-000	"202D953-25-08-0", "5-1192228-8"
494367-000	"202A153-15-CS-2067-0", "1-1193697-8"
807033-000	"202A185-3-00-0", "7-1196249-0"
936829-000	"462A011-3/86-0", "6-1197257-0"
634309-000	"382A034-3/86-0", "1195017-3"
808272-000	"222D242-3-22-0", "9-1196271-3"
840929-000	"101A021-3-CS-2060-0", "8-1196560-0"
E84696-001	"8-1201236-0", "CES-2-D1"
814728N004	"202A142-3/42-0", "1196347-7"
232120-001	"2-1200084-7", "CES-1-CS-2067"
407125-001	"5-1193071-7"
CX4849-000	
808286N001	"222D242-3-0-CS5429", "3-1196272-4"
147681-000	"3-1191067-4", "214A342-3-02/42-0"
813355-000	"202D121-3-0", "9-1196327-3"
531095-000	"234A642-3-03/42-0", "9-1194170-7"
C47645-001	"4-1201147-0", "CES-1R"

Product Affected	Alias Part Number
823765-000	"382A023-3-0", "8-1196432-5"
808150-000	"202A153-3-00-0", "6-1196269-8"
879029-000	"200W542-3-0", "9-1196842-0"
822749-000	"223K013-3-0", "9-1196417-5"
662435-000	"101A021-3/86-0", "6-1195221-7"
572044-001	"5-1194539-9", "CES-4-F1"
683729-000	"202A121-3-0-CS8341", "5-1197864-0"
147733-000	"7-1191067-4", "222D152-3-60-0-CS5078"
823482-000	"382A012-3-00-0", "1196428-5"
370839-000	"234A021-3/86-0", "1192778-1"
843039-000	"101A021-3-0", "2-1196576-6"
C13226-001	"4-1201715-9", "F3-9FR"
807480-000	"204A011-3/42-0", "1-1196257-5"
814756-000	"202B553-3-0", "7-1196347-8"
715783-000	"222K121-25-00/225-0", "8-1195600-3"
814103-000	"222B123-3-0", "6-1196335-2"
704450-000	"400W242-3-0", "8-1199176-9"
422488-000	"227W245-3-01/42-0", "7-1193181-1"
CS3647-000	"CES-2-F1A"
820729-000	"8-1196399-6", "222K152-3/42-0"
808506-000	"202D232-3-0", "7-1196276-1"
808910-000	"214A021-3/42-0", "3-1196283-3"
823644-000	"462A023-3/42-0", "2-1196430-4"
726355-000	"222A152-3-CS-2060-0", "6-1195676-3"
823231-000	"322A434-3-0", "5-1196423-0"
154665-000	"1191117-5", "202K142-3-01/86-0"
806541N001	"202D221-4-32-0-CS5463", "3-1196238-7"
582853-000	"382A034-15-CS-2067-0", "1-1194617-7"
823774-000	"462A023-3-0", "1-1196433-8"
CC2688-000	"202K163-3-0-CS1858"
808057-000	"222A032-3-0", "9-1196267-1"
807478-000	"202D153-3-07/42-0", "1-1196257-0"
834499-000	"202K121-15/86-0", "2-1196515-0"
419820-000	"202K132-3/86-0", "7-1193162-4"
412803-000	"101A052-3/86-0", "9-1193112-6"
814557-000	"208A042-3-0", "7-1196343-3"
659473-000	"214A042-3/86-0", "7-1195198-0"
614352N002	"222D232-3-61-0-CS5078", "5-1194856-5"
808282-000	"202D963-3-0", "1196272-8"
879263-000	"222K142-25-00-0", "9-1196844-1"

Product Affected	Alias Part Number
814510-000	"203A021-3-0", "6-1196342-5"
896345-000	"101A041-3/86-0", "2-1196969-8"
879489-000	"222K185-25-00-0", "3-1196847-1"
822536-000	"222K163-3-00-0", "8-1196414-9"
814931-000	"267K113-3-0", "9-1196349-3"
808286-000	"222D242-3-0", "2-1196272-9"
428495-001	"6-1193223-2", "T-400FR"
813007-000	"202B596-3-0", "1196325-5"
813909N003	"222A132-3-0-CS5059", "1-1196333-3"
814536-000	"234A711-3-0", "3-1196343-8"
843194-000	"101A083-3/42-0", "6-1196577-2"
808981-000	"202D121-3/42-0", "7-1196284-7"
809101-000	"222D242-3/42-0", "2-1196286-9"
878129-000	"207W256-3-01/42-0", "3-1196833-5"
814730-000	"202A185-3/42-0", "1-1196347-4"
823645-000	"301A034-3/42-0", "2-1196430-9"
276339-000	"6-1192046-3", "342A124-3-G02-0"
823758-000	"322A112-3-0", "5-1196432-3"
808735-000	"6-1196280-9", "243A012-3-0"
823605-000	"342A012-3-00-0", "5-1196429-7"
CW6364-000	
494023-000	"222D211-3/42-0", "9-1193694-7"
587109-000	"202K174-3-02/86-0", "8-1194646-6"
809124N002	"202D211-3-22/42-0-CS8244", "7-1196286-2"
823772-000	"562A022-3-0", "1-1196433-1"
878400-000	"342A112-3/42-0", "3-1196836-9"
F87032-002	"7-1201828-2", "8S23-75FR"
806542-000	"202D242-4-32-0", "3-1196238-9"
814463N003	"222D174-3-0", "1196342-2"
009235-000	"7-1190071-5", "462A011-15-CS-2067-0"
813938-000	"202A053-3-0", "2-1196333-9"
806548-000	"222D242-4-32-0", "5-1196238-7"
021915-000	"8-1190169-0", "202A132-15-CS-2067-0"
808008-000	"222D152-3-0", "7-1196266-7"
878081-000	"202K132-3/42-0", "9-1196831-7"
814472-000	"234A621-3-0", "1196342-9"
CW2696-000	
806572-000	"208A053-3-08-0", "1196239-8"
953247-000	"202K174-15-01/86-0", "5-1197381-2"
806544-000	"202D274-4-32-0", "4-1196238-8"

Product Affected	Alias Part Number
969358-000	"242W042-3-0", "2-1199157-3"
843032-000	"101A041-3-0", "6-1197930-7", "45101A0413-M"
764811-000	"222D142-3/86-0", "1-1195954-9"
C89841-000	"9-1201382-9", "322A412-100-00/180-0"
808285-000	"222D232-3-0", "2-1196272-2"
409534-001	"1-1193089-7", "CES-1"
382655N002	"283A100-25-01-0-CS6184", "4-1192866-4"
189631-000	"8-1191375-8", "202D142-3/86-0"
808621-000	"222A052-3-0", "5-1196278-5"
823313-000	"342A048-3/42-0", "6-1196425-7"
A00123-001	"9-1200275-2", "F133-200FR-CS-2065"
F23390-000	"234A032-3-CS-2065-0", "8-1200755-4"
823489-000	"101A062-3/86-0", "2-1196428-1"
813848-000	"202A132-3-0", "5-1196332-0"
052833-000	"6-1190403-9", "222A142-3-0-CS5501"
CL2921-000	"222D121-3/42-0-CS8607"
602513-000	"462A023-3/86-0", "3-1194769-1"
604252-000	"202D242-4-00/42-0", "4-1194781-9"
965773-000	"202K153-25-00/225-0", "9-1197468-3"
806644-000	"202D253-3-61/42-0", "2-1196240-8"
568767-000	"322A158-3/86-0", "3-1194516-1"
823665-000	"362A024-3/42-0", "5-1196430-3"
203579N001	"202D121-3-60/42-0-CS5077", "8-1191475-6"
806649-000	"234A021-3/42-0", "4-1196240-1"
CH5298-000	"8-1899666-7", "PP000009"
807806N001	"222D121-3-60/42-0-CS5078", "5-1196263-1"
749093-000	"342A034-3-0-CS5666", "8-1195842-0"
823339-000	"301A034-3-0", "1-1196426-4"
901307-000	"234A752-3-02/42-0", "6-1197005-7"
486053-000	"228A075-3-03-0", "4-1193637-4"
809138-000	"202D121-3-60/42-0", "1196287-7"
823261-000	"342A215-3-0", "3-1196424-7"
809134-000	"202D253-3/42-0", "1196287-2"
806550-000	"222D274-4-32-0", "6-1196238-7"
814094-000	"202D174-3-0", "5-1196335-3"
195702-001	"2-1191419-5", "T3-9FR"
A50759-001	"1-1201719-7", "CES-2R"
EP5208-000	
EM7588-000	"R85049/141-04AC"
813202-000	"222A021-3-00-0", "7-1196326-7"

Product Affected	Alias Part Number
879459-000	"202K153-25-00-0", "1196847-2"
814457-000	"208A053-3-0", "8-1196341-8"
CL9429-000	"CES-5-T4"
814493-000	"234A021-3-0", "3-1196342-4"
895514-000	"222K132-25-00-0", "5-1196963-3"
349875-000	"202K153-100-00/180-0", "2-1192632-8"
823231N002	"322A434-3-0-CS5425", "5-1196423-3"
879132-000	"200W562-3-0", "9-1196843-2"
CX0406-000	"202K142-3-CS-1821-0"
CZ8629-000	"243D012-3-G04/86-0"
823233-000	"382A046-3-0", "6-1196423-0"
806550N001	"222D274-4-32-0-CS5460", "6-1196238-9"
823509-000	"462A023-3-00-0", "5-1196428-0"
807990-000	"222D921-4-00-0", "3-1196266-7"
004241-000	"4-1190032-2", "362A014-3/86-0"
813788-000	"1196332-6", "202A142-3-0"
808036-000	"234A142-3-0", "4-1196267-3"
EG9746-000	"243D022-3-G04/86-0"
879028-000	"200W531-3-0", "8-1196842-8"
808949-000	"202D211-3-0", "1196284-3"
823782-000	"462A046-3-0", "5-1196433-1"
813681-000	"208A086-3-0", "7-1196330-8"
814728-000	"202A142-3/42-0", "1196347-4"
113417-000	"3-1190827-2", "222A163-3-CS-2060-0"
808980-000	"202D132-3/42-0", "7-1196284-3"
813434-000	"222A152-3-0", "7-1196328-6"
629224-000	"8-1200836-1", "CES-2A-D1"
EM4253-000	"242W042-3-G01-0"
809218-000	"222D232-4-32-0", "5-1196288-0"
688849-001	"1-1195410-9", "CES-2A100"
808059-000	"208A011-3-0", "9-1196267-6"
809220-000	"222D263-4-32-0", "5-1196288-8"
488851N001	"202K121-3-0-CS1858"
814310-000	"234A121-3-0", "2-1196338-1"
617652-000	"202D932-3/86-0", "9-1194880-9"
812861-000	"202K232-3-0", "9-1196323-9"
158229-000	"1191143-9", "202A163-3/86-0"
823340N002	"382A012-3/42-0", "2-1196426-3"
595431-000	"202A142-3/86-0", "7-1194708-6"
767839-000	"202D211-25-00/86-0", "6-1195983-8"

Product Affected	Alias Part Number
296519N002	"202D153-3-60-0-CS5077", "3-1192246-5"
822763-000	"202K163-3-02-0", "1196418-6"
808947-000	"214A521-3/42-0", "9-1196283-8"
823726-000	"342A112-3-03-0", "6-1196431-2"
F27196-000	"342A012-3-CS-1821-0", "9-1200780-3"
330355-000	"234A121-3/86-0", "3-1192496-2"
972137-000	"234A111-3/42-0", "2-1197514-0"
154183N001	"8-1191113-6", "202A312-3-12/42-0-CS6687"
293826-000	"202A132-3/86-0", "7-1192226-7"
151661-000	"2-1191096-6", "202A163-15-0"
823355-000	"382A034-3/42-0", "5-1196426-9"
CN8836-000	"CES-5-F4"
843031-000	"101A011-3-0", "1196576-4"
807006-000	"222A121-3-00-0", "9-1196248-1"
823646-000	"462A011-3/42-0", "3-1196430-4"
913883-000	"101A041-3-CS-2060-0", "8-1197095-3"
297241-000	"222A163-3/86-0", "2-1192251-6"
806352-000	"202D163-3-60-0", "9-1196234-9"
E10434-001	"6-1201681-6", "D50-100FR"
140855-000	"2-1191021-0", "202A132-3-CS-2060-0"
571791-000	"207W223-3-01/86-0", "2-1194534-8"
806995-000	"202D121-3/86-0", "7-1196248-7"
668634-000	"202W302-130-CS-2065-0", "1-1197988-2"
500665-000	"202K174-15/86-0", "2-1193743-8"
823807-000	"342A024-3/42-0", "8-1196433-8"
580068-001	"2-1194597-9", "CES-3-T1"
889407-000	"202A153-3-CS-2060-0", "4-1196919-9"
453519-000	"202K185-25-21-0", "8-1193404-3"
809061N001	"202D121-3-60-0-CS5503", "6-1196285-0"
D49398-000	"9-1201557-1", "382A023-3-CS-1821-0"
822570-000	"202K153-3-00-0", "8-1196415-5"
174617-000	"9-1191269-2", "322A134-3/86-0"
814910-000	"267K023-3-0", "7-1196349-0"
820017-000	"342A034-3/42-0", "1196390-7"
808119-000	"228A032-3-0", "1196269-2"
814732-000	"222A185-3/42-0", "2-1196347-4"
821895-000	"214A352-3-02/42-0", "8-1196409-6"
878128-000	"207W245-3-01/42-0", "3-1196833-0"
707290-000	"382A012-25-00-0", "5-1195544-9"
810155-000	"222K142-3/86-0", "8-1196295-8"

Product Affected	Alias Part Number
488305-000	"202A121-3/86-0", "8-1193653-5"
875269-000	"202A142-15-CS-2067-0", "8-1196808-3"
814443N002	"204A011-3-0", "4-1196341-7"
806547-000	"222D221-4-32-0", "5-1196238-3"
522046-000	"342A024-3/86-0", "6-1194102-6"
758611-000	"202D232-3-08/86-0", "7-1195910-7"
808502-000	"202D253-3-22-0", "5-1196276-3"
805947-000	"222K132-3/86-0", "2-1196229-8"
899052-000	"204A711-3-0", "1196988-7"
029595-000	"4-1190229-2", "202A132-3-0-CS5086"
809079-000	"202D174-3-10/42-0", "7-1196285-9"
808836-000	"202D174-3/42-0", "1-1196282-1"
CM0413-000	"CES-2-T1B"
733950-000	"202D253-3/86-0", "1-1195732-2"
814309-000	"222A111-3-0", "1-1196338-6"
945459-000	"222K152-15/86-0", "3-1197317-2"
809235-000	"202D174-3-60/42-0", "9-1196288-2"
808203-000	"202D121-3-37-0", "6-1196270-7"
470862-000	"301A022-3-07-0", "1-1193528-8"
843056-000	"101A073-3-0", "5-1196576-0"
114225-000	"101A083-3-G01-0", "8-1190832-2"
814715-000	"222A121-3/42-0", "5-1196346-6"
808012-000	"202D142-3-0", "8-1196266-8"
814611-000	"234A152-3-0", "7-1196344-4"
808669-000	"222A224-3-0", "5-1196279-7"
014946-000	"3-1190117-4", "202A174-4-00/42-0"
813856-000	"222A163-3-0", "7-1196332-1"
823496-000	"301A011-3-00-0", "3-1196428-2"
827807N002	"202D221-3-61-0-CS5077", "1196465-8"
A06179-000	"9-1201250-6", "202K121-3-CS-2068-0"
843052-000	"101A052-3-0", "4-1196576-3"
431837-000	"214A342-3/86-0", "7-1193247-2"
814720-000	"222A174-3/42-0", "7-1196346-7"
510141-000	"222A111-3/86-0", "1194010-7"
448321-000	"202K153-15/86-0", "7-1193368-3"
819810-001	"7-1200274-1", "CES-3-CS-2065"
853248-000	"220A012-3-0", "1-1196651-9"
808513N001	"202D221-3-0", "1196277-1"
C35565-000	"101A052-3/42-0-CS8194", "1199908-3"
833081-000	"203A312-3-0", "6-1196504-6"

Product Affected	Alias Part Number
A92645-000	"214A021-3-CS-2065-0", "1-1200756-2"
812827-000	"202K185-3-0", "2-1196323-7"
822799-000	"202K232-3-01-0", "3-1196418-6"
040291-000	"2-1190308-8", "222A052-3-0-CS6634"
967279-001	"3-1197479-4", "CES-2"
CL2830-000	"CES-4-A150"
650388-000	"202W263-3-0", "2-1195136-0"
813030-000	"222A245-3-0", "2-1196325-8"
814172-000	"214A311-3-00-0", "5-1196336-0"
806068-000	"202D185-3-00-0", "4-1196230-3"
CV7312-000	"101A041-3-0-CS5414"
310059-000	"101A094-3-CS-2060-0", "6-1192347-2"
878100-000	"207W213-3-0", "2-1196832-6"
843053-000	"101A052-3/42-0", "4-1196576-7"
D15798-001	"7-1201784-9", "D3-9FR"
249315N001	"202D211-3/180-0", "3-1191828-5"
806374N002	"202D132-3-60-0-CS5503", "5-1196235-0"
807059-000	"242A312-3-0", "3-1196250-0"
215287-000	"203W112-3-0", "9-1191554-6"
808786-000	"228A064-3-0", "3-1196281-9"
808905-000	"222D142-3/42-0", "1-1196283-9"
807014-000	"222D211-3-22-0", "1-1196249-2"
313123-000	"214A332-3/86-0", "7-1192368-1"
483979-001	"9-1193621-9", "SSB-1202FR/NM"
609473-000	"6-1194819-1"
814697-000	"234A642-3-0", "1-1196346-5"
814299-000	"214A332-3-0", "8-1196337-2"
309636-000	"9-1192344-4", "502A823-3/42-0"
612614-000	"222D921-3/86-0", "3-1194843-8"
806828-000	"234A011-3/42-0", "5-1196245-1"
D32325-000	"1-1200892-4", "T500-600FR"
697689-000	"202A333-3-0-CS5847", "8-1195475-5"
245376-000	"214A352-3/86-0", "1-1191800-7"
823781-000	"562A067-3-0", "4-1196433-6"
037328-001	"4-1190288-3", "SSB-1202FR"
808501-000	"202D232-3-22-0", "4-1196276-8"
575934-000	"202D921-3/86-0", "1-1194570-8"
812996-000	"202K142-3-0", "8-1196324-3"
814336-000	"202A142-3-04-0", "8-1196338-0"
823211-005	"301A011-3-CS-2068-0", "1196423-6"

Product Affected	Alias Part Number
156266-000	"8-1191128-6", "243D022-3-G04-0"
814723-000	"234A042-3-0", "8-1196346-8"
844745-000	"227W256-3-01/42-0", "3-1196590-7"
823667-000	"301A022-3/42-0", "5-1196430-7"
820068-000	"562A032-3/42-0", "2-1196391-7"
CR9782-000	"203W301-3/42-0"
814353-000	"222A142-3-0", "3-1196339-4"
952677-000	"222D921-25-00-0", "2-1197377-0"
822519-000	"202K142-3-01-0", "5-1196414-7"
015189-000	"2-1190119-1", "202K132-3-01/42-0"
419396-000	"202A111-3/86-0", "7-1193159-2"
808761-000	"202D921-3/42-0", "1-1196281-0"
586375-000	"234A742-3-02/42-0", "6-1194641-9"
814798-000	"202A121-3-00-0", "3-1196348-1"
807030-000	"202D153-3-00-0", "6-1196249-3"
CS8860-000	
807025-000	"202D221-3-22-0", "4-1196249-0"
935473-001	"3-1197248-7", "CES-3A-D2"
733447-000	"214A321-3/86-0", "6-1195728-8"
808046-000	"228A042-3-0", "6-1196267-6"
808016-000	"222D142-3-0", "1196267-6"
807614-000	"202D953-3/42-0", "6-1196259-5"
843921-000	"202K174-3-0", "9-1196583-5"
CM8723-000	"243D012-3/86-0", "7-1899443-8"
412167-000	"202D221-3/86-0", "7-1193108-3"
808950-000	"202D285-3-0", "1196284-8"
257897-000	"202D232-3/180-0", "9-1191886-7"
879067-000	"2-1196843-4", "462W023-3-0"
CH5292-000	"8-1899666-1", "PP000003"
820785N003	"202D142-3-60-0-CS5077", "8-1196400-3"
809061-000	"202D121-3-60-0", "5-1196285-5"
447937-000	"202A185-3/86-0", "8-1193365-3"
480029-000	"222D152-3/86-0", "6-1193593-0"
814486-000	"208A032-3-0", "2-1196342-6"
814678-000	"8-1196345-3", "403A134-3-0"
315163-000	"202A121-3-CS-2060-0", "8-1192384-3"
808311-000	"202A142-3-00-0", "8-1196272-7"
D24840-000	"CES-4S", "1-1200792-7"
806129-000	"222D132-3/42-0", "5-1196231-7"
823255-000	"322A123-3-0", "1-1196424-8"

Product Affected	Alias Part Number
CP5629-000	"222D921-3-27/42-0"
806549-000	"222D253-4-32-0", "6-1196238-3"
589883-000	"202D932-25-G11-0", "1-1194667-3"
878939-000	"202K163-3-01/42-0", "2-1196842-6"
814597-000	"222A163-3-00-0", "4-1196344-5"
721041-001	"5-1195638-7", "CES-2-A75"
814591-000	"202D185-3/42-0", "3-1196344-1"
812049-000	"202D132-3-00-0", "1196317-5"
843192-000	"101A094-3/42-0", "5-1196577-7"
823356-000	"362A114-3-0", "6-1196426-4"
CM0414-000	"CES-2-F1"
664815-001	"5-1195238-9", "CES-3-F1"
215669-000	"202D285-3/86-0", "8-1191557-3"
245582-001	"7-1191801-3", "T42-100FR"
823040-000	"6-1196420-5", "562A011-3-00-0"
814439-000	"214A021-3-0", "3-1196341-2"
814449-000	"222A185-3-0", "6-1196341-9"
823783-000	"462A034-3-0", "5-1196433-6"
808148-000	"222D132-3-0", "5-1196269-9"
575133-001	"6-1194564-3", "CES-3A-T2"
807988-000	"202D921-4-00-0", "2-1196266-8"
878092-000	"207W234-3/42-0", "2-1196832-1"
049611-000	"1-1190380-2", "234A632-3-03/42-0"
215664-000	"7-1191557-5", "322A412-3/86-0"
140989-000	"1-1191022-3", "202K163-100-00/180-0"
907761-000	"202W302-130-0", "5-1197051-6"
753044-000	"562A011-3/86-0", "8-1195870-3"
820705-000	"202K163-3-G03-0", "4-1196399-0"
812846-000	"222K152-3-0", "7-1196323-8"
812842-000	"202K153-3-0", "6-1196323-1"
965411-000	"222A132-3-0-CS5501", "5-1197466-7"
531090-000	"342A012-3/86-0", "9-1194170-2"
666984-000	"234A111-25-00-0", "6-1195253-9"
900197-000	"5-1196997-5"
813337-000	"202B585-3-0", "6-1196327-7"
817896-000	"202D142-25-00/225-0", "3-1199380-5"
823963-000	"602A012-3-0", "4-1196435-2"
879501-000	"222K121-25-00-0", "5-1196847-1"
D13560-000	"202K153-3-CS-1821-0", "1-1200340-2"
812997-000	"202K121-3-0", "9-1196324-3", "42FLS202K121-3-M"

Product Affected	Alias Part Number
751843-001	"3-1195862-7", "CES-3A-F1"
CP3360-000	
260516-001	"1191906-7", "F42-60-FR"
822596-000	"202K142-3/42-0", "2-1196416-7"
CC4330-000	"CES-4R"
814716-000	"222A132-3/42-0", "5-1196346-9"
923793-000	"234A721-3-02/42-0", "5-1197166-5"
808489-000	"202D242-3-0", "2-1196276-2"
823243-000	"322A123-3/42-0", "9-1196423-0"
642257-000	"234A132-25-00-0", "8-1195075-1"
CA0230-000	"422A813-3-04/42-0"
F11809-000	"204A011-3-04/42-0", "4-1200506-4"
017547-000	"9-1190136-8", "205W061-3-0"
823201-000	"362A024-3-0", "7-1196422-9"
404917-000	"301A022-3/180-0", "1193056-2"
808392-000	"222A132-3-00-0", "4-1196274-9"
074117-000	"7-1190554-1", "222D242-3-22/86-0"
807097-000	"203A021-3/42-0", "1-1196251-6"
820034N001	"202D142-3-60/42-0-CS5077", "3-1196390-9"
853272-000	"205A123-3/42-0", "5-1196651-5"
823763-000	"381A115-3-0", "8-1196432-0"
231503-000	"202D921-25-G11-0", "7-1191700-1"
806485-000	"222D121-3/42-0", "4-1196237-7"
843927-000	"202K174-3-02-0", "1196584-9"
199135-000	"6-1191442-0", "382A012-15-0"
436933-000	"2-1193284-7", "462A046-3/86-0"
027138-000	"1-1190210-6", "214A311-3-02/42-0"
808013-000	"202D153-3-0", "9-1196266-3"
808940-000	"204A121-3-01-0", "7-1196283-9"
969371-000	"222D932-25-G11-0", "4-1197494-8"
517053-000	"202A121-15-CS-2067-0", "9-1194059-4"
812836-000	"222K121-3-0", "4-1196323-1"
808097-000	"234A611-3-0", "6-1196268-6"
878121-000	"207W223-3-01-0", "9-1196832-3"
820016-000	"381A015-3/42-0", "1196390-3"
715055-000	"202K132-3-01/86-0", "8-1195595-2"
036641-000	"1190283-2", "202A212-3/86-0"
808252-000	"222A152-3-00-0", "5-1196271-6"
856497-001	"7-1196675-0", "CES-3A-T1"
CX0405-000	"202D921-3-CS-1821-0"

Product Affected	Alias Part Number
412014-001	"3-1193107-5", "CES-3-A100"
808834-000	"202D153-3/42-0", "1196282-1"
C05170-000	"7-1201164-2", "101A041-3-CS-2068-0"
806980-000	"222D132-4-00-0", "5-1196248-5"
898768-000	"202K163-25-00-0", "1-1196986-3"
808037-000	"214A511-3-0", "4-1196267-8"
814717N003	"222A142-3/42-0", "6-1196346-6"
823962-000	"342A034-3-0", "3-1196435-6"
808205-000	"202D142-3-37-0", "7-1196270-5"
A12822-000	"202K111-3/42-0", "8-1200812-0"
675496-000	"202W321-130-0", "4-1198240-6"
843223-000	"101A011-3/42-0", "8-1196577-9"
814300-000	"202A174-3-0", "8-1196337-7"
527321-000	"400W242-130/86-0", "2-1194143-6"
139835-000	"1191014-6", "222K174-15/86-0"
C49185-000	"2-1201251-1", "202K132-3-CS-2068-0"
843338-000	"101A041-3/42-0", "6-1197930-8"
814550-000	"522A013-3-0", "5-1196343-5"
808129-000	"222D163-3-0", "1-1196269-5"
345975-000	"101A031-3/86-0", "5-1192604-0"
809285-000	"202D211-3/86-0", "4-1196289-5"
599703-000	"102A962-3/42-0", "1194741-3"
814717-000	"222A142-3/42-0", "6-1196346-3"
814515-000	"214A352-3-0", "8-1196342-1"
990827-000	"243A022-3-G02-0", "5-1197661-9"
822840-000	"222K132-3-0", "6-1196418-5"
663825N002	"202D121-3-60-0-CS5077", "6-1195231-2"
823964-000	"342A024-3-0", "4-1196435-6"
808030-000	"202D132-3-0", "3-1196267-3"
806543-000	"202D263-4-32-0", "4-1196238-4"
807258-000	"202D211-3/42-0", "4-1196253-2"
808222-000	"208A064-3-0", "9-1196270-9"
090289-000	"9-1190661-9", "101A052-3-CS-2060-0"
EM1414-000	
806931-000	"202D253-3-21-0", "8-1196247-7"
966325-000	"202K232-3/42-0", "4-1197472-3"
991496-000	"2-1199152-8", "QFT2-130/42-0"
853293-000	"205A112-3/42-0", "9-1196651-3"
843190-000	"102A832-3/42-0", "5-1196577-0"
879228-000	"202K142-25-00-0", "5-1196844-0"

Product Affected	Alias Part Number
F87032N001	"8S23-75FR-CS8184", "1-1201068-2"
047897-000	"9-1190367-8", "234A611-3-03/42-0"
353567N001	"222D285-3/86-0", "4-1192655-5"
814086-000	"202D185-3-0", "3-1196335-2"
843222N005	"1-1200787-7"
808396-000	"222D211-3-0", "6-1196274-3"
822739-001	"7-1196417-8", "CES-2A-T2"
807197N001	"220A012-3/42-0", "5-1196252-8"
822574-000	"202K163-3-01-0", "9-1196415-2"
814744-000	"228A021-3-0", "4-1196347-9"
CN9349-000	
040571-000	"3-1190310-3", "202D211-100-00/180-0"
808102-000	"222D932-3-0", "8-1196268-2"
916901-000	"202K163-3/180-0", "3-1197117-4"
538618-000	"202A153-3/86-0", "1-1194227-0"
808101-000	"222D185-3-0", "7-1196268-7"
CC3674-000	"234A142-3-00-0"
843222-000	"101A021-3/42-0", "8-1196577-4"
D72571-000	"4-1201251-1", "222K121-3-CS-2068-0"
234849-000	"3-1191725-4", "322A412-3-CS-2068-0"
422691-000	"222D263-3-03/86-0", "1-1193183-3"
814711-000	"202A121-3/42-0", "3-1196346-6"
204473-000	"202K163-25-00/225-0", "1191482-6"
273590-000	"202K174-3/86-0", "5-1192026-5"
808162-000	"234B111-3-0", "8-1196269-8"
520413-000	"322A112-3-G01-0", "1194091-1"
808065-000	"214A052-3-0", "1196268-1"
807988N001	"202D921-4-00-0-CS5428", "3-1196266-0"
809095N001	"222D142-3-60-0-CS5078", "1-1196286-9"
879030-000	"200W552-3-0", "9-1196842-2"
044391-000	"3-1190341-3", "222K163-15/86-0"
823943-000	"342W012-3-0", "1-1196435-7"
298088-000	"2-1199151-6", "QFT1-130/42-0"
CR5600-000	"214A042-3-0-CS2988"
823757-000	"342A012-3-0", "4-1196432-8"
809218N001	"222D232-4-32-0-CS5460", "5-1196288-2"
182363-000	"1-1191325-3", "202A163-3-CS-2060-0"
968605-000	"222D921-3/42-0", "6-1197488-9"
474383-000	"101A073-3/86-0", "9-1193553-8"
808503-000	"202D263-3-22-0", "5-1196276-8"

Product Affected	Alias Part Number
814409-000	"214A011-3-0", "8-1196340-1"
131277-000	"4-1190954-7", "562A022-3/86-0"
570159-000	"202A142-3-CS-2060-0", "6-1194519-6"
813206-000	"222A074-3-00-0", "8-1196326-3"
807991-000	"222D963-4-00-0", "4-1196266-1"
823009-000	"342A024-4-00-0", "1-1196420-0"
806132-000	"202D185-4-03-0", "6-1196231-3"
358028-000	"9-1192685-8", "382A023-3/86-0"
808332-000	"222D953-3-0", "5-1196273-0"
820216-000	"462A046-3-06/42-0", "8-1196394-5"
822841-000	"222K163-3-0", "7-1196418-6"
094698N002	"1190694-3", "227W213-3-A10-0-CS5697"
822522-000	"202K132-3-01-0", "7-1196414-7"
808511-000	"202A042-3-00-0", "8-1196276-9"
814916-000	"207K113-3-0", "8-1196349-2"
806531-000	"202D285-4-32-0", "1-1196238-5"
EP5209-000	
CA5765-000	"CES-4-D3"
813090-000	"242A142-3-00-0", "7-1196325-3"
823662-000	"382A012-3-04/42-0", "5-1196430-0"
822322-000	"222K174-3-00-0", "1196413-7"
CS2469-000	"T3-9FR-01"
060151-000	"1-1190456-5", "202K142-15/86-0"
822283-000	"204K012-3-0", "7-1196412-4"
813945-000	"222A313-3-0", "3-1196333-7"
814741-000	"228A053-3-0", "3-1196347-9"
808952-000	"202D196-3-0", "1-1196284-4"
814749-000	"234A132-3-0", "5-1196347-9"
296277-000	"222D921-3-02/86-0", "4-1192244-1"
CC4331-000	"CES-3R"
812860-000	"202K163-3-0", "9-1196323-1"
820941-000	"202K121-3-01/42-0", "1-1196402-4"
CM4994-000	"202K121-25-G39-CS-2100-0", "1899419-3"
EJ2403-000	"202K111-3/86-0"
813752N002	"243A022-3-02-0-CS5501", "3-1196331-6"
806542N001	"202D242-4-32-0-CS5463", "4-1196238-2"
F07461-000	"7-1201878-2", "101A083-3/86-0"
730488-000	"202D921-25-00-0", "6-1195706-9"
098921-000	"9-1190724-7", "222A174-3-0-CS5501"
912229-001	"3-1197084-1", "CES-3"

Product Affected	Alias Part Number
744945-001	"1195811-5", "CES-5"
808415-000	"228A032-3-00-0", "9-1196274-4"
738430-000	"202K163-3/86-0", "5-1195764-4"
822747-000	"222K174-3-0", "8-1196417-6"
167194-000	"4-1191217-8", "202K121-3/86-0"
CM9145-000	"243D012-3/42-0", "5-1899446-7"
806551-000	"222D285-4-32-0", "7-1196238-1"
EK2882-000	"222K163-3-CS-2068-0"
878125-000	"207W213-3-01/42-0", "1-1196833-6"
965357-000	"203A021-3/42-0-CS8290", "2-1197466-2"
821718-000	"202D153-3-02/42-0", "6-1196408-1"
823244-000	"322A134-3/42-0", "9-1196423-4"
853254-000	"205A134-3/42-0", "3-1196651-2"
652949-001	"6-1195153-4", "CES-1A50"
502945-000	"202K153-3-01/86-0", "7-1193785-8"
552552-000	"222D132-3/86-0", "3-1194367-8"
290207-000	"202K132-25-00/225-0", "4-1192200-2"
128309-000	"3-1190932-4", "202D274-3/86-0"
C17968-000	"1-1201251-7", "202K132-3-01-CS-2068-0"
609347-000	"222A163-3-0-CS5501", "6-1194818-8"
878118-000	"207W245-3/42-0", "7-1196832-8"
814179-000	"214A332-3-00-0", "5-1196336-6"
193578-001	"6-1191404-6", "T14-23FR"
833222-000	"602A012-3/42-0", "9-1196505-6"
823265-000	"562A054-3/42-0", "4-1196424-6"
417597N002	"202D132-3-60-0-CS5077", "5-1193146-0"
CC2691-000	"101A062-3-14-0"
251213-000	"202D232-3-21-0", "1-1191841-7"
268769-000	"222A255-3-01/42-0", "7-1191983-8"
009751-000	"6-1190075-8", "202K132-3-CS-1821-0"
807071-000	"202D232-3/42-0", "4-1196250-7"
808284-000	"222D221-3-0", "1-1196272-6"
878120-000	"207W213-3-01-0", "8-1196832-7"
C21703N001	"7-1201572-9", "101A041-3-06-0-CS5504"
813765-000	"202A163-3-00-0", "5-1196331-4"
682065-000	"214A321-3-02/42-0", "4-1195361-6"
814498-000	"204A511-3-0", "4-1196342-6"
957073-000	"202A264-3/42-0", "2-1197409-3"
564368-000	"202D153-3/86-0", "1-1194458-0"
808200-000	"222A111-3-00-0", "5-1196270-8"

Product Affected	Alias Part Number
808266-000	"202A174-3-00-0", "8-1196271-0"
822306-000	"202A163-3-K03-0", "9-1196412-0"
791073-000	"3-1196127-3"
D24909-000	"214A032-3-CS-2065-0", "2-1200756-3"
823762-000	"381A015-3-0", "7-1196432-5"
808405-000	"202D921-3-0", "7-1196274-5"
EJ1925-000	"202D142-3-0-CS4119"
807989-000	"202D932-4-00-0", "3-1196266-2"
834240-000	"222D253-3/86-0", "3-1196513-4"
806096-000	"214A311-3/42-0", "1196231-8"
823435-000	"462A060-3-0", "3-1196427-7"
808394-000	"222D953-4-00-0", "5-1196274-8"
013206-000	"7-1198069-1", "QFT3-130/42-0"
815363-000	"202A111-4-00-0", "5-1196354-7"
814415-000	"214A032-3-0", "8-1196340-8"
823635N003	"382A023-3/42-0", "9-1196429-9"
235705-000	"222D211-3-0-CS5429", "7-1191733-0"
CL9153-000	"222D242-3-21/42-0"
808204-000	"202D132-3-37-0", "7-1196270-1"
852331-000	"101A073-3-04-0", "5-1196644-2"
813597-000	"202D163-3-0", "1196330-3"
823363-000	"322A514-3-0", "8-1196426-0"
666605-001	"2-1195251-2", "T150-300FR"
813353-000	"208A021-3-0", "8-1196327-8"
CM8725-000	"264W012-3/86-0", "7-1899443-9"
111853-000	"5-1190816-4", "202K163-15/86-0"
724408-000	"202K132-3/180-0", "7-1195662-1"
807488-000	"204A511-3/42-0", "3-1196257-1"
946543-000	"101A031-3-CS-2060-0", "6-1197324-8"
813645-000	"5-1196330-4", "562A011-3-0"
373785-000	"6-1192799-8", "562A032-3/86-0"
CZ2912-000	"202K132-3/42-0CS2131"
820671-000	"222K132-3/42-0", "1-1196399-3"
878112-000	"207W223-3-0", "4-1196832-8"
806180-000	"214A011-3/42-0", "5-1196232-4"
460555-000	"382A012-130-0", "5-1193454-3"
878113-000	"207W234-3-0", "5-1196832-3"
879498-000	"202K121-25-00-0", "4-1196847-3"
814309N003	"222A111-3-0-CS5501", "1-1196338-9"
650533-001	"1195137-7", "SSB-2002FR"

Product Affected	Alias Part Number
806543N001	"202D263-4-32-0-CS5463", "4-1196238-6"
544121-000	"234A621-3-03/42-0", "2-1194268-4"
853346-000	"220A023-3/42-0", "6-1196652-1"
EP7411-000	
925536-000	"381A015-3-0-CS6634", "1199109-5"
807206-000	"222D152-3-00-0", "7-1196252-0"
823225-000	"301A022-3-0", "3-1196423-3"
911259-000	"234A011-25-00-0", "4-1197077-1"
878424-000	"462A011-3-G05-0", "6-1196836-6"
814610-000	"202A153-3-00/42-0", "7-1196344-0"
813789-000	"202A163-3-0", "1-1196332-4"
450122-001	"1193381-6", "CES-3-D1"
823756-000	"382A034-3-0", "4-1196432-1"
899117-000	"462A023-3-0-CS5453", "5-1196988-9"
812841-000	"202K132-3-0", "5-1196323-3"
811955-000	"222D132-3-60/42-0", "7-1196315-2"
339376-000	"3-1192561-8", "222K152-3/86-0"
D33548-000	"1201165-2", "101A031-3-CS-2068-0"
465098-001	"2-1193487-7", "CES-3A-D1"
814327-000	"462A011-3-0", "6-1196338-5"
814719-000	"222A163-3/42-0", "7-1196346-2"
094698-000	"1190694-1", "227W213-3-A10-0"
613924-001	"5-1194853-5", "CES-2A50"
823184-000	"382A023-3-00-0", "5-1196422-0"
814757-000	"202B574-3-0", "8-1196347-3"
843486-000	"101A031-3/42-0", "3-1196580-7"
807946-000	"202D932-3/42-0", "5-1196265-5"
823283-000	"322A423-3-0", "8-1196424-7"
590087-000	"214A332-3-02/42-0", "5-1194668-6"
061353-000	"3-1190464-5", "202K232-3/86-0"
814089-000	"222A174-3-0", "4-1196335-1"
823225-007	"301A022-3-CS-2068-0", "3-1196423-6"
822520-000	"6-1196414-3", "202K153-3-01-0"
620409-000	"202K142-25-11-0", "6-1194902-4"
500141-000	"222A132-3/86-0", "8-1193738-6"
254972-000	"234A111-3/86-0", "1197949-2"
879027-000	"200W521-3-0", "8-1196842-6"
511310-000	"382A012-3/42-CS-1821-0", "7-1200172-0"
813970-000	"202A021-3-0", "7-1196333-8"
019265-000	"3-1190150-9", "462A023-3-G08-0"

Product Affected	Alias Part Number
037190-000	"3-1190287-4", "202W285-3-0"
820691-000	"222K174-3/42-0", "3-1196399-4"
814447-000	"214A321-3-0", "5-1196341-9"
823604-000	"301A022-3-00-0", "5-1196429-2"
807549-000	"202A121-4-00-0", "4-1196258-2"
F71979-000	"1-1200398-3", "QFT1-130/42-CS-2065-0"
CX0409-000	
669074-000	"202K132-15/86-0", "2-1195268-2"
820655-000	"222W072-3-0", "8-1196398-8"
457931-000	"234A932-3-04/42-0", "1193436-8"
823178-000	"342A058-3-0", "4-1196422-2"
808287-000	"222D263-3-0", "3-1196272-6"
814458-000	"234A011-3-0", "9-1196341-3"
808167-000	"222D921-3-0", "1196270-3"
808953-000	"202A111-3-00-0", "1-1196284-8"
440998-001	"8-1200273-3", "SSB-1202FR-CS-2065"
E20878-000	"214A011-3-CS-2065-0", "3-1200756-9"
128665-000	"6-1190934-8", "227W223-3-01/42-0"
822051-000	"562A043-3/42-0", "1196411-3"
820706-000	"202K174-3-G03-0", "4-1196399-5"
791411-000	"234A011-3/180-0", "6-1196129-7"
431041-000	"222D932-3/42-0", "1193242-8"
843031N004	"101A011-3-0-CS5537", "1196576-7"
CW0478-000	
885113-000	"222A152-3-0-CS5501", "8-1196887-1"
809219N001	"202D253-4-32-0-CS5463", "5-1196288-6"
855688-000	"222K132-15/86-0", "7-1196669-4"
274243-000	"1192031-2", "243D012-3-G04-0"
848633-001	"7-1196617-9", "CES-4"
613927-000	"462A034-3-0-CS5453", "5-1194853-8"
511808-001	"9-1200273-2", "F42-60FR-CS-2065"
391133-000	"214A011-3/86-0", "1-1192936-1"
304850-000	"202K132-25-11-0", "5-1192308-4"
806997-000	"222A121-3/86-0", "8-1196248-3"
862779-000	"382A012-15-CS-2067-0", "1-1196720-0"
892428-001	"5-1200273-9", "T42-100FR-CS-2065"
813614-000	"208W012-3-0", "2-1196330-4"
899068-000	"002A011-3-0", "2-1196988-1"
808624-000	"202D221-3/42-0", "6-1196278-5"
814341-000	"234A032-3-0", "8-1196338-5"

Product Affected	Alias Part Number
591731-000	"301A022-3/86-0", "5-1194680-1"
CN9783-000	
809124-000	"202D211-3-22/42-0", "7-1196286-0"
241174-000	"202D953-3/86-0", "9-1191771-1"
810596-000	"382A012-3/86-0", "1-1196299-5"
808513-000	"202D221-3-0", "9-1196276-7"
823481-000	"302A024-3-0", "9-1196427-9"
557732N002	"2-1194399-7", "CES-4-T1-CS8365"
808490-000	"202D263-3-0", "2-1196276-7"
654258-001	"1-1195162-0", "CES-3-A150"
218753-000	"202K232-15/86-0", "1191614-2"
814713-000	"202A163-3/42-0", "4-1196346-6"
814589-000	"202D142-3/42-0", "2-1196344-7"
823227-000	"322A134-3-0", "4-1196423-4"
424281-000	"234A132-3/86-0", "5-1193194-6"
D45495-001	"9-1201696-5", "D14-30FR"
823326-000	"342A048-3-0", "9-1196425-4"
814712-000	"202A153-3/42-0", "4-1196346-1"
253127-000	"202K232-25-00-0", "2-1191852-2"
823823-000	"562A011-3/42-0", "1-1196434-7"
980683-000	"202K142-25-00/225-0", "2-1197578-4"
522807-000	"202K174-25-11-0", "9-1194107-5"
843193-000	"101A062-3/42-0", "6-1196577-0"
823363N004	"322A514-3-0-CS5425", "8-1196426-3"
EP5207-000	
843041-000	"101A073-3/42-0", "3-1196576-1"
806486-000	"222D211-4-32-0", "5-1196237-0"
820017N002	"342A034-3/42-0-CS8300", "1-1196390-0"
808292-000	"208A075-3-0", "5-1196272-8"
810028-000	"222K121-3/86-0", "8-1196294-9"
F13325-000	"202D196-3/86-0", "4-1201104-3"
CN1080-000	"CES-3R-A150"
798941-000	"202D232-3/86-0", "2-1196177-2"
808285N002	"222D232-3-0-CS5429", "2-1196272-7"
823170-000	"562A043-3-0", "3-1196422-1"
843031N002	"101A011-3-0-CS8723"
820028-000	"462A046-3/42-0", "2-1196390-7"
814448-000	"214A311-3-0", "6-1196341-4"
814731-000	"202A196-3/42-0", "1-1196347-9"
938983-000	"222A132-3-CS-2060-0", "1-1197274-1"

Product Affected	Alias Part Number
C80357-001	"5-1200275-1", "CES-4-CS-2065"
843036-000	"101A031-3-0", "1-1196576-5"
814596-000	"222A142-3-00-0", "4-1196344-0"
413171-000	"222A111-3-CS-2060-0", "3-1193115-2"
878123-000	"207W245-3-01-0", "1196833-6"
615970-001	"8-1194866-6", "F-23-FR"
812843-000	"222K142-3-0", "6-1196323-8"
703989-000	"202D242-25-00-0", "9-1195522-1"
823241-000	"562A032-3-0", "7-1196423-9"
648906-000	"234A032-3/42-0", "3-1195122-8"
224645N002	"202D163-3-60-0-CS5077", "8-1191654-7"
878122-000	"207W234-3-01-0", "9-1196832-9"
148468-000	"2-1191073-3", "462A034-3/86-0"
878126-000	"207W223-3-01/42-0", "2-1196833-0"
808507-000	"202D253-3-0", "7-1196276-6"
843223N004	"101A011-3/42-0-CS8194", "8-1200966-2"
808393-000	"202D953-4-00-0", "5-1196274-4"
260516N003	"F42-60-FR-CS8665"
482579N001	"202D142-3-02/42-0-CS5501", "1193612-7"
364815-000	"202K142-3-G04/180-0", "8-1192735-6"
CU2643-000	"202D142-3-35-0"
005121-000	"1-1190039-1", "234A711-3-02/42-0"
823364-000	"322A148-3-0", "8-1196426-5"
808835-000	"202D163-3/42-0", "1196282-6"
820665-000	"202K174-3/42-0", "9-1196398-5"
EG9804-000	"502A823-3/42-0-CS4112"
314612-000	"202D153-25-00/225-0", "6-1199369-2"
746504-001	"5-1200274-6", "T3-9FR-CS-2065"
843765-000	"202D263-3/86-0", "3-1196582-9"
094692-000	"9-1190693-4", "222D163-3/86-0"
309570-000	"227W223-3-01-0", "3-1192344-5"
CP4263-000	"202D142-3-03-0"
EG9803-000	"302A812-3/42-0-CS4112"
808460-000	"234A111-3-0", "3-1196275-9"
952223-000	"202K232-25-11-0", "9-1197373-7"
CU2640-000	"202D132-3-35-0"
823222-000	"342A124-3-0", "2-1196423-0"
357545-000	"234A732-3-02/42-0", "7-1192682-1"
A45302-001	"9-1200275-4", "CES-2-CS-2065"
577323-000	"227W234-3-01-0", "6-1194579-3"

Product Affected	Alias Part Number
813971-000	"202A032-3-0", "8-1196333-3"
814316-000	"202A121-3-0", "2-1196338-9"
420897-000	"101A062-3-CS-2060-0", "9-1193170-7"
858623-000	"202K185-15/86-0", "1196691-2"
812997-014	"202K121-3-CS-1858-0", "9-1196324-6"
822598-000	"202K121-3/42-0", "3-1196416-9"
878127-000	"207W234-3-01/42-0", "2-1196833-5"
823351-000	"362A014-3-0", "4-1196426-1"
806507-000	"202D232-4-32-0", "8-1196237-0"
848633N003	"3-1201562-6", "CES-4-CS8365"
055566-000	"7-1199150-0", "QFT2-130/42-0-B500"
286287-000	"7-1192168-2", "423A117-3-0"
815366N001	"222D132-3-60-0-CS5078", "7-1196354-0"
823211-000	"301A011-3-0", "1196423-4"
743925-000	"222K163-3/86-0", "6-1195803-8"
703870-000	"202D132-3/86-0", "1195522-1"
823635-000	"382A023-3/42-0", "9-1196429-7"
032673-000	"4-1190253-3", "202A111-3-CS-2060-0"
823248-000	"362A014-3/42-0", "1196424-5"
F84125-000	"3-1201850-3", "202D163-3-72/42-0-CS5501"
880719-000	"202D953-3-26/42-0", "4-1196856-4"
814816-000	"234A052-3-0", "6-1196348-0"
879026-000	"200W511-3-0", "8-1196842-3"
806540-000	"202D211-4-32-0", "3-1196238-1"
820888-000	"382A023-3-G01-0", "6-1196401-4"
806996-000	"202D163-3/86-0", "8-1196248-0"
809832-000	"202K142-3/86-0", "4-1196293-3"
099391-000	"4-1190728-1", "222B112-3/42-0"
843195-000	"101A094-3-0", "6-1196577-4"
115683-000	"9-1190842-4", "222D174-3/86-0"
991265-001	"7-1197665-5", "CES-2-T1"
843114-000	"101A083-3-0", "9-1196576-2"
628920-001	"1-1200274-6", "CES-1-CS-2065"
CC2429-000	"CES-2-D1-AL"
482579-000	"202D142-3-02/42-0", "1193612-5"
CH5299-000	"8-1899666-8", "PP000010"
813997-000	"222D121-3-0", "2-1196334-6"
426269N002	"1-1193208-4", "CES-2L-AL-2.3-CS8365"
814777-000	"202A111-3/42-0", "1196348-6"
878546-000	"202K142-3-01/42-0", "8-1196839-2"

Product Affected	Alias Part Number
742955-000	"222A152-3-0-CS6634", "1195797-6"
807056-000	"242A322-3-0", "1-1196250-9"
879462-000	"200W582-3-0", "1196847-7"
822597-000	"202K153-3/42-0", "3-1196416-3"
822595-000	"222K163-3/42-0", "2-1196416-1"
814090-000	"222A196-3-0", "4-1196335-6"
E51049-000	"234A021-3-CS-2065-0", "4-1200756-8"
806144-000	"228A032-3/42-0", "8-1196231-3"
036862-001	"8-1200274-4", "CES-3-F1-CS-2065"
626437-000	"234A652-3-03/42-0", "5-1194961-1"
915536-000	"322A112-3/42-0", "5-1197107-6"
820669-000	"222K121-3/42-0", "1196399-7"
370687-000	"222D121-3/86-0", "7-1192776-9"
823064-000	"562A054-3-0", "9-1196420-2"
840368-000	"382A023-15-0", "6-1196556-5"
562053-000	"342A012-3/180-0", "1194441-3"
820643-000	"202K132-4-00-0", "7-1196398-6"
809969-000	"202K153-3/86-0", "4-1196294-1"
814710N004	"202A132-3/42-0", "3-1196346-4"
808837-000	"222D163-3/42-0", "1-1196282-6"
033299-000	"1-1190258-3", "101A073-3-CS-2060-0"
814589N002	"202D142-3/42-0", "3-1196344-0"
822767-000	"202K111-3-0", "1-1196418-5"
350193-000	"214A021-3/86-0", "9-1192633-2"
900119-000	"382A046-3/86-0", "8-1196996-7"
843037-000	"101A062-3-0", "2-1196576-0", "45101A0623-M"
823776-000	"2-1196433-6", "382A012-3-0"
814441-000	"243A022-3-0", "4-1196341-0"
C17627-000	"234A011-3-CS-2065-0", "1-1200756-5"
806998-000	"222A152-3/86-0", "8-1196248-7"
814308-000	"202A111-3-0", "1-1196338-0"
822066-000	"342A012-3/42-0", "2-1196411-5"
557732-001	"2-1194399-6", "CES-4-T1"
814718-000	"222A152-3/42-0", "6-1196346-7"
848777-000	"234A011-3/86-0", "8-1196618-7"
456425-000	"6-1193425-5"
608856-000	"202W321-130-CS-2065-0", "1197988-6"
814135-000	"234A111-3-00-0", "1196336-5"
632774-000	"202K132-25-00-0", "1195006-8"
F40762-000	"202K121-3-CS-1821-0", "2-1200974-8"

Product Affected	Alias Part Number
912229N002	"3-1197084-2", "CES-3-CS8365"
042421N001	"3-1190325-0", "202D211-3-61/42-0-CS5077"
A63971-000	"101A031-3-05-0", "1-1200375-5"
822521-000	"202K121-3-01-0", "7-1196414-0"
820672-000	"222K142-3/42-0", "2-1196399-0"
808472N004	"222D932-4-00-0-CS5545", "7-1196275-6"
820023-000	"562A022-3/42-0", "2-1196390-2"
813752-000	"243A022-3-02-0", "3-1196331-3"
EJ2316-000	"200W404-3-0"
294463-001	"9-1192230-5", "CES-2A-T3"
814710-000	"202A132-3/42-0", "3-1196346-1"
154791-000	"6-1191118-1", "214A311-3/86-0"
819095-000	"462A034-3/42-0", "9-1196382-1"
813966-000	"202A074-3-0", "6-1196333-1"

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.

Alert document created by IHS Markit based on content provided by TE Connectivity.