

1 Products affected

Product hierarchy no. *				Part no.	SBU	Type / Description	Customer part no.
SBU	PG	PUG	Type				
02	007	001	0000002433	See list below	Connector	2576 Appliance Inlet C8	n/a
02	007	001	0000002314	See list below	Connector	2576 Retaining Kit	n/a

*SBU (2-digit) / PG (3-digit) / PUG (3-digit) / Type (10-digit)


List of part numbers affected				
6160.0021	6160.0022	6160.0023	6160.0028	6160.0050
6160.0058	6160.0076	6160.0099	6160.0108	6160.0109
6160.0110	6160.0111	6160.0112	6160.0113	6160.0114
6160.0115	6160.0116	6160.0117	6160.0118	6160.0119
6160.0120	6160.0121	6160.0122	6160.0123	

2 Type of change

UL upgrade from UL 498 to UL 60320-1.

Marking for UL rating 7A/125V~ updated. Marking for IEC rating 2.5A/250V~ updated.

3 Detailed description of change



4 Reason of change

Standards update according to the new UL/CSA 60320-1.

5 Release date

The change takes effect in ww 19/2021 (Date code 2119 or higher on label).

Product Change Notification					2576 Change of marking		
owner	creation date	release date	released by	change order no	rev	page	D10-055-674
zeierjo	31.03.2021	31.03.2021	muehlema	2021023	B	1 of 2	

6 Impact of change and recommended action

Form	Yes	Change of rating marking.
Fit	No	-
Function	No	-
Manufacturing	No	-
Label	No	-
Packaging	No	-

7 Reference Documents / Attachments

Kind of document	Remarks
Data sheet 2576	

Product Change Notification					2576 Change of marking		
owner	creation date	release date	released by	change order no	rev	page	D10-055-674
zeierjo	31.03.2021	31.03.2021	muehlema	2021023	B	2 of 2	