

Before Picture

Overview

- This PCN was raised to rectify the document error which mainly was the discrepancy found between the 3D model, 2D drawing versus the physical part. The changes shall be made only on the drawing and model documents to reflect current physical parts.
- Product Impact
 - no impact to fit, form or function
- Part Number Impact
 - 76170-1006, 76170-1008, 76170-1010, 76170-1016
 - 76170-1036, 76170-1038, 76170-1020, 76170-1026
- No Qualification reports conducted as the changes doesn't impact product/physical part.

After Picture BEFORE (SD-76170-001 REV E4) AFTER (SD-76170-001 REV E5) -1.2 TAIL LENGTH 13.28 1.00 MIN BOARD THICKNESS SEE NOTE 10 -1.00 MIN BOARD THICKNESS SEE NOTE 10 12.75 10.80 10.80 molex BACKPLANE (REF) BP ВВ Updated views of the drawing to eliminate the discrepancy between the 3D model, 2D drawing versus the physical part.

RELEASED

You may address inquires regarding this PCN by clicking on the below link mailto:pcn_coordinator@molex.com?subject=PCN_Notification:514148 or contact your Local Sales Engineer.

Note: While responding, please retain "PCN Notification: PCN Notification: 514148" in the e-mail Subject line for faster response.

Molex, LLC 2222 Wellington Court Lisle, IL 60532 TEL (800) 786-6539 www.molex.com