

Dear Customer,

With this INFINEON Technologies Errata Note we would like to inform you about the following

### **Correction of RBSOA Characteristic in IFF450B12ME4P\_B11 and IFF450B12ME4S8P\_B11 data sheets**

# ERRATA



N° 10182AERRA

## Correction of RBSOA Characteristic in IFF450B12ME4P\_B11 and IFF450B12ME4S8P\_B11 data sheets

► **Products affected:**

Sales Name	SP N°	OPN
IFF450B12ME4P_B11	SP001377612	IFF450B12ME4PB11BPSA1
IFF450B12ME4S8P_B11	SP001665620	IFF450B12ME4S8PB11BPSA1


► **Detailed Change Information:**

**Subject:** Due to wrong scaling RBSOA Characteristic curve of both IFF450B12ME4P\_B11 and IFF450B12ME4S8P\_B11 data sheets is incorrect


**Reason:** Manual entry error

**Description:**

Old



New



► **Impact of Change:**

Shift of RBSOA Characteristic curves

► **Attachments:**

Updated data sheet in Internet available

► **Implementation Date:**

Immediately

If you have any questions, please do not hesitate to contact your local Sales office.