




## Product Change Notification

Product Line:	COMBO A	Part No:	NCJ6FA-*
Piece Part:	XLR contact	Part No:	91418511 91418521 91418531 91418561 91418571
Engineering Change Request:	-	Date:	-
Engineering Change Execution:	-	Date:	-
Comments:	XLR contacts changed to selective plating		
Affected products:	NCJ6FA-H, NCJ6FA-H-0, NCJ6FA-H-0-Y, NCJ6FA-H-D, NCJ6FA-H-Y, NCJ6FA-V, NCJ6FA-V-0, NCJ6FA-V-0-Y		
First Shipment of Modified Product:	H01		

### Engineering Change Notice



Plating changed from fully gold plated to selective gold plating at contact area and tin plating at PCB termination area for best conductivity and solderability.





**OLD**

XLR contacts  
fully gold plated



**NEW**

XLR contacts  
with gold plating  
at contact area  
and tin plating at  
PCB termination  
area

