

**Murata Power Solutions
(Milton Keynes) Limited**

Power Solutions House
Presley Way,
Milton Keynes MK8 0ES
United Kingdom

Tel: +44 (0)1908 615232
Email: info@murata-ps.co.uk
www.murata-ps.com

Product Change Notification:

Reference: PCNMK1005

Affected Part Numbers:











The bracketed number represents which image should be referred to in the “Description of the Change” section.

50105C (1)	50225C (1)	50474C (1)	50475C (1)	54050C (2)	54100C (2)
54200C (2)	76250ENC (3)	76253/35ENC (3)	76253/55ENC (3)	76601/1C (4)	76601/2C (4)
76601/3C (4)	76602/1C (4)	76611/2C (4)	76615/1C (4)	76615/1QC (4)	77202C (3)
77203HVC (3)	77204C (3)	77205C (3)	77208C (3)	77209C (3)	782100/33VC (5)
782100/35JVC (5)	782100/35JVC-R (5)	782100/53VC (5)	782100/55JVC (5)	782100/55JVC-R (5)	782482/33VC (5)
782482/53VC (5)	782485/35C (5)	782485/55C (5)	78250C (5)	78250JC (5)	78250JC-R (5)
78250JVC (5)	78250JVC-R (5)	78250MC (5)	78250MC-R (5)	78250MVC (5)	78250MVC-R (5)
78250VC (5)	78253/35C (5)	78253/35JC (5)	78253/35JC-R (5)	78253/35JVC (5)	78253/35JVC-R (5)
78253/35MC (5)	78253/35MC-R (5)	78253/35MVC (5)	78253/35MVC-R (5)	78253/35VC (5)	78253/55C (5)
78253/55JC (5)	78253/55JC-R (5)	78253/55JVC (5)	78253/55JVC-R (5)	78253/55MC (5)	78253/55MC-R (5)
78253/55MVC (5)	78253/55MVC-R (5)	78253/55VC (5)	78601/16C (5)	78601/16JC (5)	78601/16JC-R (5)
78601/16MC (5)	78601/16MC-R (5)	78601/1C (5)	78601/1JC (5)	78601/1JC-R (5)	78601/1MC (5)
78601/1MC-R (5)	78601/2C (5)	78601/2JC (5)	78601/2JC-R (5)	78601/2MC (5)	78601/2MC-R (5)
78601/3C (5)	78601/3JC (5)	78601/3JC-R (5)	78601/3MC (5)	78601/3MC-R (5)	78601/4C (5)
78601/4JC (5)	78601/4JC-R (5)	78601/4MC (5)	78601/4MC-R (5)	78601/8C (5)	78601/8JC (5)
78601/8JC-R (5)	78601/8MC (5)	78601/8MC-R (5)	78601/9C (5)	78601/9JC (5)	78601/9JC-R (5)
78601/9MC (5)	78601/9MC-R (5)	78602/16C (5)	78602/16JC (5)	78602/16JC-R (5)	78602/16MC (5)
78602/16MC-R (5)	78602/1C (5)	78602/1JC (5)	78602/1JC-R (5)	78602/1MC (5)	78602/1MC-R (5)
78602/2C (5)	78602/2JC (5)	78602/2JC-R (5)	78602/2MC (5)	78602/2MC-R (5)	78602/3C (5)
78602/3JC (5)	78602/3JC-R (5)	78602/3MC (5)	78602/3MC-R (5)	78602/4C (5)	78602/4JC (5)
78602/4JC-R (5)	78602/4MC (5)	78602/4MC-R (5)	78602/8C (5)	78602/8JC (5)	78602/8JC-R (5)
78602/8MC (5)	78602/8MC-R (5)	78602/9C (5)	78602/9JC (5)	78602/9JC-R (5)	78602/9MC (5)
78602/9MC-R (5)	78604/16C (5)	78604/16JC (5)	78604/16JC-R (5)	78604/16MC (5)	78604/16MC-R (5)
78604/1C (5)	78604/1JC (5)	78604/1JC-R (5)	78604/1MC (5)	78604/1MC-R (5)	78604/2C (5)
78604/2JC (5)	78604/2JC-R (5)	78604/2MC (5)	78604/2MC-R (5)	78604/3C (5)	78604/3JC (5)
78604/3JC-R (5)	78604/3MC (5)	78604/3MC-R (5)	78604/4C (5)	78604/4JC (5)	78604/4JC-R (5)
78604/4MC (5)	78604/4MC-R (5)	78604/8C (5)	78604/8JC (5)	78604/8JC-R (5)	78604/8MC (5)
78604/8MC-R (5)	78604/9C (5)	78604/9JC (5)	78604/9JC-R (5)	78604/9MC (5)	78604/9MC-R (5)
78613/16C (5)	78613/16JC (5)	78613/16JC-R (5)	78613/16MC (5)	78613/16MC-R (5)	78613/1C (5)
78613/1JC (5)	78613/1JC-R (5)	78613/1MC (5)	78613/1MC-R (5)	78613/2C (5)	78613/2JC (5)
78613/2JC-R (5)	78613/2MC (5)	78613/2MC-R (5)	78613/3C (5)	78613/3JC (5)	78613/3JC-R (5)
78613/3MC (5)	78613/3MC-R (5)	78613/4C (5)	78613/4JC (5)	78613/4JC-R (5)	78613/4MC (5)
78613/4MC-R (5)	78613/8C (5)	78613/8JC (5)	78613/8JC-R (5)	78613/8MC (5)	78613/8MC-R (5)
78613/9C (5)	78613/9JC (5)	78613/9JC-R (5)	78613/9MC (5)	78613/9MC-R (5)	78615/16C (5)
78615/16JC (5)	78615/16JC-R (5)	78615/16MC (5)	78615/16MC-R (5)	78615/1C (5)	78615/1JC (5)
78615/1JC-R (5)	78615/1MC (5)	78615/1MC-R (5)	78615/2C (5)	78615/2JC (5)	78615/2JC-R (5)
78615/2MC (5)	78615/2MC-R (5)	78615/3C (5)	78615/3JC (5)	78615/3JC-R (5)	78615/3MC (5)
78615/3MC-R (5)	78615/4C (5)	78615/4JC (5)	78615/4JC-R (5)	78615/4MC (5)	78615/4MC-R (5)
78615/8C (5)	78615/8JC (5)	78615/8JC-R (5)	78615/8MC (5)	78615/8MC-R (5)	78615/9C (5)
78615/9JC (5)	78615/9JC-R (5)	78615/9MC (5)	78615/9MC-R (5)	CD1553C-R (5)	CD1561C-R (5)
DA101C (5)	DA101JC (5)	DA101JC-R (5)	DA101MC (5)	DA101MC-R (5)	DA102C (5)
DA102JC (5)	DA102JC-R (5)	DA102MC (5)	DA102MC-R (5)	DA103C (5)	DA103JC (5)
DA103JC-R (5)	DA103MC (5)	DA103MC-R (5)			

Description of the Change:

Currently, the product information is printed in ink. This will change to laser marking.

e.g.

Ref	Ink printing	Laser marking
1		
2		
3		
4		
5		

This change will be implemented on 12th April 2021.
Ink printed stock will be consumed before shipping laser marked parts.

Reason for the Change:

Ongoing improvement of manufacturing process repeatability and efficiency.
Elimination of material usage and waste.

Potential Product Performance / Behavior Impact:

The product marking will continue to be clear and legible, albeit with slightly decreased brightness. There are no changes to the products' design, quality, guaranteed specifications, or others, as Murata continuously uses the same production process and quality control system.

Enquiries

Should you have any questions or concerns, please contact your local Murata Sales, Representative, or Distributor.