

Product Change Notice

Issue Date: 25-January-2021

Change Description:

New PCB source for Seven Segment Display and Custom Module

Parts Affected:

HDSP-133G
HDSP-201C
HDSP-201G
HDSP-203C
HDSP-203G
HDSP-211C
HDSP-211G
HDSP-213G
HDSP-213C
HDSP-301A
HDSP-301C
HDSP-301E
HDSP-301G
HDSP-301Y
HDSP-303A
HDSP-303E
HDSP-303G
HDSP-303Y
HDSP-311A
HDSP-311E
HDSP-311G
HDSP-311Y
HDSP-313A
HDSP-313E
HDSP-313G
HDSP-313Y
HDSP-332E
HDSP-333A
HDSP-333E
HDSP-333G
HDSP-431G
HDSP-433G
HDSP-511A
HDSP-511C
HDSP-511E
HDSP-511G
HDSP-511H
HDSP-511Y-HI000
HDSP-511Y



HDSP-513A
HDSP-513E
HDSP-513G
HDSP-513Y
HDSP-515A
HDSP-521A-KL000
HDSP-521A-Z0000
HDSP-521A
HDSP-521E
HDSP-521G
HDSP-521Y
HDSP-523A
HDSP-523E
HDSP-523G
HDSP-523Y
HDSP-561A
HDSP-561C
HDSP-561E
HDSP-561G
HDSP-561Y
HDSP-563A
HDSP-563C
HDSP-563E
HDSP-563G
HDSP-563Y
HDSP-701A
HDSP-703G
HDSP-703E
HDSP-703A
HDSP-702E
HDSP-701E
HDSP-701G
HDSP-704E
HDSP-711A
HDSP-711E
HDSP-711G
HDSP-711L
HDSP-713A
HDSP-713E
HDSP-713G
HDSP-815E
HDSP-815G
HDSP-816E
HDSP-816G
HDSP-A22C
HDSP-A22G
HDSP-A27C
HDSP-A27G
HDSP-G01A
HDSP-G01E
HDSP-G01G
HDSP-G01Y



HDSP-G03A
HDSP-G03E
HDSP-G03G
HDSP-G03Y
QDSM-643C
QDSM-712Y
QDSM-711Y
QDSM-723C
QDSM-727Z
QDSM-756W
QDSM-828Z
QDSP-211C
QDSP-211G
QDSP-301G
QDSP-438G
QDSP-439G
QDSP-499G
QDSP-495C
QDSP-495A
QDSP-494A
QDSP-525G
QDSP-526G
QDSP-527C
QDSP-527G
QDSP-701C
QDSP-G09A

Description and Extent of Change:

The new PCB source shall be replacing current PCB source for part numbers above.

Reasons for Change:

1. Current PCB supplier exit business.
2. Assurance of supply to customers.

Effect of Change on Fit, Form, Function, Quality, or Reliability:

There is no change in fit and function of the product as per datasheet. However, there is PCB appearance change for new PCB source. Appropriate electrical characterization and reliability qualification have been performed on the products to ensure consistent electrical and reliability performance.

Effective Date of Change:

The shipment with above change is effective 26 April 2021. There will be a mix of products with new PCB source and old PCB source within a shipment until the old PCB source inventory is fully depleted.

Qualification Data:

Qualification data will be available upon request.

Please contact your Broadcom field sales engineer or Contact Center for any questions or support requirements. Please return any response as soon as possible, but not to exceed 30 days.