



01-Aug-2019
PCN #:P-19-017711

Subject:AMP Duoplug 2.5 Mark1 series

Description of Change: Design change for process improvement

Reason: Product [improvement.As](#) part of continuous improvement activity, design of the product is changed to improve tool and process. See attachment for design change details. Test on samples have been performed with no impact on termination process and cover retention. No other impact on performance.

Key Dates:

Contact By Date:01-Aug-2019

Implementation Date:01-Aug-2019

Product Affected

1-966195-0
284930-3
3-2311500-8
2-293207-1
4-2311500-5
2-2311500-0
1-966195-8
2-284932-5
284930-8
2-2311500-8
1-2311510-9
1-2311500-6
3-284932-3
1-2311501-3
1-2311510-8

Product Affected

1-966195-2
2311501-1
2-2311500-5
1-966194-7
1-966195-7
284932-8
1-966195-4
2311505-6
3-284930-3
284932-3
2311500-7
293207-5
3-2311500-5
1-966195-9
5-2311500-5
1-2311510-3
293132-3
1-966195-3
1-284932-6
284932-7
1-966930-7
2311511-1
284932-6
7-2311500-3
5-2311500-3
2311511-2
2-2311500-6
284932-5
8-2311500-6
1-293207-1
1-2311510-7
2-284932-6
4-284930-3
2311500-4
1-2311500-7
6-2311500-6
5-2311500-6
1-284932-0
293207-6
1-966194-8

Product Affected

1-966194-5
284930-7
1-966930-3
1-2311501-1
1-284930-1
293207-9
284930-6
1-966195-6
284932-9
1-2311510-5
2311511-5
4-2311500-3
1-2311500-3
1-966194-0
1-966195-1
1-966195-5
1-2311510-4
284930-5
1-2311506-1
2311505-7
2311511-9
3-284932-6
2311500-3
2-284930-6
4-284932-3
2311500-5
1-2311500-4
293207-3
2311500-9
2-284930-4
1-284932-1
2311506-1
2311511-6
3-284932-5
2-284932-3
2311500-8
2-284932-8
1-966194-4
2311514-3
1-293207-3

Product Affected

2311505-5
4-284932-5
2-293207-6
284932-4
1-2311505-9
284930-4
1-966194-3
2311505-3
2311500-6
2311511-8
1-2311510-6
1-966194-6
2-284932-4
2-2311500-3
293207-7
2-2311510-0
4-2311500-6
2-284930-3
1-966194-9
3-2311500-4
2-966930-7
6-2311500-3
3-2311500-6
2-293207-9
2311505-9
4-2311500-4
1-966195-0
284930-3
3-2311500-8
2-293207-1
4-2311500-5
2-2311500-0
1-966195-8
2-284932-5
284930-8
2-2311500-8
1-2311510-9
1-2311500-6
3-284932-3
1-2311501-3

Product Affected

1-2311510-8
1-966195-2
2311501-1
2-2311500-5
1-966194-7
1-966195-7
284932-8
1-966195-4
2311505-6
3-284930-3
284932-3
2311500-7
293207-5
3-2311500-5
1-966195-9
5-2311500-5
1-2311510-3
293132-3
1-966195-3
1-284932-6
284932-7
1-966930-7
2311511-1
284932-6
7-2311500-3
5-2311500-3
2311511-2
2-2311500-6
284932-5
8-2311500-6
1-293207-1
1-2311510-7
2-284932-6
4-284930-3
2311500-4
1-2311500-7
6-2311500-6
5-2311500-6
1-284932-0
293207-6

Product Affected

1-966194-8
1-966194-5
284930-7
1-966930-3
1-2311501-1
1-284930-1
293207-9
284930-6
1-966195-6
284932-9
1-2311510-5
2311511-5
4-2311500-3
1-2311500-3
1-966194-0
1-966195-1
1-966195-5
1-2311510-4
284930-5
1-2311506-1
2311505-7
2311511-9
3-284932-6
2311500-3
2-284930-6
4-284932-3
2311500-5
1-2311500-4
293207-3
2311500-9
2-284930-4
1-284932-1
2311506-1
2311511-6
3-284932-5
2-284932-3
2311500-8
2-284932-8
1-966194-4
2311514-3

Product Affected

1-293207-3
2311505-5
4-284932-5
2-293207-6
284932-4
1-2311505-9
284930-4
1-966194-3
2311505-3
2311500-6
2311511-8
1-2311510-6
1-966194-6
2-284932-4
2-2311500-3
293207-7
2-2311510-0
4-2311500-6
2-284930-3
1-966194-9
3-2311500-4
2-966930-7
6-2311500-3
3-2311500-6
2-293207-9
2311505-9
4-2311500-4

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.